


Location: Frederica, Delaware Kent Co Photographer: Joan M. Norton Date: 1974 Location of Negative: Division of Historical and Cultural Description. Hall of Records, Dover, DE Hathorn-Lowber House (1 - K-144), 3/4 view from south Photograph Manager: 1 100

NOV 9 1977



Location: Frederica, Delaware Photographer: Joan M. Norton Date 1974 Location of Negative: Division of Historical and Cultural Affairs, Dover, DE Description: Hathorn-Lowber House (1- K-144) detail from east

AUG 2 1977 NOV 9 1 2 7 24



Location: Frederica, Delaware Kent County Photographer: Sue Fox Date: 1977 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, Delaware Description: North Market Street, taken from south showing 4 North Market Street (86), 6 North Market Street (87), 8 North Market Street (89) and Hathorn-Lowber House (1-K-144

AUG 2 1977 NOV 9 197



Location: Frederica Delaware

Photograph Number:

Photographer: Joan M. Norton Date: 1974

Kent Co.

Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, Delaware Description: Wootten Market (73 - K-342) from northwest

4 g 24 AUG 2 1977 NOV 9 1977



Location: Frederica, Delaware

Photographer: Joan M. Norton Date: 1974 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, DE Description: Robbins Hardware (86-K-343), south side or facade showing all header bond brickwork

AUG 2 1977



Location: Frederica, Delaware

Kont Co

Photographer: Sue Fox
Date: 1977
Location of Negative: Division of Historical and Cultural
Affairs, Hall of Records, Dover, DE
Description: 2 Front Street (90-K-239) taken from northeast showing brick main section and frame and brick
l story wing to east

60/24 AUG 2 1977 NOV 9



Frederica Historic District

Location: Frederica, Delaware

Kent Co.

Photographer:Sue Fox
Date: 1977
Location of Negative: Division of Historical and Cultural
Affairs, Hall of Records, Dover, Delaware
Description: 1 Front Street (4) and 5 Front Street
(5+K-318) showing porch detail

AUG 2 1977

NUV 3

7 9/24



Location: Frederica, Delaware Kentlowy Photographer: Joan M. Norton Date: 1974 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, Delaware Description: View of 5 Front Street (5-K-318) from southwest



Name Frederica Historic District Kent Co. Location: Frederica, Delaware Photographer: Sue Fox Dater 1977 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, DE Description: Streetscape showing Front Street west of Market Street with Trinity Methodist Church (91-K328) taken from northeast

NUV H

Photograph Number: 9 of AUG 2 1977



Kent Co

Jane Frederica Historic District 204 . Location: Frederica, Delaware Photographer: Sue Fox Date: 1977 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, DE Description: Streetscape of Front Street, west of Market Street, taken from southwest showing 21 and 23 Front Street (12 and 13) in forefront AUG 2 1977 Nov 9 Photograph Number: 10 0 24



Frederica Historic District

Location: Frederica, Delaware

Photographer: Sue Fox Date: 1977

Kent Co.

Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, DE Description: Streetscape of Front Street, west of Market Street, showing 101, 103,105, and 107 Front Street (14, 15, 16, and 17)

Photograph Number:

11 y 24 AUG 2 1977

NOV 9 1977



Location: Frederica, Delaware Kent Co Photographer: Sue Fox Date: 1977 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, DE **Description:** 111 Front Street (19) taken from southeast showing typical Frederica modillion cornice which returns at the ends, tin roof, interior end chimneys and rear wing 12 9 24 AUG 2 1977 Photograph Number:

NOV 9 1977



Location: Frederica, Delaware

Photographer: Sue Fox

Kent Co.

Date: 1977 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, DE Description: west end of Front Street, showing 123 Front Street (24-K-344) as the visual west end of the district

Photograph Numbers of 24

AUG 2 NOV 9



Location: Frederica, Delaware Kent Co. Photographer: Sue Fox Date: 1977 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, Delaware Description: David Street, west of Market Street, showing 3-5-7-9, 11, 13-15 and 17 David Street (117, 116, 115, 114) 117 has now been demolished AUG 2 **197**

Photograph Number:

14 0/24

NOV

1977



PROPERTY OF THE NATIONAL REGISTLE

Name: Frederica Historic District

Location: Frederica, Delaware Kent Co Photographer: Joan M. Norton Date: 1974 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, Delaware Description: 8 David Street (36-K-332) taken from northwest

"http://www.inter.

15 0/ 24 AUG 2 1977 NOV



PROPERTY OF THE NATIONAL REGISTER

Name:

Frederica Historic District


Location: Frederica, Delaware Photographer: Joan M. Norton Date: 1974 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, DE Description: 13-15 David Street (115-K-317) house built by James Wakeman, one of carpenters who built the Old State House in Dover

Photograph Number:

16 124 AUG 2 1977 NUSS

1977





1787 24 AUG 2 1977 NOV 9



FROPERTY OF THE NATIONAL REGISTER

Name: Frederica Historic District

Location: Frederica, Delaware

Photographer: Sue Fox Date: 1977 Location of Negative: Division of Historical and Cultural

Affairs, Hall of Records, Dover, Delaware Description:

Market Street north of David Street showing 9 Market Street (119)

AUG 2 1977 18 0/ 24 NOV



PROPERTY OF THE NATIONAL REGISTER

Name: Frederica Historic District

Location: Frederica Delaware

Photographer: Sue Fox Date: 1977 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, DE Description: Detail of 8 Market Street (81 - K-341)

Photograph Number:



PROPERTY OF THE NATIONAL REGISTER

Name: Frederica Historic District

Location: Frederica Delaware Photographer: Sue Fox Date: 1977 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, Delaware Description: 105 Market Street (40 - K-335) and 107 Market Street (41 - K-336) taken from northeast

Photograph Number:

20 07 24 AUG 2 1977



Name: Frederica Historic District

Location: Frederica, Delaware Photographer: Sue Fox Date: 1977 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, DE Description: Market Street south of David Street, west side with 113 Market Street (44 - K-338) in the foreground

Photograph Number:



Name: Frederica Historic District

Sue Fox

Location: Frederica, Delaware

Kent County

Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, Delaware Description:

207 and 209 Market Street (48 and 49) taken from the southeast

Photograph Number:

Photographer:

Date:



Frederica Historic District Name: Kent Co. Location: Frederica, Delaware Photographer: Sue Fox ę Date: 1977 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, DE Description: 200 and 218 Market Street (57 and 58) south of David Street

Photograph Number:

23 7 24 AUG 2 1977 NOV 9 1977



Name: Frederica Historic District

Location: Frederica, Delaware Photographer: Sue Fox Date: 1977 Location of Negative: Division of Historical and Cultural Affairs, Hall of Records, Dover, DE Description: (54 and 55) 226 and 224 Market Street, south of David Street taken from southwest

AUG 2

NOV 9

Photograph Number:

24 01 24