



THE CLOVERLAND GARAGE (name of
property since 1918)

In this photo: **FLORANCE & COMPANY** or
FLORANCE & MORROW.

Cloverland, WA (Route 2, Asotin, WA 99402)

Photographer unknown. Photo courtesy of
Robert Florance.

ca. 1905

Copy negative enclosed. (OAHP)

View of south and east walls, with camera
pointing northwest.

1 of 5 photos



HAVOLINE OIL
IT MAKES A DIFFERENCE

THE CLOVERLAND GARAGE

Cloverland, WA (Route 2, Asotin, WA 99402)

Photographer unknown. (probably Olive Green
or Minnie Walter Roup)

1918

Copy negative eOAHPed.

View of front of the Cloverland Garage,
with camera pointing west. Men are:

Fred Walter, proprietor, and George Roup.)
#2 of 5 photos



THE CLOVERLAND GARAGE

Cloverland, WA (Route 2, Asotin, WA 99402)

Photographer: Johnny L. Therrell

June 9, 1985

Original negative :OAHF

View of The Cloverland Garage from county road with camera pointed northwest. Shows 3 phases of building: original rectangle 1902, added south wing shortly thereafter, covered stairway in 1919.

3 of 5 photos.



THE CLOVERLAND GARAGE

Cloverland, WA (Route 2, Asotin, WA 99402)

Photographer: Johnny L. Therrell

June 9, 1985

Original negative OAHP

View of The Cloverland Garage from county road with camera pointed southwest. Environment is shown: parsonage at left; wheat field and old locust trees in distance at right.

4 of 5 photos.



THE CLOVERLAND GARAGE

Cloverland, WA (Route 2, Asotin, WA 99402)

June 9, 1985

Original negative OAHF

Photographer: Johnny L. Therrell

View of downstairs S.E. room. Camera pointed east and southeast toward county road, with Barkley residence showing through window.

(Barkley Hotel, built in 1910) Room where business of Cloverland Garage was conducted.

New ceiling, new floor, new west wall,

original counter with top sanded and refinished, entire room painted, new door and window, 9 drawers rebuilt on back of counter.

5 of 5 photos.