



TREVINO-URIBE RANCHO

304 TREVINO AVENUE, SAN YGNACIO

ZAPATA COUNTY, TEXAS

TERRI MYERS, PHOTOGRAPHER

FEBRUARY 1997

TEXAS HISTORICAL COMMISSION

NORTH AND EAST ELEVATIONS

CAMERA FACING WEST-SOUTHWEST

PHOTOGRAPH 1



TREVIÑO-URIBE RANCHO

304 TREVIÑO AVENUE, SAN YGNACIO

ZAPATA COUNTY, TEXAS

MARIO SÁNCHEZ, PHOTOGRAPHER

1996

TEXAS HISTORICAL COMMISSION

MESQUITE ENTRY DOOR TO

CUARTO VIEJO, FIRST

ROOM, CA. 1830

PHOTOGRAPH 3



TREVIÑO-URIBE RANCHO

304 TREVIÑO AVENUE, SAN YGNACIO
ZAPATA COUNTY, TEXAS

MARIO SÁNCHEZ, PHOTOGRAPHER
1996

TEXAS HISTORICAL COMMISSION
HARDWARE DETAIL, 1851 ADDITION

PHOTOGRAPH 6



TREVIÑO-URIBE RANCHO

304 TREVIÑO AVENUE, SAN YGNACIO

ZAPATA COUNTY, TEXAS

MARIO SÁNCHEZ, PHOTOGRAPHER

1996

TEXAS HISTORICAL COMMISSION

TRONERA AT ZAGUAN (ENTRY)

PHOTOGRAPH 7



TREVIÑO - UBIBE RANCHO
304 TREVIÑO AVENUE, SAN YGNACIO
ZAPATA COUNTY, TEXAS
MARIO SÁNCHEZ, PHOTOGRAPHER
1996
TEXAS HISTORICAL COMMISSION
SUNDIAL DETAIL, ATOP
ZAGUAN (ENTRY)
PHOTOGRAPH 11

A black and white photograph of a wooden beam, likely a coffin lid, with a date inscription. The beam is positioned horizontally and shows signs of wear and discoloration. The inscription is in a serif font and reads "OCTUBRE 2 DE 1851". The background consists of vertical wooden planks, possibly part of a wall or another structure. The lighting is somewhat uneven, with shadows and highlights across the wood's surface.

OCTUBRE 2 DE 1851

TREVIÑO - URIBE RANCHO

304 TREVIÑO AVENUE, SAN YGNACIO

ZAPATA COUNTY, TEXAS

MARIO SÁNCHEZ, PHOTOGRAPHER

1996

TEXAS HISTORICAL COMMISSION

INTERIOR, DATED BEAM, 1851 ADDITION

PHOTOGRAPH 12

TREVIÑO-URIBE RANCHO
304 TREVIÑO AVENUE, SAN YGNACIO
ZAPATA COUNTY, TEXAS
MARIO SÁNCHEZ, PHOTOGRAPHER
1996

TEXAS HISTORICAL COMMISSION
DATED BEAM, 1871 ADDITION
PHOTOGRAPH 13