

Dundee Woman's Club Photo, 1985 PO Box 15 Dundee, OR 97115

1 of 14 Historic view, "No. 3 Main Street," c. 1915, looking North along Pacific Highway



Dundee Woman's Club Photo, 1985 PO Box 15 Dundee, OR 97115

2 of 14 South and East (front) elevations



Dundee Woman's Club Photo, 1985 PO Box 15 Dundee, OR 97115

3 of 14 East (front) elevation



Dundee Woman's Club Photo, 1985 PO Box 15 Dundee, OR 97115

4 of 14 North elevation fronting parking area



Dundee Woman's Club Photo, 1985 PO Box 15 Dundee, OR 97115

5 of 14 West end elevation showing lean-to addition of 1964



Dundee Woman's Club Photo, 1985 PO Box 15 Dundee, OR 97115

6 of 14 Interior view of assembly hall area, looking East, to front of building



Dundee Woman's Club Photo, 1985 PO BOx 15 Dundee, OR 97115

7 of 14 Interior view of assembly hall area, looking Northeasterly to front of building



Dundee Woman's Club Photo, 1985 PO BOx 15 Dundee, OR 97115

8 of 14 Interior view of assembly hall area, looking Soutwesterly toward stage end of hall



Dundee Woman's Club Photo, 1985 PO BOx 15 Dundee, OR 97115

9 of 14 Interior view of assembly hall area, looking West to former stage end



Dundee Woman's Club Photo, 1985 PO BOx 15 Dundee, OR 97115

10 of 14
Interior view of library, Southeast corner of building




Dundee Woman's Club Photo, 1964 PO Box 15 Dundee, OR 97115

11 of 14 Interior view of kitchen, Northeast corner of building, looking West



Dundee Woman's Club Photo, 1962 PO Box 15 Dundee, OR 97115

12 of 14 Historic view, dedication day, 1915, looking West to stage end. Note roof trusses



Dundee Woman's Club Photo, 1985 PO BOx 15 Dundee, OR 97115

13 of 14 Looking West to stage end, 1962.



Dundee Woman's Club Photo, 1915 PO Box 15 Dundee, OR 97115

14 of 14 North elevation during fire on January 29, 1964