


Photo Credit: Bonnie J. Halda Date: April 5, 1983

Negative location: State Historical Society of ND

Heritage Center Bismarck, ND

Esterior: Facade, north elevation, and 1950's addition View from northeast

Photo 1/16



Date: April 5, 1983

Negative location: State Historical Society of ND
Heritage Center
Bismarck, ND

Exterior: West and south elevations

view from southwest

Photo Credit: Bonnie J. Halda

Photo 2/16



Date: April 5, 1983 Negative location: State Historical Society of ND Heritage Center Bismarck, ND

Photo Credit: Bonnie J. Halda

Exterior: Detail of carved sandstone tympanum View from east

Photo 3/16




Photo Credit: Bonnie J. Halda
Date: April 5, 1983
Negative location: State Historical Society of ND
Heritage Center
Bismarck, ND

Exterior: Detail of copper entrance door View from east

Photo 4/16



Photo Credit: Bonnie J. Halda
Date: April 5, 1983
Negative location: State Historical Society of ND
Heritage Center
Bismarck,=ND

Nave. View from east.


photo 5/16



Photo Credit: Bonnie J. Halda
Date: April 5, 1983
Negative location: State Historical Society of ND
Heritage Center
Bismarck, ND

Nave. View from west.

Photo 6/16



Date: May 19, 1983
Negative location: Cultural Research & Management Inc.
P.O. Box 2154
Bismarck, ND

Detail of side altar and stencil painting. View from west.

Photo Credit: Patricia Jessen

Photo 7/16




Photo Credit: Bonnie J. Halda
Date: April 4, 1983
Negative location: State Historical Society of ND
Heritage Center
Bismarck, ND

Detail of Sanctuary. View from east.

Photo 8/16



Photo Credit: Patricia Jessen

Date: May 19, 1983
Negative location: Cultural Research & Management Inc.
P.O. Box 2154
Bismarck, ND

Detail of stencil painting and round canvas ceiling panels

Photo 9/16



Photo Credit: Patricia Jessen
Date: May 19, 1983
Negative location: Cultural Research & Management
P.O. Box 2154
Bismarck, ND

Detail of ornamental plaster panels

Photo 10/16



Photo Credit: Patricia Jessen
Date: May 19, 1983
Negative location: Cultural Research & Management Inc.
P.O. Box 2154
Bismarck, ND

View from south

Photo 11/16



Photo Credit: Patricia Jessen Date: May 19, 1983

Negative location: Cultural Research & Management

P.O. Box 2154 Bismarck, ND

View from southwest

Photo 12/16



Date: May 19, 1983
Negative location: Cultural Research & Management
P.O. Box 2154
Bismarck, ND

Main cemetery cross. View from north.

Photo Credit: Patricia Jessen

Photo 13/16




Negative location: Cultural Research & Management P.O. Box 2154
Bismarck, ND
Hand-fashioned wrought iron grave marker.

Photo Credit: Patricia Jessen

Date: May 19, 1983

Photo 14/16

View from east.



Date: May 19, 1983
Negative location: Cultural Research & Management Inc.
P.O. Box 2154
Bismarck, ND

Enclosed burial plot. View from northeast.

Photo Credit: Patricia Jessen

Photo 15/16



Photo Credit: Patricia Jessen

Date: May 19, 1983

Negative location: Cultural Research & Management Inc.

P.O. Box 2154

Bismarck, ND

Foundry-produced cast iron grave marker. View from east.

Photo 16/16