



THOMPSON

HUGHES

WES

A. Prairie Center Methodist Episcopal Church

Dallas County, Iowa. June 20, 2003.

View from Pleasant Hill cemetery, west facade

Mary Bennett, photographer. Negatives at SHSI.



FARRIE
CENTER
ME CHURCH
BRAD
HARTOLI

B. Prairie Center Methodist Episcopal Church

Dallas County, Iowa. June 30, 2003

Façade to west

Mary Bennett, photographs. Negatives at 57151.



C. Prairie Center Methodist Episcopal Church

Dallas County, Iowa. June 30, 2003.

South elevation to N showing modifications made in 1916 (tower) and 1925 (classroom/nursery and stair hall to new basement).

Mary Bennett, photographer. Negatives at SHSI.



D. Prairie Center Methodist Episcopal Church
Dallas County, Iowa, June 20, 2003
East end of building with Gothic-style
window and 1910 addition of north
side for chancel area.
Mary Bennett, photographer. Negatives at SHSI.



E. Prairie Center Methodist Episcopal Church
Dallas County, Iowa. June 20, 2003
North elevation to S with 1910 addition
to original 1880 structure
Many Bennett, photographer. Negatives at SHSI



F. Prairie Center Methodist Episcopal Church
Dallas County, Iowa. June 20, 2003

Detail front entrance on west side

Mary Bennett, photographer

Negatives at SHSI



G. Prairie Center Methodist Episcopal Church

Dallas County, Iowa. September 3, 2003

Interior: from east toward organ and
Gothic-style window (colored glass) on
west wall, looking WNW

Mary Bennett, photographer. Negatives
at SSSI



H. Prairie Center Methodist Episcopal Church

Dallas County, Iowa. September 3, 2003.

Interior: from back of sanctuary toward
pulpit in alcove built in 1910, looking N.
Mary Bennett, photographer. Negatives at SHSI.



I. Prairie Center Methodist Episcopal Church

Dallas County, Iowa

Interior: basement stairs, looking

S toward south entrance, kitchen

to right. Mary Bennett, photographer

Negative at SHSI



J. Prairie Center Methodist Episcopal Church
Dallas County, Iowa. Interior: basement,
added in 1925 remodeling, looking SW
Many Bennett, photographer. Negatives at SHSI.



K. Prairie Center Methodist Episcopal Church

Dallas County, Iowa. June 20, 2003

Priny or outhouse with two seats,
situated on eastern edge of church

property, probably built in 1960s-1970s.
(non-contributing)

Mary Bennett, photographer. Negatives at SHSI



PLEASANT HILL CEMETERY

L. Prairie Center Methodist Episcopal Church
Dallas County, Iowa. June 20, 2003.

± Pleasant Hill Cemetery entrance sign across
the road to the west of Prairie Center Church
and slightly south on Beaumont Avenue
to SSW

Mary Bennett, photographer. Negatives at SHSI