NPS Form 10-900 United States Department of the Interior National Park Service

National Register of Historic Places Registration Form laces

This form is for use in nominating or requesting determinations for individual properties and districts. See instructions in National Register Bulletin, How to Complete the National Register of Historic Places Registration Form. If any item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, architectural classification, materials, and areas of significance, enter only categories and subcategories from the instructions.

1. Name of Property			
Historic name: Creaser Building			
Other names/site number: Cooks on Main, Judy's Cupboard, Colonial Shop, JB Lyon Women's Wear Clothing, First National Building, 32WI740			
women's wear Clothing, First National Building, 32 W1/40			
Name of related multiple property listing:			
(Enter "N/A" if property is not part of a multiple property listing N/A			
2. Location Street & numbers 224 Main Street			
Street & number: 224 Main Street City or town: Williston State: ND County: Williams			
Not For Publication: Vicinity:			
3. State/Federal Agency Certification			
As the designated authority under the National Historic Preservation Act, as amended,			
I hereby certify that this $\underline{\mathbf{x}}$ nomination request for determination of eligibility meets the documentation standards for registering properties in the National Register of Historic Places and meets the procedural and professional requirements set forth in 36 CFR Part 60.			
In my opinion, the property <u>x</u> meets <u>does not meet the National Register Criteria. I recommend that this property be considered significant at the following level(s) of significance:</u>			
nationalstatewidex_local Applicable National Register Criteria:			
ABx_CD			
Oliving, DIRECTOR 5.23.2016			
Signature of certifying official/Title: Date			
NDS HPO			
State or Federal agency/bureau or Tribal Government			

easer Building ne of Property	Williams, North I
In my opinion, the property meets o	
Signature of commenting official:	Date
Title:	State or Federal agency/bureau or Tribal Government
4. National Park Service Certification	
I hereby certify that this property is:	
ventered in the National Register	
determined eligible for the National Registe	r
determined not eligible for the National Reg	gister
removed from the National Register	
other (explain:)	a D
Signature of the Keeper	Beally 7.10.16 Date of Action
5. Classification	
Ownership of Property	
(Check as many boxes as apply.) Private:	
Public – Local	
Public – State	
Public – Federal	
Category of Property	
(Check only one box.)	
Building(s)	
District	
Site	

Creaser Building	<u> </u>	Williams, North Dakota
lame of Property		County and State
Structure		
Object		
Number of Resources within Property	5 7	
(Do not include previously listed resour		
Contributing	Noncontributing	
1		buildings
		sites
		structures
		objects
<u> </u>		Total
Number of contributing resources previous	ously listed in the Natio	onal Register0
6. Function or Use		
Historic Functions (Enter actagories from instructions)		
(Enter categories from instructions.) Commerce/Trade - Business		
Commerce/Trade- Professional		
Commerce/Trade-SpecialtyStore		
Current Functions		
(Enter categories from instructions.) Commerce Trade- Specialty Store		
7. Description		
Architectural Classification		
(Enter categories from instructions.)		
Early 20th Century Commercial Style	<u>. </u>	

National Park Service / National Register of Historic Places Registration Form
NPS Form 10-900

Creaser Building
Name of Property

Williams, North Dakota
County and State

Materials: (enter categories from instructions.)

Narrative Description

United States Department of the Interior

(Describe the historic and current physical appearance and condition of the property. Describe contributing and noncontributing resources if applicable. Begin with **a summary paragraph** that briefly describes the general characteristics of the property, such as its location, type, style, method of construction, setting, size, and significant features. Indicate whether the property has historic integrity.)

Principal exterior materials of the property: **Brick and Glass**

Summary Paragraph

The property located at 224 Main St in Williston ND has been a constant staple for downtown Williston ND for generations. It has held the corner of Main Street and Broadway as other structures were built and demolished.

The two story with full basement building is of masonry construction with blond and dark red brick banding throughout. Expressed structural bays on the exterior provide steady rhythm with regular fenestration along frontage streets. The building is of early commercial style with large commercial frontage on both the west and north sides of the building. Stretching 96'-6" eastwest and 24'-0" north-south, the building's proportions provide traditional commercial space on the main floor space with large glazing on Main Street and multi-use rentable space upstairs.

Narrative Description

The building sits on a full height concrete basement for the entire main floor footprint. Rough cut lumber framing supports the main floor above and bisects the framing with additional post support at north-south midspan. A single interior stairway provides access for primarily storage and mechanical space. A single coal chute on the north side of the building was used for the initial heating supply, but has since been enclosed and paved over on the exterior.

The ground floor street level includes a large 24'x50' commercial space opening west to Main St., commercial kitchen and separate 24'x15' commercial space opening north to Broadway. Original tile and wood floors have been maintained in the large commercial space. The high-volume first floor has its wood grid ceiling set at 14'. Aluminum storefront matching the design of the building in the 1940s still stands on the west and north elevations, but is in poor condition.

Creaser Building	Williams, North Dakota
Name of Property	County and State

The second floor has been most recently occupied as two apartments with an exterior access stairwell. Since then, demolition of the apartments has started and finishes have been removed to leave only the framing. Throughout demolition, portions of a hand painted advertisement mural was uncovered on the neighboring building's party wall that is exposed on the second floor. This advertisement predates the construction of the building.

The exterior fenestration on the second floor currently includes regular large 4'-0"x6'-8" double hung wood windows along the north and west elevations centered in the structural bays. Historic photos show the fenestration was larger on the second floor at approximately 12'-0"x6'-8" originally and have since been filled in with dark brown metal panel. First floor fenestration other than the storefront is made up of 3 small high-bay fixed wood windows approximately 4'-0"x2'-0" centered in the structural bays. Through historical photos, the building has had multiple different awnings above the Main St. entrance. From fabric to steel to current shakes, the sidewalk protection has changed as uses have changed. Signage has also been varied over the years as tenants move in. Wooden signs, lit lettering and currently lit blade signage has identified the building on the Main street corridor.

The most distinctive features of the building lie in the unique running bond brickwork. Along the north façade, dark red brick forms approximately a 48" tall base anchoring the building to the ground. Above the base, alternating 1' bands of blond and dark red brick march up the building capped by an ornamental diagonal blond brick inlay in soldier course dark red brick centered above each window lintel. Structural bays on the north elevation are expressed on the exterior with simple 2' wide pilasters of red brick every 16' on center that extend from the ground up past the parapet of the building. Each punched window opening has a flat running board bond lintel above and angled brick sill in dark red brick.

The storefront on the north elevation is along the east end of the building and deviates from the regular pattern of the building. Bordering red brick pilasters provide framework to the approximately 26'x18' storefront opening. Currently, a buff colored concrete panel in poor condition above the length of the storefront is where signage once hung for the commercial space. Separate doors at this north storefront with an angled entrance provide the only access for the second floor and the commercial space. A base of blonde brick approximately matching the color, but not texture of the rest of the building separates the sidewalk and storefront.

Creaser Building		Williams, North Dako	
Name of Property	C	County and State	
8. Statement of Significance	,	_	
Applicable National Register (Mark "x" in one or more boxes listing.)	Criteria s for the criteria qualifying the property for Na	tional Register	
A. Property is associated broad patterns of our	ted with events that have made a significant court history.	ntribution to the	
B. Property is associated	ted with the lives of persons significant in our p	past.	
construction or repr	the distinctive characteristics of a type, period, resents the work of a master, or possesses high ificant and distinguishable entity whose component.	artistic values,	
D. Property has yielded history.	d, or is likely to yield, information important in	n prehistory or	
Criteria Considerations (Mark "x" in all the boxes that a	apply.)		
A. Owned by a religiou	us institution or used for religious purposes		
B. Removed from its o	original location		
C. A birthplace or grav	ve		
D. A cemetery			
E. A reconstructed bui	ilding, object, or structure		
F. A commemorative p	property		
G. Less than 50 years of	old or achieving significance within the past 50	0 years	

easer Building	Williams, North Dakot
me of Property	County and State
Areas of Significance	
(Enter categories from instructions.)	
Architecture	
	
Period of Significance	
1015 1055	
1915-1955	
	
Significant Dates	
1015 1016	
1915-1916 1925	
Circuificant Danson	
Significant Person (Complete only if Critorian P. is morbed shave)	
(Complete only if Criterion B is marked above.)	
Cultural Affiliation	
A 124 47D 211	
Architect/Builder	
Stacy-Judd of Minot_	

Creaser Building	Williams, North Dakota
Name of Property	County and State

Statement of Significance Summary Paragraph (Provide a summary paragraph that includes level of significance, applicable criteria, justification for the period of significance, and any applicable criteria considerations.)

The First National Bank Building, a 25' x 98' two-story brick building on the corner of Main Street and Broadway in Downtown Williston, is being recommended for National Register of Historic Places under Criteria C. The Creaser Building is significant under Criterion C at the local level for its use of blond and red brick to create a distinctive design that sets it visually apart from all of the neighboring buildings. This property located at 224 Main St. in Williston ND has been a constant staple for downtown Williston for generations. It has held the corner of Main Street and Broadway as other structures were built and demolished.

In 1915, The First National Bank began the work of building a brick block on the intersection of Main Street and Broadway in Downtown Williston. The project was completed in 1916. Once the building was finished, it was referred to as the Creaser Building since the first floor housed the Creaser Drug Store during its first twenty-five years (1915-1940). The Creaser Building is an excellent example of early 20th century commercial style.

The two story with full basement building is of masonry construction with unique brick banding throughout. Expressed structural bays on the exterior provide steady rhythm with regular fenestration along frontage streets. The building is of early commercial style with large commercial frontage on both the west and north sides of the building. Stretching 96'-6" eastwest and 24'-0" north-south, the building's proportions provides traditional commercial space on the main floor space with large glazing on Main Street and multi-use rentable space upstairs.

In 1925, the Creaser Building, along with the Jarrell-Johnson Building, which is located on the lot directly to the south, suffered major loss after a late-night fire spread to the Creaser Building.

Narrative Statement of Significance (Provide at least **one** paragraph for each area of significance.)

In April 1915, the First National Bank purchased the northwest corner of Main Street and Broadway to build a significant two-story brick building in Downtown Williston. At that time, a small old-framed one-story building had been previously moved to this location and housed the Williston Graphic, whose editor was Dick Copeland. It is noted that this framed building was one of the oldest of its kind on Main Street. Then, the William Electrical Construction Company purchased the building from Copeland and resided in the building. With the contract signed for the construction of the First National Bank Building, the old wood structure was demolished to make space for the new structure, the Creaser Building. Williston would experience the largest construction season of its time.

Creaser Building

purposes.

Williams, North Dakota

County and State

Name of Property In early 1916, the \$25,000 Creaser Building was completed. The rear of the main floor would be occupied by the William Electrical Construction Company; the front of the main floor would be occupied by Creaser Drug. The unique use of the blond and red brick banding created a distinctive design that set the Creaser Drug apart from any other building of that time and it still holds that title today. With the expressed structural bay on the exterior provide steady rhythm with the regular fenestration along frontage streets. The building exemplifies the early commercial style with the large commercial frontage on both the west and north sides of the building. Currently, the customers of Cooks on Main still enjoy the intricate original .75" x .75" green and white tile pattern on our retail floor. The tile is throughout the main floor retail space, and many of the customers still comment on this authenticity of the time period. The second

floor held offices for numerous businesses including the O.L. Wingate Real Estate, the War Finance Corporation, Burdick and Lake Lawyers, Mortgage Service Corporation, and the United

Life Insurance. Presently, the second floor is not being used for residential or commercial

On December 27, 1925, the Creaser Building suffered damage from a fire that began in the building adjacent to it to the south, the Jarrell-Johnson Hardware. While the fire started around 2:00 A.M. in the Jarrell-Johnson Hardware Store, it quickly spread to the Creaser Building even though the shared second-floor hallway was equipped with a large metal fire door that was supposed to release when the safety wire would reach a certain temperature. The fire department was not able to determine if the fire spread through the fire door or from the shared roof. Despite the Creaser Building receiving over \$100,000 in damage from smoke and fire, the Creaser family reopened the store after it had been renovated.

The following businesses have lived on the main floor of this location: In 1940, J.B. Lyon Women's Wear Exterior In 1959, the Colonial Shop In 1980, Judy's Cupboard

9. Major Bibliographical References

Bibliography (cite the books, articles, and other sources used in preparing this form.)

First National to Build Block. (1915, April 22). Williston Graphic, p. 10 Col 2

Boom Seen in Building. (1915, April 22). The Williston Herald, p.1 Col 5

Work Started on New First National Bank Building. (1916, June 8). Williston Graphic, p. 1 Col 6

Keiter Directory Company. (1918). Williston City and Williams County North Dakota Directory 1918-1919. Norfolk, Nebraska.

Jarrell-Johnson Block Destroyed by Morning Fire. (1925, December 31). Williams County Farmers Press, p. 1 Col 6

Williston Herald- Progress Edition. (1927, June 23). Sec 4 p.1

Jarrell-Johnson Hardware Store Fire was Tough on the Fireman. (1999, October 5).

Creaser Building Name of Property			Williams, North Dakota County and State
	1A col 1-2, p. 5A 1-3		County and State
Previous documentati	on on file (NPS):		
previously listed in previously determined designated a National recorded by History	mination of individual listing n the National Register tined eligible by the National onal Historic Landmark ric American Buildings Surveric American Engineering Re ric American Landscape Surveric American Landscape Surveric	Register ey # cord #	-
Primary location of ac			
State Historic Pre			
	cy-ND State Archives		
Federal agency Local governmen	t		
University	·		
Other			
Name of repositor	ry:		
	rvey Number (if assigned):		
10. Geographical Data	l		
Acreage of Property	Less than 1 acre		
gr			
UTM References Datum (indicated on Use	SGS map):		
NAD 1927 or	× NAD 1983		
1. Zone: 13	Easting: 602540	Northing:	5333494
2. Zone:	Easting:	Northing:	
3. Zone:	Easting:	Northing:	

United States Department of the Interior National Park Service / National Register of Historic Places Registration Form NPS Form 10-900 OMB No. 1024-0018	
Creaser Building	Williams, North Dakota
Name of Property	County and State
Verbal Boundary Description (Describe the boundaries of the property.)	
West 98' of Lot 23 in block 10 of the original town site to the city of Williams County, North Dakota	of Williston,
Boundary Justification (Explain why the boundaries were selected.)	
The boundaries include the land historically associated with the building.	
11. Form Prepared By	
name/title: Angela Skogen	
organization:	
street & number: 1210 East Hillcourt ND 58801	<u> </u>
city or town: Williston state: ND zip code: 588	01
e-mail_angela@cooksonmain.com	
telephone: 612-910-1870 (cell) or 701-572-2665 (Office)	

Additional Documentation

date: March 2016

Submit the following items with the completed form:

- Maps: A USGS map or equivalent (7.5 or 15 minute series) indicating the property's location.
- **Sketch map** for historic districts and properties having large acreage or numerous resources. Key all photographs to this map.
- Additional items: (Check with the SHPO, TPO, or FPO for any additional items.)

Creaser Building	
Name of Property	

Williams, North Dakota
County and State

Property Owner

name/title:Angela Skogen /Owner			
organization:			
street & number: 1210 East Hillcourt			
city or town: Williston	state:	ND	zip code: 58801
e-mail angela@cooksonmain.com			-
telephone: 701-572-2665	_		

Photographs

Submit clear and descriptive photographs. The size of each image must be 1600x1200 pixels (minimum), 3000x2000 preferred, at 300 ppi (pixels per inch) or larger. Key all photographs to the sketch map. Each photograph must be numbered and that number must correspond to the photograph number on the photo log. For simplicity, the name of the photographer, photo date, etc. may be listed once on the photograph log and doesn't need to be labeled on every photograph.

Photo Log

Creaser Building William County Eryn Vornous 4 March 2016

Main Street and Broadway Façade (northwest)

1 of 6

Main Street Façade (west)

2 of 6

Historical Green and White Tiles on the 1st Floor Retail floor

3 of 6

Historical Green and White Tile highlighting the intricate border

4 of 6

Historical Green and White Tile border close-up

5 of 6

Lorna Meidinger 5 April 2016 Broadway Facade (north from northeast corner) 6 of 6

NPS Form 10-900	OMB No. 1024-0018	
Out of the Park		AA/III'a aa Alla dh Dalla (a
Creaser Building		Williams, North Dakota

County and State

Paperwork Reduction Act Statement: This information is being collected for applications to the National Register of Historic Places to nominate properties for listing or determine eligibility for listing, to list properties, and to amend existing listings. Response to this request is required to obtain a benefit in accordance with the National Historic Preservation Act, as amended (16 U.S.C.460 et seg.).

United States Department of the Interior

Name of Property

National Park Service / National Register of Historic Places Registration Form

Estimated Burden Statement: Public reporting burden for this form is estimated to average 100 hours per response including time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding this burden estimate or any aspect of this form to the Office of Planning and Performance Management. U.S. Dept. of the Interior, 1849 C. Street, NW, Washington, DC.

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number	Additional Documentation

Creaser Building
Name of Property
Williams, North Dakota
County and State
-
Name of multiple listing (if applicable)

14

Page _

"J.B. Lyon Women's Wear exterior, Williston N.D." taken between 1940 and 1959, State Historical Society of North Dakota, William E. (Bill) Shemorry Photograph Collection (1-32A-200-2).

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number	Additional Documentation

Creaser Building
Name of Property
Williams, North Dakota
County and State
•
Name of multiple listing (if applicable)

Page _ 15

"J.B. Lyon Women's Wear window display, Williston N.D."" taken September 27, 1955, State Historical Society of North Dakota, William E. (Bill) Shemorry Photograph Collection (1-32A-203-2).

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number	Additional Documentation	
Section number	Additional Documentation	

Creaser Building
Name of Property
Williams, North Dakota
County and State
Name of multiple listing (if applicable)

16

Page _

ENTINCEA

J.B. Lyon Women's Wear interior, Williston N.D." taken ca. 1940, State Historical Society of North Dakota, William E. (Bill) Shemorry Photograph Collection (1-32A-201-1).

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number	Additional Documentation	Page
Section number	Additional Documentation	raye

Creaser Building
Name of Property
Williams, North Dakota
County and State
Name of multiple listing (if applicable)

<u>17</u>



"Band Day parade 1961, Veterans of Foreign Wars marching, Williston N.D." taken 1961, State Historical Society of North Dakota, William E. (Bill) Shemorry Photograph Collection (1-31B-6-22).

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number	Additional Documentation	Page
	/ dditional bocarrichtation	i ago

Creaser Building
Name of Property
Williams, North Dakota
County and State
Name of multiple listing (if applicable)

18



"Williston, Main Street, N.D." taken 1931, State Historical Society of North Dakota, William E. (Bill) Shemorry Photograph Collection (1-186-23-3).

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number	Additional Documentation

Creaser Building
Name of Property
Williams, North Dakota
County and State
Name of multiple listing (if applicable)

19

Page

Ca. 1920 photo, photographer unknown

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number	Additional Documentation
Occion manned	, taattorial Boodinontation

Creaser Building	
Name of Property	
Williams, North Dakota	
County and State	
Name of multiple listing (if applicable)	

20

Page

Photo Courtesy of Sylvia Larvick Rockney

The north side of the Creaser building is pictured the morning after the big fire. The ladder leaning on the wall was the only means of access to the second floor, the regular stairs facing Main Street having been destroyed. In back is the telephone building which was saved with only small smoke damage.





Published in Section 4 on page 1 of the Williston Herald Progress Edition 1927 June 23.

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number <u>Additional Documentation</u>

Creaser Building


Name of Property

Williams, North Dakota

County and State

Name of multiple listing (if applicable)


Page _____21















UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

REQUESTED ACTION: NOMINATION
PROPERTY Creaser Building NAME:
MULTIPLE NAME:
STATE & COUNTY: NORTH DAKOTA, Williams
DATE RECEIVED: 5/26/16 DATE OF PENDING LIST: DATE OF 16TH DAY: DATE OF 45TH DAY: 7/11/16 DATE OF WEEKLY LIST:
REFERENCE NUMBER: 16000442
REASONS FOR REVIEW:
APPEAL: N DATA PROBLEM: N LANDSCAPE: N LESS THAN 50 YEARS: N OTHER: N PDIL: N PERIOD: N PROGRAM UNAPPROVED: N REQUEST: N SAMPLE: N SLR DRAFT: N NATIONAL: N
COMMENT WAIVER: N
ACCEPT RETURN REJECT DATE
ABSTRACT/SUMMARY COMMENTS: Entered in The Madienel Register of Historic Places
RECOM./CRITERIA
REVIEWERDISCIPLINE
TELEPHONEDATE
DOCUMENTATION see attached comments Y/N see attached SLR Y/N
If a nomination is returned to the nominating authority, the nomination is no longer under consideration by the NPS.

RECEIVED 2280

To:

Keeper, National Register of Historic Places Claudia J. Berg/ Lorna Meidinger

From:

23 May 2016

Date: Subject:

National Register Nomination

MAY 26 2016

Nat. Register of Historic Places National Park Service

(Sala)	materials are submitted on this 23rd day of May 2016, for the nomination of the ing to the National Register of Historic Places.
	National Register of Historic Places nomination form on archival paper
	Multiple Property Nomination form on archival paper
	Photographs
·	USGS map(s)
	Sketch map(s)/figure(s)/exhibit(s)
	Pieces of correspondence
2	CDs
1	Signature Page
	Other:
COMMENTS:	
	Please insure that this nomination is reviewed
	This property has been certified under 36 CFR 67
	The enclosed owner objections do do not constitute a majority of property owners.
	Others