



Couiter Residence, 3162 Second Avenue,  
San Diego, CA 92103. *San Diego County*  
Photographer: Ray Brandes, January  
15, 1982. Negative property of the  
Drs. Utley, 3162 Second Avenue, San  
Diego, CA 92103. View from East to  
West. Photo #1 of 7 photos.





Coulter Residence, 3162 Second Avenue  
San Diego, CA 92103, *San Diego County*  
Photographer: Ray Brandes, January 15,  
1982. Negative property of the Drs.  
Utley, 3162 Second Avenue, San Diego,  
CA 92103

View of first floor facade and yard,  
looking East to West.

Photo #2 of 7 photos.





Coulter Residence, 3162 Second Avenue  
San Diego, CA 92103, *San Diego County*  
Photographer: Ray Brandes, January 15,  
1982. Negative property of the Drs.  
Utley, 3162 Second Avenue, San Diego,  
CA 92103

View of main entrance through arched  
doorway to main entryway.

Photo #3 of 7 photos.



Coulter Residence, 3162 Second Avenue,  
San Diego, CA 92103. *San Diego County*

Photographer: Ray Brandes, January 15,  
1982. Negative property of the Drs.  
Utley, 3162 Second Avenue, San Diego,  
CA 92103.

Side view of residence looking from the  
North to the South.

Photo #4 of 7 photos.





Coulter Residence, 3162 Second Avenue,  
San Diego, CA 92103., *San Diego County*  
Photographer: Ray Brandes, January 15,  
1982. Negative property of the Drs.  
Utley, 3162 Second Avenue, San Diego,  
CA 92103.

View from NE to SW showing the full  
2 1/2 stories with chimney stack.  
Photo #5 of 7 photos.



Coulter Residence, 3162 Second Avenue,  
San Diego, CA 92103 *San Diego County*

Photographer: Ray Brandes, January 15,  
1982. Negative property of the Drs.  
Utley, 3162 Second Avenue, San Diego,  
CA 92103.

View NE to SW reflecting overhanging  
roofline, mission tile and sashed  
windows.

Photo #6 of 7 photos.





Coulter Residence, 3162 Second Avenue,  
San Diego, CA 92103, *San Diego County*

Photographer: Ray Brandes, January 15,  
1982. Negative property of the Drs.

Utley, 3162 Second Avenue, San Diego,  
CA 92103

View of upper 1-1/2 stories from N to  
S at rear of house.

Photo #7 of 7 photos.