



GRIFFITH HOUSE

Aberdeen

Harford County, Md.

Photo by David C. Hodge

South facade

APR 18 1977

NOV 14 1978

South facade

IF PUBLISHED, PLEASE CREDIT:

DAVID C. HODGE
3103 WOOLSEY DRIVE
CHURCHVILLE, MD. 21028
301 - 734-4196



GRIFFITH HOUSE
Aberdeen

Harford County, Md.

Photo by David C. Hodge

From southeast

APR 18 1977

NOV 14 1978

from SE

IF PUBLISHED, PLEASE CREDIT:

DAVID C. HODGE
3103 WOOLSEY DRIVE
CHURCHVILLE, MD. 21028
301 - 734-4196



GRIFFITH HOUSE
Aberdeen
Harford County, Md.
Photo by David C. Hodge
West facade

APR 18 1977

NOV 14 1978

west facade

IF PUBLISHED, PLEASE CREDIT:

DAVID C. HODGE
3103 WOOLSEY DRIVE
CHURCHVILLE, MD. 21028
301 - 734-4196



GRIFFITH HOUSE

Aberdeen

Harford County, Md.

Photo by David C. Hodge

From northeast

APR 18 1977

NOV 14 1978

IF PUBLISHED, PLEASE CREDIT:

from NE

DAVID C. HODGE
3103 WOOLSEY DRIVE
CHURCHVILLE, MD. 21028
301 - 734-4196



GRIFFITH HOUSE

Aberdeen

Harford County, Md.

Photo by David C. Hodge

Exterior, East entrance door

APR 18 1977

NOV 14 1978

East entrance^{door} to exterior

DAVID C. HODGE
3103 WOOLSEY DRIVE
CHURCHVILLE, MD. 21028
301 - 734-4196

294-6



GRIFFITH HOUSE

Aberdeen

Harford County, Md.

Photo by David C. Hodge

South end wall, south room

APR 18 1977

NOV 14 1978

FLASH OBSCURED BY DOOR

DAVID C. HODGE
3103 WOOLSEY DRIVE
CHURCHVILLE, MD. 21028

301-734-4196

South end wall, S rm.

294-10



GRIFFITH HOUSE

Aberdeen

Harford County, Md.

Photo by David C. Hodge

South end wall, south room

APR 18 1977

NOV 14 1978

DAVID C. HODGE
3103 WOOLSEY DRIVE
CHURCHVILLE, MD. 21028
301-734-4196

S end wall, S rm-
294-4



GRIFFITH HOUSE

Aberdeen

Harford County, Md.

Photo by David C. Hodge

Interior, East entrance door

APR 18 1977

NOV 14 1978

DAVID C. HODGE
3103 WOOLSEY DRIVE
CHURCHVILLE, MD. 21028
301-734-4196

East Entrance interior
294-5