



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

South elevation, north view

1 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

South & east elevations, NW view

2 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

East elevation, West view

3 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

North elevation, South view

4 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

West elevation, East view

5 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

West elevations, East view

6 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

South elevation, door detail,

north view

7 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

Cast iron fence and brick sidewalk

North view

8 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

Carriage House, South elevation,

North view

9 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

Carriage House, West & North elev.

Southeast view

10 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

Outhouse, West & North elevations

Southeast view

11 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

Front parlor (ca. 1866), East view

12 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

Foyer (ca. 1866), door detail,

South View

13 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

Foyer (ca. 1866), door detail

South View

14 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

Stairway (ca. 1883), Northwest View

15 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

*Original stained glass panel from
1883 stairway projection*

16 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

Dining Room (ca. 1860), NE view

17 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

Stairway and hall (ca. 1860).

West view

18 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

Second floor hall (ca. 1860)

East View

19 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

Second Floor hall (ca. 1860),

West view

20 of 21



Merritt Insley Property

Leavenworth, Kansas

February 1986

Martha Hagedorn

Kansas State Historical Society

Sink (ca. 1883) in 1860 wing,

East view

21 of 21