

C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (1 of 17): Front facade and

south side; photographer facing north-

west.




C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (2 of 17): Front facade; photographer facing southwest.



C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (3 of 17): Rear of house and north side; photographer facing southeast.



C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (4 of 17): Rear of house and backyard; photographer facing east.



C. W. DEEN HOUSE Baxley, Appling County, Georgia

Photographer: James R. Lockhart

Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (5 of 17): Rear of house and south side, showing glassed-in side porch; photographer facing northeast.



C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (6 of 17): Porch detail, south side of house; photographer facing northeast.



C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (7 of 17): Detail of bay window and front entrance on front (east) porch; photographer facing southwest.



C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (8 of 17): First floor stairhall; photographer facing southwest.



C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (9 of 17): First floor stairhall; photographer facing northwest.



C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (10 of 17): First floor parlor; photographer facing southwest.



C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981

Date: November, 1981

Description (11 of 17): First floor dining room; photographer facing southeast.



C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (12 of 17): Built-in sideboard in dining room; photographer facing southwest.



C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (13 of 17): "Billiard" room; photographer facing south.



C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (14 of 17): Library; photo-


grapher facing east.



C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (15 of 17): Second floor southwest rear room; photographer facing southwest.



C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (16 of 17): Second floor southeast front bedroom; photographer facing northeast.



C. W. DEEN HOUSE Baxley, Appling County, Georgia Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (17 of 17): Second floor northwest rear bedroom; photographer facing north.