



HIRAM D. SCOTT HOUSE

NOV 23 1976

Scotts Valley, CA

Photographer: Agnes Lewis

Date: 1975

Negative at Scotts Valley

Historical Society.

1975 southern exposure of the
house with asbestos siding.



HIRAM D. SCOTT HOUSE

Scotts Valley, CA

NOV 23 1976

Photographer: Dennis Craig

Date: August 1976

Negative at Scotts Valley

Historical Society.

1976 southern exposure of the house
after removal of asbestos siding,
revealing original 1853 clapboard

20047



HIRAM D. SCOTT HOUSE

Scotts Valley, CA

NOV 23 1976

Photographer: Judy McAlpin

Date: March 1976

Negative at Scotts Valley

Historical Society.

Southern exposure of house - front door. Note etched panels

Photo 3 of 7

DOE APR 13 1977



HIRAM D. SCOTT HOUSE
Scotts Valley, CA

Photographer: Judy McAlpin

Date: March 1976

Negative at Scotts Valley

Historical Society.

Interior shot of fireplace in
sitting room.

Photo 4 of 7

DOE APR 13 1977

NOV 23 1976



HIRAM D. SCOTT HOUSE

NOV 23 1976

Scotts Valley, CA

Photographer: Judy McAlpin

Date: March 1976

Negative at Scotts Valley Historical

Historical Society.

View of 1853 clapboard and 1930s
asbestos siding

Photo 5 of 7

NOTE APR 13 1977



HIRAM D. SCOTT HOUSE

NOV 23 1976

Scotts Valley, CA

Photographer: Judy McAlpin

Date: March 1976

Negative at Scotts Valley

Historical Society.

View of whitewashed random width
planks in attic area.

Photo 6 of 7

DOE APR 13 1977



HIRAM D. SCOTT HOUSE

Scotts Valley, CA

Photographer: Unknown NOV 23 1976

Date: 1912

Negative at Scotts Valley

Historical Society.

1912 southern exposure of the
house at original location.

Photo 2 of 7

APR 13 1977