


KENTUCKY HISTORIC RESOURCES INVENTORY

Site No. PDF 44

45

| | | | |
|--|---|--|--|
| 1. Historic Name(s) <u>Watson Store (F.M.R.A.),</u> Original Owner <u>George and James Watson</u> | | 22. ADD/County <u>NKADD/Pendleton</u> 096 | |
| 2. Present Name <u>504 W. Shelby Street</u> | | 23. U.S.G.S. Quadrant (15'/75') <u>Falmouth</u> 137 | |
| 3. Location <u>NW corner Park and Shelby</u> | | 24. UTM Reference <u>16</u> <u>731930</u> <u>4284320</u> Zone Easting Northing | |
| 4. Owner's Name <u>Kincaid Development Co.</u> | | 25. Coordinate Accuracy <input type="checkbox"/> | |
| 5. Owner's Address <u>c/o Veldon Boggs, 405 Robbins, Falmouth, Ky. 41040</u> | | 26. Prehistoric Site Object Historic Site Structure Building Other | |
| 6. Open to Public Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> | 7. Visible from road Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> | 8. Ownership Private <input checked="" type="checkbox"/> Local <input type="checkbox"/> State <input type="checkbox"/> Federal <input type="checkbox"/> | |
| 9. Local Contact/Organization | | 27. National Register District Name: <u>Historic Resources of Falmouth</u> | |
| 10. Site Plan with North Arrow <u>51NW-1-9 less than 1 acre</u>  | | 11. Architect 12. Builder 13. Date <u>1873</u> A. <input checked="" type="checkbox"/> B. <input type="checkbox"/> 14. Style A. Vernacular <input checked="" type="checkbox"/> B. <input type="checkbox"/> 15. Original Use <u>store</u> <input checked="" type="checkbox"/> 16. Present use <u>vacant, being restored</u> 17. Condition <u>poor</u> <input checked="" type="checkbox"/> | |
| 18. Description <u>Original stone foundation has been replaced with concrete. Western portion of building is one story, with shed roof, one door and one window on Shelby, one door at rear. Exterior of west facade is board and batten. Rest of building sheathed in beveled siding. Eastern portion is two story, with gable end roof. Lower level has two plate</u> (Continue on Back) (over) | | 28. Significance Evaluation <u>National Register</u> <input checked="" type="checkbox"/> 29. Status <input type="checkbox"/> Date National Landmark <input type="checkbox"/> National Register <input type="checkbox"/> Landmark Certificate <input type="checkbox"/> Kentucky Survey <input type="checkbox"/> Local Landmark <input type="checkbox"/> HABS/HAER <input type="checkbox"/> 30. Historic Theme Primary <u>commerce</u> <input checked="" type="checkbox"/> Secondary <u>Architecture</u> <input checked="" type="checkbox"/> Other <input type="checkbox"/> 31. Endangered Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> 32. Preservation Project Status <input type="checkbox"/> Actual Cost in \$1,000s <input type="checkbox"/> | |
| 19. History <u>Built by Watson brothers, George and James, in 1873. It was built as a store, but has had many uses during its history. Purchased by Kincaid Development Co. in 1982--currently vacant, in process of rehabilitation.</u> | | 33. ATTACH PHOTO <u>see photos 30, 31</u> | |
| 20. Significance <u>19th century commercial building not located in central business district; probably related to railroad, original storefront intact.</u> | | Roll No. <u>6</u> Picture No. <u>9, 10</u> Direction <u>rear (N), front (SE)</u> | |
| 21. Source of Information <u>Barton microfilms Virginia Boggs</u> | | 34. Prepared by: <u>Lori A. Feldman</u> 35. Organization <u>P--NKADD</u> 36. Date <u>82</u> 37. Revision Dates 38. Staff Review 12/82 SCG | |

18 continued : glass windows and one door; two 8 over 8 double hung windows above. Red standing seam metal roof, chimney at rear, box cornice with return and brackets in the front gable end. Porch across 2 story portion on Shelby St. side; stairs originally on east facade, now new stairs installed at rear. Interior lower level is two long rooms divided by row of turned posts. Apartment on second floor has original woodwork, windows, and molded baseboard.