



## JORDAN HOUSE

Carthage, Leake County, Mississippi

Looking northerly, the southerly facade of the Jordan House during restoration. Restoration plans call for the removal of the plastic shutters, the removal of the brick infill between the supporting piers, and the installation of a new iron railing on the deck of the hipped roof.

Mary W. Miller, Historic Natchez Foundation,  
February 1982.



JORDAN HOUSE

Carthage, Leake County, Mississippi

Looking northwesterly, the stairway and the second-story hallway of the Jordan House showing the millwork after removal of later paint layers.

Mary W. Miller, Historic Natchez Foundation,  
February 1982.

Photo 2 of 4



JORDAN HOUSE

Carthage, Leake County, Mississippi

Looking northerly, the easterly front downstairs room showing the stripped and re-finished millwork.

Mary W. Miller, Historic Natchez Foundation,  
February 1982

Photo 3 of 4



JORDAN HOUSE

Carthage, Leake County, Mississippi

Looking easterly, the columned divider  
of the northwestern second-story bedroom.

Mary W. Miller, Historic Natchez Foundation,  
February 1982.

Photo 4 of 4