

Form (7/72		0-301a UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE		STATE Maryland						
		NATION	AL REGISTER OF HISTORIC PLACES		COUNTY					
NATION			AL REGISTER OF HISTORIC PLACES		Anne Arundel					
		PROP	ERTY PHOTOGRAPH FORM		FOR NPS USE ONLY					
		(Type all entries - attach to or enclose with photograph)			ENTRY NUMBER	DATE				
S	-									
z	1.00	NAME			1 1					
0			Thomas Viaduct							
		AND/OR HISTORIC: Thomas Viaduct								
<u> </u>	2.	LOCATION								
		STREET AND NUMBER: C&O-B&O Railroad where it crosses Patapsco River, 2200 feet								
U		northwest of U.S. Route 95.								
		CITY OR TOWN:								
R										
			near Relay							
-1		STATE:	14 1 1	CODE COUNTY:		CODE				
S			Maryland	24 I	Baltimore	005				
Z	3.	PHOTO REFERENCE								
-		PHOTO CREDIT: National Park Service								
		DATE OF PHOTO: 1964; verified July 1974								
ш		NEGATIVE FILED AT:								
ш		National Park Service, Washington Negative File								
5	4.	DENTIFICATION								
•••		DESCRIBE VIEW, DIRECTION, ETC.								
		View of Thomas Viaduct looking North.								

☆ U.S. GOVERNMENT PRINTING OFFICE: 1973-729-152/1446 III-1



Thomas Viaduct, Baltimore and Ohio Railroad, Relay. The curve of the viaduct, the massive arches and the half-columns are especially noteworthy in this photograph.

December, 1962 National Park Service Photograph



Form No (7/72)	o. 10-301a UNITE	UNITED STATES DEPARTMENT OF THE INTERIOR		Maryland					
	NATION	NATIONAL REGISTER OF HISTORIC PLACES			Baltimore				
	PROP	ERTY PHOTOGRAPH FO	RM	FOR NPS USE ONLY					
	/7	(Type all entries - attach to or enclose with photograph)			DATE				
S	(Type all e								
Z	1. NAME								
0	соммон: Т	COMMON: Thomas Viaduct							
-	AND/OR HISTORIC: T								
	2. LOCATION								
U	STREET AND NUMBER	STREET AND NUMBER: C&O-B&O Railroad where it crosses Patapsco River, 2200 feet							
5		northwest of U.S. Route 95.							
œ	CITY OR TOWN:	near Relay							
H	STATE:		CODE COUNTY:		CODE				
s.		Maryland	24	Baltimore	005				
Z 3. PHOTO REFERENCE									
-	PHOTO CREDIT:								
	DATE OF PHOTO: July 1974								
ш	NEGATIVE FILED AT:	Historic Sites Survey, National Park Service							
ш	4. IDENTIFICATION								
S		DESCRIBE VIEW, DIRECTION, ETC.							
		View of intrusions around viaduct							