Form No. 10-300 (Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

TECEIVED MAY 5 1978		H	Ď		6	8	3	5	φ
	OR	NPS	USE C	NLY					
	1EGE	IVEL	,	(ANY	5	1978		

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- COMPLETE APPLICABLE SECTIONS

1 NAME

HISTORIC

/John Knap House

AND/OR COMMON

2 LOCATION

STREET & NUMI	984 Stillwater	Road	NOT FOR PUBLICATION	
CITY, TOWN	Stamford		CONGRESSIONAL DISTR Fourth - Stewart B	
STATE	Connecticut	CODE	COUNTY Fairfield	CODE () /

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESI	ENTUSE
DISTRICT	PUBLIC		AGRICULTURE	MUSEUM
X_BUILDING(S)		UNOCCUPIED	COMMERCIAL	PARK
STRUCTURE	ВОТН		EDUCATIONAL	X PRIVATE RESIDENCE
SITE	PUBLIC ACQUISITION	ACCESSIBLE	ENTERTAINMENT	RELIGIOUS
OBJECT	IN PROCESS	YES: RESTRICTED	GOVERNMENT	SCIENTIFIC
•	BEING CONSIDERED	XYES: UNRESTRICTED	INDUSTRIAL	TRANSPORTATION
		NO	MILITARY	OTHER:

4 OWNER OF PROPERTY

			· · · · · · · · · · · · · · · · · · ·	
NAME	Virginia T. Da	vis		×*
STREET & NU				
	984 Stillwate	Road		
CITY, TOWN			STATE	
	Stamford		Connecticut 06902	
5 LOCA	FION OF LEGAL D	ESCRIPTION		
COURTHOUS				
	DEEDS.ETC Municipal	Building		
STREET & NU			·	
	429 Atlan	ic Street		
CITY, TOWN	Ctowfound		STATE	
	Stamford		Connecticut 06901	
6 REPRE	SENTATION IN I	EXISTING SURVEY	(S	1
TITLE				
	Works Progress	Administration (Census of Old Buildings	
DATE				
	1930s	FEDER	AL XSTATE COUNTY LOCAL	
DEPOSITORY SURVEY REC	FOR ORDS Connecticut St	ate Library		
CITY, TOWN			STATE	
	Hartford		Connecticut 06103	

7⁻ DESCRIPTION

CON	DITION	CHECK ONE	CHECK ONE CHECK ONE	
X_EXCELLENT	DETERIORATED	XUNALTERED		SITE
GOOD FAIR	RUINS UNEXPOSED	ALTERED	MOVED	DATE

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The John Knap House is located in west central Stamford, Connecticut, on the west side of Stillwater Road half way between the Merritt Parkway and the Connecticut Turnpike, two miles from each. Set back approximately 30 feet from the road where it curves to the west, the house faces south on a three-quarters of an acre site of uneven ground. Despite its urban neighborhood the house has a pastoral setting. It is separated from the street by a great stone wall four feet high and two and one-half feet wide capped by flat stones up to six feet long. Similar walls run across the back yard. In the side yard is an old, open, stone¹well: "Several tall trees both front and back and on thick hedge across the front serve to insulate the house from the sights and sounds of the city.

The plan of the Knap House of only two rooms on each floor with chimney in the center is the same as that of the Older Bushnell House in Old Saybrook, Connecticut, shown in Figure 3 by J. Frederick Kelly in his definitive study of early domestic architecture in Connecicut. Kelly's diagram shows one window on each side of the front door which is the same arrangement as found at the Knap House.

The east end of the house faces the street, and the front facade faces south. In the center of the facade is the doorway with a four light transom. There is one twelve-over-eight window on each side of the doorway at ground floor level. At the second floor level are three evenly spaced windows. The windows are 19th century replacements.

The west gable has an 18 inch overhang at the attic level. This is the only overhang in the house. The west end of the house also has a window in the attic and at the second floor level (off center to the south), and a ground floor door.

The rear (north) facade has a modern one story addition with low pitched roof which serves the same purpose as a colonial lean-to in that it houses the kitchen. Above it are four windows, the two in the center having been added recently.

The east end of the house has a window in the attic gable and two windows at each of the first and second floor levels, symmetrically placed.

The exterior sheathing of the house is clapboards, authentically replaced in mid-20th century. They are made of red cedar, have five inches exposed to the weather and are without beading or taper. On the front the clapboards are unpainted and on the other three sides they are painted a dark blue/grey.

The stone chimney rises from the center of the composition shingled roof, and has a stone molding just below its top. Roof framing includes rafters fitted together at the ridge line by use of mortise and tenon with peg; there is no ridge pole.

An old barn is on the premises. Thought to be more than 200 years old, it is in good condition.

The fieldstone foundations measure 22 feet 6 inches by 40 feet 10 inches. The chimney, of the same stone, at its base measures 11 feet by 11 feet 6 inches. There is a cellar under the east room only. First floor joists visible in the cellar are undressed timbers.

During 20th century restoration three of the sills and one or

(continued)



MAY 5 1978

PERIOD	AREAS OF SIGNIFICANCE CHECK AND JUSTIFY BELOW				
PREHISTORIC 	ARCHEOLOGY-PREHISTORIC ARCHEOLOGY-HISTORIC AGRICULTURE XARCHITECTURE ART COMMERCE COMMUNICATIONS	COMMUNITY PLANNING CONSERVATION ECONOMICS EDUCATION ENGINEERING EXPLORATION/SETTLEMENT INDUSTRY 	LANDSCAPE ARCHITECTURE LAW LITERATURE MILITARY MUSIC PHILOSOPHY POLITICS/GOVERNMENT	RELIGION SCIENCE SCULPTURE SOCIAL/HUMANITARIAN THEATER TRANSPORTATION OTHER (SPECIFY)	

SPECIFIC DATES 1705

BUILDER/ARCHITECT John Knap

STATEMENT OF SIGNIFICANCE

mented, early date of its construction (1705), and from the high percnetage of original fabric which remains in the house. It has been well maintained throughout its history and has not been altered. It is a classic example of a center chimney house without lean-to and is of museum quality.

In tracing the origins of the house, there is a clean line in the land records back to when Samuel Knap was the owner. The 1781 Erskine map at the New-York Historical Society shows his name at the curve in the road where the house is located, confirming his ownership in that year. Probate records show that Samuel Knap purchased the house in 1765 from the estate of his father, Lt. John Knap, who was the son of the builder, Capt. John Knap. Study of the land records of adjoining properties reveals that Capt. John Knap marked trees along the boundaries of his property with the initials J K. These initials are cut in the stone of the chimney of the house, in the front just above the roof line.

Acquisition of the first parcel of land for the Knap farm was recorded 28 February 1698. Additional purchases were made made up to 1710. The presence of the house is indicated by a 2 April 1712 reference to it in the description of a property across the street which is said to be a certain distance from a road intersection and across from "ye dwelling house and barn of John Knap." The intersection is still there and when measured off the point is found to be opposite the house. These records demonstrate that the house was built not before 1698 and not after 1712. The mid point between these two limits is 1705, and this year is assigned as the date of the origin of the house.

The first Knap to come to Stamford was Nicholas Knap who arrived in 1648 as a member of the second Wethersfield group. (The first group from Wethersfield, who founded Stamford, arrived in 1641.) His grandson was Captain John Knap who built the house. The builder was a captain in the militia, a farmer, and also a surveyor and fence viewer for the town. The Knap family occupied the house until 1835 and the property was a working farm until 1924.

An idiosyncracy in the early history of the house was discovered during 20th century restoration. When the framing of the second floor of the east end, facing the street, was uncovered it was found to provide for a larger opening than a normal window. The supposition is that this opening was for goods being hoisted to the second floor for storage, the room serving as a small warehouse. The absence of a fireplace in the upstairs east room supports this theory.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

J. Frederick Kelly, <u>The Early Domestic Architecture of Connec-</u> <u>ticut</u>, New York: Dover Publications, Inc., 1963 (reprint of work first published by Yale University Press in 1924).

Stamford Land Records, various entries.

				-
10 GEOGRAPHICAL DA				
UTM REFERENCES				:
		BL ZONE E DL	ASTING NORTI	
VERBAL BOUNDARY DESCRIPT The nominated prope roughly 235 by 145	rty occupies		amford map 50-2	9 and is
e set a na na karaka -	N. CAN	·	おういいよう	
	an a		and the area of the second	-
LIST ALL STATES AND CO	UNTIES FOR PROPERT	IES OVERLAPPING	STATE OR COUNTY BOU	INDARIES
STATE	CODE	COUNTY		CODE
STATE	CODE	COUNTY		CODE
11 FORM PREPARED B NAME / TITLE David F. R			· · · ·	
ORGANIZATION			DATE 17 Octobe	er 1977
STREET & NUMBER 33 Sunrise	Hill Drive	c. Y	теlерноне 203 521-2	2518
CITY OR TOWN West Hartf	ord	مىلىمەر مىلىكى مىلىرىمىرىمىيى بۇرىمە يە	STATE Connectio	cut
12 STATE HISTORIC P	-'		- 二、二、二、二、二、二、二、二、二、二、二、二、二、二、二、二、二、二、二、	N
THE EVALUA NATIONAL	TED SIGNIFICANCE OF STAT		LOCAL	
As the designated State Historic Prese hereby nominate this property for inc criteria and procedures set forth by the STATE HISTORIC PRESERVATION OFFICE	lusion in the National F e National Park Service.	Register and certify	Fig. 1 Applies of the South Control of the South	
TITLE PIARETM, COMPE	The HISTON	me comm	SS- ADATE S	1178
FOR NPS USE ONLY I.HEREBY CEBTIFY THAT THIS PR	OPERTY IS INCLUDED	IN THE NATIONAL	DATE	2/5725
ATTEST: BUC La Low		IESEN VATION	DATE MOLA	LS 1979

Form No. 10-300a (Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

FOR NPS L	ISF ONLY		
RECEIVED			
	Beau w		
	MAY 5	1070	
		1978 ees	1070
DOVATION DATE	ERED		₩ NGU S
Construction of the Construction of the		·····	

John Knap House CONTINUATION SHEET Description ITEM NUMBER 7 PAGE 1

two feet of the bases of the front posts were replaced due to the deteriorated condition of the originals; otherwise all framing is original. All eight posts are flared or "gunstock" in shape, with beaded casing.

On the first floor are two stone fireplaces. In the east room the opening measures ten feet two inches wide by five feet four inches high, and has a bake oven in the back wall. The lintel is a huge timber. There is no mantel. This room has a summer beam. It is 18 inches in width.

In the west room the fireplace opening originally measured nine feet ten inches wide by four feet eight inches high but was partially filled in and made smaller during the 19th century. The original bolection molding is in place, however, and it is immense, measuring ten inches in width and 4 3/4 inches in maximum projection. In addition, this fireplace wall has fine, original pine paneling. The centers of the panels are raised to the same height as the stiles and rails, which have beaded edges.

Original stone steps run from first floor to the cellar along the front of the chimney, an arrangement "indicative of very early work," according to Kell y. Above them the stairway from the first to the second floors, which is a replacement of the original, runs from right to left in front of the chimney wall.

Upstairs there is a fireplace only in the west room and this room has walls and ceiling of wide boards fastened with rose headed nails and believed to be original. Such a ceiling is quite unusual; customarily the structural members were left exposed. The floors in both rooms upstairs and in front of the stairs at ground level are original.

The John Knap House is in an excellent state of repair and is impeccably maintained as a private residence.

 J. Frederick Kelly, <u>Early Domestic Architecture of Connec-</u> <u>ticut</u>, p. 7.
 2. Ibid., p. 8. UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

FOR NPS USE ONLY RECEIVED FEB 2 6 1979 DATE ENTERED MAR 5 1979

Knap, John, House Stamford, CT

CONTINUATION SHEET Description ITEM NUMBER 7 PAGE 2

Addendum

During the centuries that the John Knap House remained in the Knap family (1705-1924) few changes were made. Fenestration on the front (south) facade appears never to have been changed. On the east facade (toward the street) the second floor goods door (see main body of Description) was replaced with the present two windows somewhere along the line. In like fashion, there were no windows originally on the west end of the house at second floor level. On the back of the house (north facade) there was a small back porch of undetermined nature mentioned in the land records as early as the 18th century. By the 19th century it had developed into a milk shed.

In 1925 the new owner installed the first bathroom. During this period of ownership a two story porch was added on the west end, and French doors were cut in to provide access to it at both first and second stories. The porch has been removed but the doors remain. Several interior partitions and alterations were introduced from 1925 to 1955 that have subsequently been reversed. At this time the milk shed was made into a laundry. Also, the wall in front of the stairs was removed.

During the years 1955/1965 the milk shed/laundry was further developed into a kitchen. The stairs were restored with new balusters. The house was rewired. The two, small, bathroom windows on the north side were cut in. It was at this time that the new clapboards and sections of sills and posts (see main body of Description) were installed as replacements of deteriorated fabric, in each case duplicating the originals in size, shape, and contour. The wide clapboards covering the west end second floor and the west one-third of the north side (over the kitchen -- see photo) were not replaced at this time and are thought themselves perhaps to be earlier replacements of the original clapboards. The floors of the two downstairs rooms were replaced using old, wide boards from another structure.

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM



John Knap House
CONTINUATION SHEET Significance ITEM NUMBER 8 PAGE 1

The John Knap House is considered by the Stamford Historical Society to be the second oldest house in Stamford. Since its constuction the house has undergone remarkably few changes, and exists today as a rare example of turn-of-the-18th-century architecture.

1. Stamford Land Records, Book G, page 415.

- 2. Ibid., Book A, page 309.
- 3. Ibid., Book C, page 419.

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM



Knap, John, House Stamford, CT

CONTINUATION SHEET Significance ITEM NUMBER 8 PAGE 2

Addendum

The remarkable integrity of the John Knap House results largely from the more than 200 year span of ownership by the Knap family during which little was done to the house. Its survival at all in the midst of a good sized city is unusual, and its survival with all original framing intact is especially notewoethy. In addition to the timbers of the framing, the stone chimney from its square base to its molded top, with fireplaces, also survives as do the flooring in front of the stairs on the first floor, the raised paneling of the west first floor room, the entire second story flooring, the wall sheathing and ceiling boards of the west chamber, and the beaded casing of the posts. The pastoral site with rugged stone walls and big trees is equally surprising and valuable, especially considering the urban location.

It is the presence of wide, one inch, oak (or chestnut) vertical sheathing without interruption under the clapboards that suggests the second floor west wall has never had fenestration, except for the 1920s French doors, and interruption in such sheathing on the east wall that suggests the early presence of the second floor goods door. The avsence of any change in the fenestration of the main facade since 1705 adds to the importance of the house. On the interior the floor plan remains unchanged, except for the addition of bathrooms. The present kitchen results from continuation in the development of a porch/ milk shed/laundry that had its start perhaps 200 years ago.