


81-268

Christ Church
Guilford, Vermont
Credit: Hugh H. Henry
Date: November 1981
Negative filed at Vermont Division for
Historic Preservation
Description: West and south elevations;
environs. View looking northeast.
Photograph 1



81-188

Christ Church
Guilford, Vermont
Credit: Hugh H. Henry
Date: November 1981
Negative filed at Vermont Division for
Historic Preservation
Description: East and north elevations.
View looking southwest.
Photograph 2



Christ Church
Guilford, Vermont
Credit: Hugh H. Henry
Date: November 1981
Negative filed at Vermont Division for
Historic Preservation
Description: Interior toward altar.
View looking southwest.
Photograph 3