



ANDALUSIA

DEC 04 1979

Milledgeville vicinity, Baldwin County,
Georgia

Photographer: James R. Lockhart

Date: June 1979

Negatives filed: Georgia Department of
Natural Resources

Photograph: Main house from across pond;
photographer facing north

FEB

8 1980



ANDALUSIA

DEC 04 1979

Milledgeville vicinity, Baldwin County,
Georgia

Photographer: James R. Lockhart

Date: June 1979

FEB 8 1980

Negatives filed: Georgia Department of
Natural Resources

Photograph: S.E. (front) facade of main
house; photographer facing northwest



DEC 04 1979

ANDALUSIA

Milledgeville vicinity, Baldwin County,
Georgia

FEB 8 1980

Date: June 1979

Negatives filed: Georgia Department of
Natural Resources

Photograph: N.E. elevation of main house;
photographer facing north



DEC 04 1979

ANDALUSIA

Milledgeville vicinity, Baldwin County,
Georgia

Photographer: James R. Lockhart

Date: June 1979

Negatives filed: Georgia Department of
Natural Resources

FEB 8 1980

Photograph: N.W. (rear) elevation of
main house and outbuilding and water
tank; photographer facing S.E.



ANDALUSIA

DEC 04 1979

Millēdgeville vicinity, Baldwin County,
Georgia

Photographer: James R. Lockhart

Date: June 1979

Negatives filed: Georgia Department of
Natural Resources

Photograph: S.W. elevation of main house;
photographer facing S.E.

FEB 8 1980



DEC 04 1979

ANDALUSIA

Milledgeville vicinity, Baldwin County,
Georgia

Photographer: James R. Lockhart

Date: June 1979

Negatives filed: Georgia Department of
Natural Resources

Photograph: Entrance hall, main house;
photographer facing northwest



ANDALUSIA

DEC 04 1979

Milledgeville vicinity, Baldwin County,
Georgia


Photographer: James R. Lockhart

Date: June 1979

FEB 8 1980

Negatives filed: Georgia Department of
Natural Resources

Photograph: Parlor on ground floor of
main house; photographer facing S.E.



ANDALUSIA

DEC 04 1979

Milledgeville vicinity, Baldwin County,
Georgia

Photographer: James R. Lockhart FEB 8 1980

Date: June 1979

Negatives filed: Georgia Department of
Natural Resources

Photograph: Outbuilding and peafowl cages;
photographer facing north



DEC 04 1979

ANDALUSIA

Milledgeville vicinity, Baldwin County,
Georgia

Photographer: James R. Lockhart FEB 8 1980

Date: June 1979

Negatives filed: Georgia Department of
Natural Resources

Photograph: Tenant house near main house;
photographer facing south



ANDALUSIA

DEC 04 1979

Milledgeville vicinity, Baldwin County,
Georgia

Photographer: James R. Lockhart FEB 8 1980

Date: June 1979

Negatives filed: Georgia Department of
Natural Resources

Photograph: Barn to left, milk processing
building to right; photographer facing
north



DEC 8 1979

ANDALUSIA

Milledgeville vicinity, Baldwin County,
Georgia

Photographer: James R. Lockhart

Date: June 1979

Negatives filed: Georgia Department of
Natural Resources

Photograph: Tenant house; photographer
facing S.W.

FEB 8 1980