

Grouping: Stalnaker Hall

Location: WVU Downtown Campus, Morgantown, WV

Monongalia County

Photo Credit: Lynette Jones

Negative Filed At: Dept. of History, WVU

Description of Photo: Southwest Wall - center section

Direction: Camera facing northeast

tion



Grouping: Stalnaker Hall

Location: WVU Downtown Campus, Morgantown, WV

Monongalia County

Photo Credit: Lynette Jones

Negative Filed At: Dept. of History, WVU

Description of Photo: Southwest Wall - center section Direction: Camera facing north



Grouping: Stalnaker Hall

Location: WVU Downtown Campus, Morgantown, WV

Monongalia County

Photo Credit: Lynette Jones

Negative Filed At: Dept. of History, WVU

Description of Photo: Southwest wall - Northwestern soc

section

Direction: Camera facing northeast



Property Name: West Virginia Univ. Thematic Grouping: Stalnaker Hall

Location: WVU Downtown Campus, Morgantown, WV Monongalia County

Photo Credit: Lynette Jones

Negative Filed At: Dept. of History, WVU

Description of Photo: Northeastern exterior wall

Direction: Camera facing north

40F.8



Grouping: Stalnaker Hall

Location: WVU Downtown Campus, Morgantown, WV

Monongália County

Photo Credit: Lynette Jones

Negative Filed At: WVU Communicationss

Description of Photo: Northeastern exterior wall

- southeastern section

WIVI

Direction: camera facing southeast



Property Name: West Virginia Univ. Thematic Grouping: Stalnaker Hall

Location: WVU Downtown Campus, Morgantown, WV Monongalia County

Photo Credit: Lynette Jones

Photo Credit: Lynette Jones
Negative Filed At: WVU Communications
Description of Photo: Southwest exterior wall

Direction: Camera facing southeast



Property Name: West Virginia Univ. Thematic Grouping: Stalnaker Hall

Location: WVU Downtown Campus, Morgantown, WV Monongalia County

Photo Credit: Lynette Jones

Negative Filed At: Dept. of History, WVU Description of Photo: Southeast exterior wall

Direction: camera facing northwest



Grouping: Stalnaker Hall

Location: WVU Downtown Campus, Morgantown, WV

Monongalia County

Photo Credit: Lynette Jones

Negative Filed At: Dept. of History, WVU

Description of Photo: Southwest wall - southeastern

section

Direction: Camera facing east

80 F.8

section