

BANK OF JERSEY Jersey, Walton County, Georgia Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: August, 1982 Description (1 of 7): Front facade of building; photographer facing southwest.



BANK OF JERSEY Jersey, Walton County, Georgia Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: August, 1982 Description (2 of 7): Front facade and south side of building; photographer

facing west.



BANK OF JERSEY Jersey, Walton County, Georgia Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: August, 1982 Description (3 of 7): Rear and north side of building; photographer facing east.



BANK OF JERSEY Jersey, Walton County, Georgia Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: August, 1982 Description (4 of 7): Detail of south wall; photographer facing northwest.



BANK OF JERSEY Jersey, Walton County, Georgia Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources

Date: August, 1982
Description (5 of 7): Interior, front room;
photographer facing southwest.



BANK OF JERSEY Jersey, Walton County, Georgia Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: August, 1982 Description (6 of 7): Interior, rear room; photographer facing west.



BANK OF JERSEY Jersey, Walton County, Georgia Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: August, 1982 Description (7 of 7): Interior, rear room; photographer facing south.