HISTORIC PROPERTY INVENTORY FORM

IDENTIFICATION SECTION			Office of Archaeology and 111 W. 21st Ave. KL-11	Historic Preservation
20, 200		LOCATION SECTION	Olympia, WA 98504	and the set
Jdiles	Knuppenburg House		(206) 753-5010	FEB 18 1987
Site Name: Historic	ward House	Street Number <u>111 S. 9th St.</u>	(Union)	· · • • 18.51
Common <u>UDNG</u> Field Recorder: J. Kipp/G. (City/Town Yakima	Zip Code <u>98901</u> Range <u>19</u> Sect <u>19</u> % Se	
		County <u>39</u> Twp. <u>13</u>	. Range <u>19</u> Sect <u>19</u> % Se	ect <u>NE</u> % % Sect <u>SE</u>
	tom II	Tax No./Parcel No. 191319-14412	-	
Owner's Name: Newman, Will Street 111 S. 9th S		UTM References Zone <u>10</u>	Easting692100	_Northing <u>51638.60</u>
Training and the second s		Acreage: Less than one.		Yakima East (7.5)
City/Town <u>Yakima</u>				
County <u>39</u>		Legal boundary description		Scale 1:24,000
Zip Code <u>98901</u>		Frances E. Dunnings Vil	la	
Status:		Lots, Lot 12.		
		·		
National Register				
State Register				
Survey / inventory				
Determined Eligible		PHOTOGRAPHY		
Other (NHL, HABS, HAER)	Indicate 🛛	-		
Classification	Date:	Photography Neg. No.: 12-3		
Classification	Date.	(Roll No. + Frame No.)		
District 🔲	·			
Site		Date: 9/3/85		
Building		Date		
Building 🛛 🖾 Structure 🗖				
Object				
DESCRIPTION SECTION				
Materials & Features/Structural Typ	>es :		Style/Form: (Check one or more of	the following)
Roof Material:	Pool Turne	En la detta d		
Wood Shingle	Roof Type:	Foundation:	Pioneer/Homestead	Dutch Colonial Image: Colonial Spanish Colonial Image: Colonial English Revival Image: Colonial Bungalow Image: Colonial Craftsman Image: Colonial
-		ip 🗌 Log 🗍 yramid 🗌 Post & Pier 🗌	Greek Revival	Spanish Colonial
Asbestos/Asphalt Shingle Slate			Gothic Revival	English Revival
Tar			Italianate	Bungalow
		ther (specify)	Second Empire	
Metal (specify)		Block	Stick/Eastlake	American Foursquare/
Other (specify)	_ 0	Poured	Queen Anne	Classic Box
		Brick 🔛	Shingle Style	Prairie Style
		Other (specify)	RichardsonianRomanesque 🛛	Classic Box Image: Classic Box Prairie Style Image: Classic Box Art Deco/Moderne Image: Classic Box Commercial Vernacular Image: Classic Box
Cladding (Exterior Wall Surface	ae).		Chicago School/	Commercial Vernacular
Log		Height/No. of Stories:	Sullivanesque	Vernacular 🔂
Horizontal Wood Siding	Rustic/Novelty	One 🔲	Beau Arts Classicism 🛛 🗍	Other (specify)
Horizontal Wood Siding	Clapboard	One and one-half	Princess Anne	
		Two	Neo-Colonial	
	Split Shakes	Two and one-half	_	Fenton
		Three		TENIGA
Wood Shingle	Re-sawn	Other (specify)		
	Machine Shingle		• • •	
Asbestos/Asphalt Shingle		A 1 1 1 1 1 1 1		
Brick Masonry		Integrity: (include detailed		
		'Additional Descri	ption section) E 5 8 X	
Stone Masonry	Ľ	Additions to house plan		
Stucco	Ľ	Changes to windows		
Terra Cotta	Ľ	Changes to roof shape		C NC
Carrara Glass		÷ ,		
Vinyl/Aluminum Siding		Changes to interior plan		
Other (specify)	0	Other (specify)		

State of Washington

NARRATIVE SECTION

Areas of Significance/Study Unit Themes: (check one or more of the following)

Agriculture		Conservation	Military
Architecture/Landscape Architecture	$\mathbf{\Sigma}$	Education	Politics/Government/Law
Arts		Entertainment / Recreation	Religion
Commerce		Ethnic Heritage (specify)	 Science & Engineering
Communications		Health/Medicine	Social Movements/Organizations
Community Planning/Development		Manufacturing/Industry	Transportation
			Other (Specify)

Statement of Significance: (Reference names, dates, events, areas of significance/study

	unit themes)	
Date of Construction:	<u></u>	-
Architect/Builder:		_
Historical Significance:		

The residence at 111 South 9th Street (Union) is associated with North Yakima's earliest development period: 1885- 1900. Properties in Frances E. Dunning's Villa Lots, platted December 15, 1896, were usually sold in parcels of several lots and small farms were established in this section at the eastern edge of town. The Knuppenburg house is significant as a vernacular house of the late 19th and early 20th century designed and built by tradesmen carpenter/contractors for modest/middle income families. The vernacular elements dominate the front-facing gambrel roof and are carried into pedimented segmental brick arches above windows and doors. The brick masonry cladding is unusual for early modest residences built in Yakima where clapboard siding prevailed. The house is unique and well-preserved. This residence is also important for its association with the original owner, contractor James A Knuppenburg. Knuppenburg's wife Georgia purchased the property from Frances Dunning in 1897. She sold the property to Henry H. Tinkham in 1902. City Directories, 1903-1912, do not list Tinkham. Tinkham owned the property until 1931. Other long-term property owners included Alvin L. (a farmer) and Cora M. Hersom (1931-1977). Although Newman's name still appears on the Assessor's records, Philip R. Jongeward purchased the residence in 1977 from Newman. Jongeward, a descendent of early Dutch settlers in Moxee, has restored the house to its original condition.

Additional Descripton of Physical Appearance & Significant Architectural Features: (Architectural significance; can include interior & site features; address integrity issues specifically)

111 South Union/111 South 9th Street is a one and one-half story, brick clad residence. The floor plan is "T" shaped with a gable roof intersecting a gambrel roof of wood shingles. Two shallow hipped roofs cover the porch on the west elevation. These porches are supported by turned posts with small curved "knee" braces for brackets. Engaged 1/2 round columns support the porch and simple railing at the building face. The brick is laid in common bond with 6th course headers. Openings are formed by segmental brick arches. The foundation projects from the exterior wall and is coated with a cement wash. The gable ends are clad with clapboard siding with a "sunburst" pattern at the gable end and with a vertical pattern at the gambrel ends. The windows are 1/1 double-hung units with storm windows affixed to the exterior. A small 1/2 round window serves as a vent within the gable end. A glazed sun porch is located in the southeast corner of the building. This unique building of the pioneer Yakima era has been well maintained and may be essentially unaltered. The only obvious additions have been a deck and hot-tub on the east elevation. The picket fence is also new.

The interior features oak floors, target moldings, and wood trim. Total contributing properties: 1 (house); noncontributing properties: 1 (garage)

Major Bibliographic References: (Include books, periodicals, manuscripts, newspapers,

legal documents, maps, photos, oral sources, etc.)

Newbill, Jim and Herb Blisard, eds. Yakima: <u>A Centennial Perspective, 1885-1985</u>. Franklin Press, Yakima. 1984, p. 72. Brown, Patricia. Manuscript n.d. ca. 1984. (Yakima Valley Museum, Archives).
Polk, R.L. & Co. Yakima City Directory. 1903-1931.
1900 Federal Census, Yakima County, Washington. Abs. Yakima Genealogy Society, Yakima, 1980. p. 65.
Yakima Herald. October 5, 1904.
Lesh Land Company, <u>Index to Lots, B</u>, B-2-1; Book 26, 468-505. (Land records at Schreiner Title Co., 30 N. 2nd St., Yakima).

Yakima County Assessor's records.