



7703/2:29
31303

PROPERTY OF THE NATIONAL REGISTER

NOV 23 1977

#1 87

MAY 4 1977

Cornelius O'Connor House

Dakota County, Nebraska

Photo by D. Murphy, Nebraska State

Historical Society, March 1977

NSHS 7703.2:29

Overall view of the house and site
showing the north facade; looking
south toward the bluffs.



7703/2:23

2/3B

PROPERTY OF THE NATIONAL REGISTER

NOV 23 1977

#2 *07* MAY 4 1977
Cornelius O'Connor House
Dakota County, Nebraska
Photo by D. Murphy, Nebraska State
Historical Society, March 1977
NSHS 7703/2:23
General view of the exterior showing
north and west facades;
looking southeast

2



7703/2:26
412

PROPERTY OF THE NATIONAL REGISTER

NOV 23 1977

#3 07 MAY 4 1977
Cornelius O'Connor House
Dakota County, Nebraska
Photo by D. Murphy, Nebraska State
Historical Society, March 1977
NSHS 7703/2:26
General view showing north and east
facades; looking southwest



7703/2:27
313B

PROPERTY OF THE NATIONAL REGISTER

NOV 23 1977

#4 07 MAY 4 1977
Cornelius O'Connor House
Dakota County, Nebraska
Photo by D. Murphy, Nebraska State
Historical Society, March 1977
NSHS 7703/2:27
General view showing the south and
east facades; looking north-
northwest



312B

7703/3:32

PROPERTY OF THE NATIONAL REGISTER

NOV 23 1977

#5 *07* **MAY 4 1977**
Cornelius O'Connor House
Dakota County, Nebraska
Photo by D. Murphy, Nebraska State
Historical Society, March 1977
NSHS 7703/3:32
Interior view of the main central
stair hall just inside the front
(north) doors; looking south



7703/3:29
210

PROPERTY OF THE NATIONAL REGISTER

#6 97

Cornelius O'Connor House

Dakota County, Nebraska

Photo by D. Murphy, Nebraska State

Historical Society, March 1977


NSHS 7703/3:29

Interior view of the dining hall
showing the built-in sideboard and
pass-through from the pantry:

looking south

MAY 4 1977

NOV 23 1977



7703/3:36
4578

PROPERTY OF THE NATIONAL REGISTER

#7 87

Cornelius O'Connor House
Dakota County, Nebraska
Photo by D. Murphy, Nebraska State
Historical Society, March 1977
NSHS 7703/3:36
Interior detail view of a door
panel (upstairs servant's room

door) showing the marbled
panels and outer edge of frame;
looking south

MAY 4 1977

NOV 23 1977