HIS	TORIC RESOURCES INVENTORY	FOR OFFICE USE ONLY					
	LDING AND STRUCTURES	Town No.: Site No.:					
	STATE OF CONNECTICUT						
	CONNECTICUT HISTORICAL COMMISSION 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106						
((203) 566-3005	QUAD: Hartford North DISTRICT					
		S NR Actual Potential					
	1. BUILDING NAME (Common) (Historic) James Butler						
	2. TOWN/CITY VILLAGE						
NO	West Hartford	Hartford					
ΑTI	3. STREET AND NUMBER (and/or location)						
FIC	239 North Main Street approx8 acres Vol. 395, p. 488.						
DENTIFICATION	Joyce Gray Witik	Public X Private					
DE	5. USE (Present) (Historic) residence farmhouse						
	TO PUBLIC: Yes No Yes No						
	7. STYLE OF BUILDING	DATE OF CONSTRUCTION					
	center hall colonial 8. MATERIAL(S) (indicate use or location when appropriate)	c. 1800					
	Clapboard Asbestos Siding Brick ² Other (Specify)					
	chimneys						
	Wood Shingle Asphalt Siding Fieldstone						
	Board & Batten Stucco Cobblestone						
	Aluminum Siding Concrete Type: X Cut stane Type: brownstone ashlar						
i,	9. STRUCTURAL SYSTEM X Wood frame X Post and beam balloon						
	Load bearing masonry Structural Iron or steel						
	Other (Specify)						
	10. ROOF (Type) X Gable Flat Mansard Monitor sawtoot						
	X Gable Flat Mansard Monitor Sawtootl	1					
z	Gambrel Shed Hip Round (Specify)					
DESCRIPTION	(Material)						
CRI	Wood Shingle Asphalt Tin Slate						
DE	X Asphalt shingle Built up Tile Other (Specify)						
ł	11. NUMBER OF STORIES APPROXIMATE DIMENSIONS						
	2, attic 35 x 32 12. CONDITION (Structural) (Exterior)						
	Excellent Good X Fair Deteriorated Excellent Goo	d 🔀 Fair 🗌 Doterioratod					
ł	13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN						
	Image: Construction of the second state of the se						
	Barn Shed X Garage Other landscape features or buildings	s (Specify)					
	Carriage Garden						
ł	15. SURROUNDING ENVIRONMENT						
	Open land Down Residential Scattered buildings visible from site						
	Commercial Indus- Rural High building density						
	16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS						
	Set farther back from the road than its 20th century single stands on a busy main thoroughfare. A few houses to the no						
	colonial, the Butler Hatheway House.	(OVER)					

i

This is a typical Federal Connecticut Valley farmhouse, with a five bay front, ridge to street, two internal brick chimneys and a central hall plan. The 12/12 sash in all the front windows appears to be original. A one story ell at the south rear may or may not be original. There is no ornament or detailing at either doorway or windows.

	18. ARCHITECT	BUILDER	······				
	IV/ /	Gideon or James Butler					
SIGNIFICANCE	between 1789 and 1816. This house re were descended from Joseph Butler. an	Butler about 1816, or by his father Gideon Butler eplaced an earlier dwelling on the site. The Butle a original settler and one of the petitioners for t a 1710. The Butler family occupied the house until	he				
SOURCES	Hartford Land Records, 16:151; 19:477; 31:523 Hartford Probate Records #2914, Thomas Hosmer; James Butler, 1846 1854 map, 1869 map, 1896, 1909 and 1923 Atlases Hall, <u>West Hartford</u> , p. 9, 10						
	PHOTOGRAPHER	DATE	-				
РНОТО	Katherine Cruse	April 1982					
4	east	CHC II-35,36	X				
B≺	NAME	DATE	1				
ED B		Nov. 1982					
OMPIL	ADDRESS						
Ŭ	227 North Main Street, West Hartford						
P n F	mantel with pilasters and dentils; appea	r deteriorated as implied below. Interior includes ars c.1790 in proportion (Georgian) rather than y case. Transomed entry very traditional. Sash HRC 12/85 (

None known	Highways	Vandali sm	Developers	Other
Renewal	Private	XX Deterioration	Zoning	Explanation

DESCRIPTION (Continued)