

Poplar Hill, Cynthiana, Kentucky Dixon Barr, Eastern Kentucky University, Richmond, Kentucky October 1975 Photo 1.

Photo taken from the northwest showing the facade of the house.

JUN 2 8 1976

NOV 7 1975



Poplar Hill, Cynthiana, Kentucky Dixon Barr, Eastern Kentucky University, Richmond, Kentucky October 1975 Harrison Co.

Photo 2.

Jun 2 8 1976

Photo taken from the north.

Notice the trefoil design on the front porch and the herringbone pattern in the old brick walk.



Poplar Hill, Cynthiana, Kentucky Photographer: Unknown circa 1890 Harrison Co.
Photo 3.

Photo taken from the north.

Notice the balustrade above the porch which has been removed.

1976


JUN 2 8 1976



Poplar Hill, Cynthiana, Kentucky Dixon Barr, Eastern Kentucky University, Richmond, Kentucky October 1975 Harrison Co. Photo 4.

Photo taken from the southwest showing the one-story wing on the rear of the house.

JUN ~ 8 1976



Poplar Hill, Cynthiana, Kentucky Dixon Barr, Eastern Kentucky University, Richmond, Kentucky October 1975 Photo 5.

Interior photo of the arch between the double parlors.

JUN 2 8 1976




Poplar Hill, Cynthiana, Kentucky Dixon Barr, Eastern Kentucky University, Richmond, Kentucky October 1975 Photo 6.

Interior photo of the plaster cornice which extends around the parlors. (The top and bottom rows of classical motifs are wallpaper borders.)



Poplar Hill, Cynthiana, Kentucky Dixon Barr, Eastern Kentucky University, Richmond, Kentucky October 1975 Photo 7.

Interior photo of the plaster medallion of grape clusters in the ceiling in one of the parlors. Note hook for unwired chandelier.



Poplar Hill, Cynthiana, Kentucky Dixon Barr, Eastern Kentucky University, Richmond, Kentucky October 1975 Harrison Co. Photo 8.

Interior photo of a plaster medallion in the double parlor.

JUN 2 8 1976