



5 EP 3981 FI Paso County

#1

JG Evans Barn

South Side

11/29/2003



5EP3981 El Paso County

#2

JG Evans Barn

west & south sides

11/29/2003



5EP3981 El Paso County

#3

JG Evans Barn

East & north sides

11/29/2003



5EP3981 El Paso County

#4

JG EVANS Barn

North side (rear)

11/29/2003





5EP3981 El Paso County

#5

JG Evans Exum

South Side

11/29/2003



SEP 3 1981 El Paso County

# 6

JG Evans Barn

Interior view - central section

11/29/2003



SEP 3 1981

El Paso County

#7

JG Evans Barn

Interior view of central section from  
east shed extension.

11/29/2003



SEP 3 1981 El Paso County

#8

JG Evans Barn

Interior view - east shed extension

11/29/2003





5EP 3981 El Paso County #9

JG Evans Barn

Interior view - feed bin/manger

11/29/2003



5EP3981 El Paso County

#10

JG Evaris Barn

Interior view - tin lined granary

11/29/2003



SEP 3 1981

El Paso County

#11

JG EVANS Barn

Interior view roof system

11/29/2003



SEP 3981 El Paso County #12

JG Evans Barun

Interior view of roof system & hayloft

11/29/2003





SEP 3981 El Paso County #13

JG Evans Barn

Interior view - gate, east extension

11/29/2003



5EP3981 El Paso County #14

JG Evans Barn

Interior view - feed bin/manger

11/29/2003