



Hugo Frisco Railroad Depot

Hugo, Oklahoma

*Cheetaw Co.*

Photographer: David Baird

8 December 1978

JUN

6 1980

Negative at OSU, Oklahoma

Preservation Survey, Stillwater, OK  
Facing southeast

#1

Overview

*1/3*

**AUG 1 1979**



HUGO

Hugo Frisco Railroad Depot

Hugo, Oklahoma

*Choctaw Co.*

Photographer: David Baird

8 December 1978

JUN

6 1980

Negative at OSU, Oklahoma.

Preservation Survey, Stillwater, OK

Facing east

#2

Front

AUG 1 1979

*2/3*



Hugo Frisco Railroad Depot

Hugo, Oklahoma

*Choctaw Co.*

Photographer: David Baird

8 December 1978

Negative at OSU, Oklahoma

Preservation Survey, Stillwater, OK

Facing north

#3/3

Old Negro waiting room

AUG 1

1979

6  
1980