



REYNOLDS (JOSEPH) HOUSE
956 Hope Street
Bristol, Rhode Island 02809

Photographer: John Shotwell
Date: 1982
Negative: John Shotwell

View: Joseph Reynolds House, west facade, showing
pedimented fanlight doorway, c. 1800.

Photo #1



Joseph Reynolds House

Bristol, RI

Photo By: Clifford M. Renshaw, III
1971

Entrance (west) front

Photo #1a



REYNOLDS (JOSEPH) HOUSE
956 Hope Street
Bristol, Rhode Island 02809

Photographer: John Shotwell
Date: 1982
Negative: John Shotwell

View: Joseph Reynolds house, west front detail
showing cove cornice and old window.

Photo #2



REYNOLDS (JOSEPH) HOUSE
956 Hope Street
Bristol, Rhode Island 02809

Photographer: John Shotwell
Date: 1982
Negative: John Shotwell

View: Reynolds house, exterior, south view,
showing ell.

Photo #3



Joseph Reynolds House

Bristol, RI

Exterior from the Southwest

Photo By: Clifford M. Renshaw, III

1971

Photo # 3a



REYNOLDS (JOSEPH) HOUSE
956 Hope Street
Bristol, Rhode Island 02809

Photographer: John Shotwell
Date: 1982
Negative: John Shotwell

View: Joseph Reynolds house, northwest parlor,
showing paneling as reconstructed from
measured drawings made by Frank Chouteau
Brown in 1935 with ground painting, waiting
application of marbledizing.

Photo #4



REYNOLDS (JOSEPH) HOUSE
956 Hope Street
Bristol, Rhode Island 02809

Photographer: John Shotwell
Date: 1982
Negative: John Shotwell

View: Stairway, first floor hall, showing two-
panel door into rear room. Painted riser
line showing above riser board.

Photo #5



REYNOLDS (JOSEPH) HOUSE
956 Hope Street
Bristol, Rhode Island 02809

Photographer: Mrs. Richard Anderson
Date: 1982
Negative: Mrs. Richard Anderson

View: Stairway, second to third story, showing
old painting defining riser behind the
later stair casing.

Photo #6



REYNOLDS (JOSEPH) HOUSE
956 Hope Street
Bristol, Rhode Island 02809

Photographer: John Shotwell
Date: 1982
Negative: John Shotwell

View: Fully finished stairway from third floor
into garret, showing rafters of roof at
banister height.

Photo #7



REYNOLDS (JOSEPH) HOUSE
956 Hope Street
Bristol, Rhode Island 02809

Photographer: John Shotwell
Date: 1982
Negative: John Shotwell

View: Southwest (dining) room. Showing mantel-
piece; hall into southeast part of the house,
doorway at right leading into south hallway.

Photo #8



REYNOLDS (JOSEPH) HOUSE
956 Hope Street
Bristol, Rhode Island 02809

Photographer: Mrs. Richard Anderson
Date: 1982
Negative: Mrs. Richard Anderson

View: Southwest (dining) room. Showing ceiling
framing with cased beams and cornice detail.

Photo #9



REYNOLDS (JOSEPH) HOUSE
956 Hope Street
Bristol, Rhode Island 02809

Photographer: Mrs. Richard Anderson
Date: 1982
Negative: Mrs. Richard Anderson

View: Detail, southwest (dining) room, showing
cased summer beam, and molded cornice
detail, to be studied for old paint finish.

Photo #10



REYNOLDS (JOSEPH) HOUSE
956 Hope Street
Bristol, Rhode Island 02809

Photographer: John Shotwell
Date: 1982
Negative: John Shotwell

View: Southeast room (old kitchen) showing mantel,
old batten door at left, framing for
partition, now removed, entrance into hall
to southeast room.

Photo #11



REYNOLDS (JOSEPH) HOUSE
956 Hope Street
Bristol, Rhode Island 02809

Photographer: John Shotwell
Date: 1982
Negative: John Shotwell

View: Northwest chamber (Lafayette Room) showing
mantelpiece with bolection paneling,
restored marbleizing. Two panel doors,
still painted and to be restored.

photo #12



Ansel Adams and the West



REYNOLDS (JOSEPH) HOUSE
956 Hope Street
Bristol, Rhode Island 02809

Photographer: Mrs. Richard Anderson
Date: 1982
Negative: Mrs. Richard Anderson

View: Southwest chamber, showing one story mantel-
piece, two-panel closet door, four-panel
door into upstairs south hall, cased summer
beams.

Photo #13