

Dist. Photos

Cape Ann Lt. Sta
South Tower



Figure 4
Cape Ann Light Station
Rockport, Massachusetts
South Tower with Brick Keepers Dwelling, ca. 1890s

20. South tower with brick keepers dwelling and covered walkway. Note the front door on the north side and the original fog signal on the left. This door was moved to the west- side some time before 1914 when an “ell” addition was added as is shown currently in photo # 10.

National Archives 026-LG-5-74. Estimated to be late 1890's.



Figure 5
Cape Ann Light Station
Rockport, Massachusetts
North Tower with Wooden Keepers Dwelling, ca. 1900



Figure 6
Cape Ann Light Station
Rockport, Massachusetts
North and South Towers, July 1914




Figure 7
Cape Ann Light Station
Rockport, Massachusetts
North and South Towers, November 1974

6. Left to right Looking Northeast Nov.74

**Principal keepers dwelling, Assitant keepers dwelling, Oil House, North Tower,
Note: railway and trestle as well as walkways to Whistle House below Oil House,
South Tower, and Whistle House on the far right.**



Figure 8
Cape Ann Light Station
Rockport, Massachusetts
North Tower, 1999

Figure 9

Cape Ann Light Station

Rockport, Massachusetts

Assistant (foreground) and Principal Keepers Dwellings, 1999






Figure 10
Cape Ann Light Station
Rockport, Massachusetts
Principal Keeper's Dwelling, 1999

6 2 '99



Figure 11
Cape Ann Light Station
Rockport, Massachusetts
Assistant Keeper's Dwelling, 1999



Figure 12
Cape Ann Light Station
Rockport, Massachusetts
Whistle House, 1999

Figure 13
Cape Ann Light Station
Rockport, Massachusetts
Utility Building, 1999





Figure 14
Cape Ann Light Station
Rockport, Massachusetts
Boat House and Ramp, 1999