


In this c. 1950 aerial photograph, the once isolated house, (as seen inside the black circle), is already threatened by encroachme





1936: Original Condition:

Hand applied integral color stucco is clearly visible. Original light fixtures, wood headers and 'vigas' are shown

Photo#2 Rancho Amorp Maricopa County Arizona Photographer: WZ Smith Loc. of Negative: BM Dann /owner) Loc. of Negative: BM Dann /owner) View: From carden, looking NW towards Main House Date: c. 1936



#### 1956: Maintained Condition:

Stucco has been painted, the outdoor fireplace has been modified into a cooking grill, and an evaporative cooler added.

Photo #3 Rancho Arroyo Maricopa County Arizona Photographer: WZ Snith Loc. of Negotive : BM Dann (owner) View: from garden, looking west toward Date: C. 1956 main house



#### Photo I Main House

#### Rancho Arroyo Maricopa County, AZ





#### Rancho Arroyo maricoza County, AZ













## Photo 5 Rancho Arroyo Maricopa County, Main A7 Main House







### Main House


Maricopa County, AZ






Rancho Arroyo Maricopa County, AZ
















#### Photo 11 Main House

Rancho Arroyo Maricopa County,







#### Photo 13 Goest House

# Rancho Arroyo Maricopa County, AZ



### Photo 14 Ranche Guestheuse Marico

Rancho Arroyo Maricopa County,



#### Photo 15 k Guesthouse R

## Rancho Arroyo Maricopa County,




### Photo 16 Garage

# Rancho Arroyo Maricopa County,




Ranche Arroyo Maricopa County, AZ Photo 17 Garage







#### Photo 19 Garden







## Ranclo Arroyo Maricopa County, AZ



Photo 21 Rancho Arroyo Jordon Maricopa County, Gardon A7



#### Photo 22 Rancho Arroyo Maricopa County, barden AZ



### Photo 23 Garden

### Rancho Arroyo Maricopa Courty, AZ