



Swett Ranch

Daggett county

MAR 6 1979

SUBJECT: Section of corral.

PHOTOGRAPHER: Carol Zubrickas.

DATE TAKEN: June, 1978.

NEGATIVE FILED: Forest Service office at Dutch John, Utah.

VIEW DESCRIPTION: This is a section of the collection corral built in 1905 for Oscar Swett's cattle (before he homesteaded there). It has been repaired over the years, but many of the original logs remain.

DOE

JUL 10 1979



Swett Ranch

Daggett county

MAR 6 1979

SUBJECT: New blacksmith shop.

PHOTOGRAPHER: Walter Toome.

DATE TAKEN: 1968.

NEGATIVE FILED: Aspen Photo in Vernal, Utah

VIEW DESCRIPTION: This shop was built to replace the old one in the early 1940's. Oscar Swett did his own blacksmithing.

DOE

JUL 10 1979



Sweet Ranch

Sageitt County

SUBJECT: Granary-tack room.

MAR 6 1979

PHOTOGRAPHER: Carol Zubrickas.

DATE TAKEN: June, 1978.

NEGATIVE FILED: Forest Service office at Dutch John, Utah.

VIEW DESCRIPTION: It was built in 1935 and has a cut out square in the door for a cat to enter (for rodent control).

DOE

0 1979



Swett Ranch

Daggett County

MAR 6 1979

SUBJECT: Root cellar.

PHOTOGRAPHER: Phil Johnson.

DATE TAKEN: May, 1971.

NEGATIVE FILED: Forest Service office at Dutch John, Utah.

VIEW DESCRIPTION: The cellar is located just west of the two room house. It was built in 1935 and used to store potatoes and canned goods.

DOE



Sweet Ranch

Daggett County

MAR 6 1979

SUBJECT: Workshop-stable.

PHOTOGRAPHER: Phil Johnson.

DATE TAKEN: May, 1971.

NEGATIVE FILED: Forest Service office at Dutch John, Utah.

VIEW DESCRIPTION: The workshop (on the right) is a cut down version of the Greendale School originally built in 1919. The stable (on the left) was added in the late 1940's.

DOE

JUN 10 1979



DOE

MAR 6 1979

JUL 10 1979

Swett Ranch

Dayette County

SUBJECT: Three generations of homes on the Swett homestead.

PHOTOGRAPHER: Phil Johnson.

DATE TAKEN: May, 1971.

NEGATIVE FILED: Forest Service office at Dutch John, Utah.

VIEW DESCRIPTION: The cabin on the left is the one room homestead house that was erected on this site in 1912. (It had been moved from another site by horse-drawn wagon.) The middle building is a sawed log five room house that was built in 1929. On the right is a two room cabin that was built in 1920. All were constructed by Oscar Swett and his family.



Swett Ranch

Daggett County

MAR 6 1979

DOE
0 1979

SUBJECT: Milking barn.

PHOTOGRAPHER: Phil Johnson.

DATE TAKEN: May, 1971.

NEGATIVE FILED: Forest Service office at Dutch John, Utah.

VIEW DESCRIPTION: It was built in the early 1940's by Oscar Swett.



DOE
JUL 10 1979

Swett Ranch

Daggett County

MAR 6 1979

SUBJECT: Two room house.

PHOTOGRAPHER: Phil Johnson.

DATE TAKEN: May, 1971.

NEGATIVE FILED: Forest Service office at Dutch John, Utah.

VIEW DESCRIPTION: The Swett family two room log cabin. It was built by Oscar Swett in 1920. Then it was re-modeled in 1948 by Oscar and his son Louis.



Swett Ranch

Daguerre County

MAR 6 1979

SUBJECT: Old blacksmith shop.

PHOTOGRAPHER: Phil Johnson.

DATE TAKEN: May, 1971.

NEGATIVE FILED: Forest Service office at Dutch John, Utah.

VIEW DESCRIPTION: This shop was built in 1920 with lumber from Oscar Swett's own sawmill. It has a window in it from an old (about 1920) Hudson auto.

DOE



Swett Ranch

Daggett County

SUBJECT: View of a portion of the ranch grounds.

MAR 6 1979

PHOTOGRAPHER: Phil Johnson.

DATE TAKEN: May, 1971.

NEGATIVE FILED: Forest Service office at Dutch John, Utah,

VIEW DESCRIPTION: This is a portion of the Swett ranch grounds showing (from left to right rear) the old blacksmith shop, a woodshed, and the five room house. The left to right front of the view shows a Hoover wagon, state road graders, and a bobsled (all horse-drawn) from the early 1900's.

006
JUL 10 1979



Sweet Ranch

Biggert County

SUBJECT: Bull rake.

MAR 6 1979

PHOTOGRAPHER: Phil Johnson.

DATE TAKEN: May, 1971.

NEGATIVE FILED: Forest Service office at Dutch John, Utah.

VIEW DESCRIPTION: This rake was used in stacking hay. It was horse-powered and is located on the ranch grounds. It is from the early 1900's.

DOE

JUL 10 1979



Swett Ranch

Daggett County

MAR 6 1979

SUBJECT: Mower and rake.

PHOTOGRAPHER: Phil Johnson.

DATE TAKEN: May, 1971.

NEGATIVE FILED: Forest Service office at Dutch John, Utah.

VIEW DESCRIPTION: This shows a hay mower and hay rake. Both were horse-drawn and are located on the Swett ranch grounds. They date back to the early 1900's.

DOE

JUL 10 1979



Swett Ranch

Daguerre County

SUBJECT: Hay stacker.

PHOTOGRAPHER: Phil Johnson.

MAR 6 1979

DATE TAKEN: May, 1971.

NEGATIVE FILED: Forest Service office at Dutch John, Utah.

VIEW DESCRIPTION: This hay stacker is the Beaver slide type. It was used in conjunction with a bull rake and plunger pole to make a rounded hay stack. It is wooden with metal nuts and bolts to join the pieces. It is located on the Swett homestead and dates from the early 1900's.

DOE

JUL 10 1979



Swett Ranch

Daggett County

MAR 6 1979

SUBJECT: Two-way plow.

PHOTOGRAPHER: Phil Johnson.

DATE TAKEN: May, 1971.

NEGATIVE FILED: Forest Service office at Dutch John, Utah.

VIEW DESCRIPTION: This is a horse-drawn two-way plow located on the Swett homestead from the early 1900's.

DOE
JUL 10 1979



Swett Ranch

Daggett County

MAR 6 1979

SUBJECT: Binder.

PHOTOGRAPHER: Phil Johnson.

DATE TAKEN: May, 1971.

NEGATIVE FILED: Forest Service office at Dutch John, Utah.

VIEW DESCRIPTION: This binder was used for tying harvested grain.
It is located on the Swett ranch and is from the
early 1900's.

DOE
JUL 10 1979