




1. Rock Presbyterian Church
2. Fair Hill, Cecil Co., Md.
3. May 3, 1982
4. Photo: Elizabeth E. Booth
5. Neg. loc. Eliz. Booth  
192 Booth Rd.  
Elkton, Md. 21921
6. South facade and west side  
outcropping of Port Deposit  
gneiss. (camera facing  
Northeast)
7. 1/13

CE-73



1. Rock Presbyterian Church
2. Fair Hill, Cecil Co., Md.
3. Photo: Elizabeth Booth
4. Aug. 22, 1979
5. Neg. loc. Eliz. Booth  
192 Booth Rd  
Elkton, Md. 21921
6. South facade of Church  
and modern (1953) Church  
House. (camera facing  
North east)
7. 2/13

CE-73



31

1. Rock Presbyterian Church
2. Fair Hill, Cecil Co., Md.
3. Photo: Elizabeth Booth
4. Aug. 22, 1979
5. Neg. Loc. Eliz. Booth  
192 Booth Rd  
Elkton, Md. 21921
6. South facade, date stone  
and rose window.  
(camera facing North)
7. 3/13

CE-73



1. Rock Presbyterian Church
2. Fair Hill, Cecil Co., Md.
3. Photo: Elizabeth Booth
4. Aug, 22, 1979
5. Neg. loc. Eliz. Booth  
192 Booth Rd  
Elkton, Md. 21921
6. South front and East side. (camera facing northwest)

7. 4/13

CE-73






5.

- 1. Rock Presbyterian Church
- 2. Fair Hill, Cecil Co., Md.
- 3. Photo: Elizabeth Booth
- 4. Aug 22, 1979
- 5. Neg. loc. Eliz. Booth  
192 Booth Rd  
Elkton, Md. 21921
- 6. North end and east side  
North side of Session  
House. Camera facing  
south west

7. 5/13

CE-73



6.

1. Rock Presbyterian Church
2. Fair Hill, Cecil Co., Md.
3. Photo: Elizabeth Booth
4. Aug. 22, 1979
5. Neg. loc. Eliz. Booth  
192 Booth Rd  
Elkton, Md. 21924
6. West side elevation.  
(camera facing east)

7. 6/13


LE-73



- 7.
1. Rock Presbyterian Church
  2. Fair Hill, Cecil Co., Md.
  3. Photo: Elizabeth Booth
  4. Aug. 22, 1979
  5. neg. loc. Eliz. Booth  
192 Booth Rd.  
Elkton, Md. 21921
  6. Interior. Looking North  
to pulpit. Camera facing  
North from gallery.

7. Z/13

CE-73



8.

1. Rock Presbyterian Church

2. Fair Hill, Cecil Co., Md.

3. Photo: Elizabeth Booth

4. Aug. 22, 1979

5. neg. loc. Eliz. Booth

192 Booth Rd


Elkton, Md. 21921

6. Interior: looking south  
to gallery and rose window  
(camera facing south)

7. 8/13

CE-73






- 9.
1. Rock Presbyterian Church
  2. Fair Hill, Cecil Co., Md.
  3. Photo: Elizabeth Booth
  4. Aug. 22, 1979
  5. Neg. loc. Eliz. Booth  
192 Booth Rd  
Elkton, Md. 21921
  6. Interior: Facing south-west. Gallery, west windows  
stair and arched beams.

7. 9/13

CE-73



10.

1. Rock Presbyterian Church
2. Fair Hill, Cecil Co., Md.
3. Photo: Elizabeth Booth
4. Aug. 22, 1979
5. Neg. Loc. Eliz. Booth  
 192 Booth Rd  
 Elkton, Md. 21921
6. Interior: Stamped steel ceiling and beams. Facing North.

7, 10/13

CE-73

A

PRESBYTERIAN

CHURCH

A.D. 1761

11.

1. Rock Presbyterian Church
2. Fair Hill, Cecil Co., Md.
3. Photo: Elizabeth Booth
4. Aug. 22, 1979
5. Neg. loc. Elizabeth Booth  
192 Booth Rd.  
Elkton, Md. 21921
6. Date stone in peak  
of roof. South facade  
(camera looking north)
7. 11/13

CE-73



- 12.
1. Rock Church Session House
  2. Fair Hill, Cecil Co., Md.
  3. Photo: Elizabeth Booth
  4. Aug. 22, 1979
  5. Neg, loc. Eliz. Booth  
192 Booth Rd  
Elkton, Md. 21921
  6. South facade  
(camera facing north)

7. 12/13

CE-73





13.

1. Rock Church Session House
2. Fair Hill, Cecil Co., Md.
3. Photo: Elizabeth Booth
4. Aug. 22, 1979
5. Neg. loc. Eliz. Booth  
192 Booth Rd  
Elkton, Md. 21921
6. East side and North side  
(camera facing southwest)
7. 13/13

CE-73