

Photographer: James R. Lockhart

NegativesFiled: Georgia Department of Natural Resources Date: July, 1980 Description (1 of 9): Front and east side of building; photographer facing northwest.



Photographer: James R. Lockhart

Negatives Filed: Georgia Department of Natural Resources Date: July, 1980 Description (2 of 9): Front and west side of building; photographer facing northeast.



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: July, 1980 Description (3 of 9): Rear and east side of building; photographer facing southwest.



Photographer: James R. Lockhart
Negatives Filed: Georgia Department of
Natural Resources
Date: July, 1980
Description (4 of 9): front entrance;
photographer facing north.




Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: July, 1980 Description (5 of 9): First floor hallway; photographer facing north.



Photographer: James R. Lockhart
Negatives filed: Georgia Department of
Natural Resources
Date: July, 1980
Description (6 of 9): Second floor stairway
and landing; photographer facing west.



Photographer: James R. Lockhart
Negatives filed: Georgia Department of
Natural Resources
Date: July, 1980
Description (7 of 9): Second floor restroom:
photographer facing west.



Photographer: James R. Lockhart Negatives filed: Georgia Department of Natural Resources Date: July, 1980 Description (8 of 9): Second floor lounge at end of hall; photographer facing north.



Photographer: James R. Lockhart
Negatives filed: Georgia Department of
Natural Resources
Date: July, 1980
Description(9 of 9): Third floor hallway;
photographer facing east.