



TAIT-ERVIN HOUSE

COUNTRYSIDE

WILLOX COUNTY, ALABAMA

ED HOOKER, PHOTOGRAPHER

1/94

Countryside looking west from beginning
of drive

Photo 1



TAIT-ERVIN HOUSE

COUNTRYSIDE

WILLOX COUNTY, AL

Ed. Hooker, Photographer

1194

Front facade ; East side

photo 2



Tait- Ervin House
Countryside
Wilcox. Co, AL

Ed Hooker, Photographer

1/94

North Facade

Photo 3



Tait-Ervin House

Countryside

Wilcox County, AL

Ed Hooker, Photographer

1194

Rear view; West facade

Photo 4



Tait-Ervin House
Countryside
Wilcox Co, AL

Ed Hooker, Photographer
1/94

South facade

Photo 5



Tait-Ervin House
Countryside

Wilcox County, AL

Ed Hooker, Photographer

1/24

View of Northwest

photo 6



Tait - Ervin House
Countryside




Wilcox County, Az

Ed Hooker, Photographer

1/94

View of steps & main entrance

photo 7



Tait Ervin House

Countryside

Wilcox Co, AL

Ed Hooker, Photographer

1/94

detail of Victorian porch
ballustrade

photo 8



Tait- Ervin House

Countryside

Wilcox Co, AL

Ed Hooker, Photographer

1/94

View of Front porch showing
lower 6 jib windows and blinds

photo

9



Tait- Ervin House

Countryside

Wilcox Co, AL

Ed Hooker Photographer

1/94

View of porch looking South
Showing Carolina Porch

photo 10



Tait-Ervin House

Countryside

Wilcox Co, AL

Ed Hooker, Photographer

1/94

Interior view of hallway looking
toward rear doorway

photo 11



Tait- Ervin House

Countryside

Wilcox Co, AL

Ed Hooker, Photographer

1/94

Interior view of hallway
looking toward main entrance

photo 12



Tait - Ervin House

Country side

Wilcox Co, AL

Ed Hooker, Photographer

1/94

Interior view of hallway
looking toward South entrance

photo 13



Tait - Ervin House

Countryside

Wilcox Co, AL

Ed Hooker, Photographer

1/24

Interior view of hallway looking
toward North entrance and
Stair hall

photo 14



Tait- Ervin House
Countryside
Wilcox Co, AL
Ed Hooker, Photographer
1/94

Detail of plaster ceiling
medallion

photo 15



Tait-Eruin House

Countryside

Wilcox Co, AL

Ed Hooker, Photographer

1/24

detail of stencilling in front parlor/nursery

photo 16.



Tait- Erwin House

Countryside

Wilcox Co, AL

Ed Hooker, Photographer

1/94

detail of typical main hall
doorway w/shouldered
architrave and transom

photo 17



Tait-Ervin House

Country side

Wilcox Co, AL

Ed Hooker, Photographer

1/94

View of partition wall in
upstairs hall

photo 18