



Main road at headquarters, looking north, Mount
McKinley National Park Headquarters District
Denali National Park and Preserve, Alaska
Photographer: Kathleen Lidfors
Date: 13 May 1985
Negative: Alaska Regional Off., Anchorage, NPS
Photo No. 1

MAY 15 1987



HEADQUARTERS
BEAULIEU NATIONAL PARK
AND FOREST
OF THE PROVINCE

Main road at headquarters, looking south, Mount
McKinley National Park Headquarters District.
Denali National Park and Preserve, Alaska
Photographer: Gail Evans
Date: 20 July 1985
Negative: Alaska Regional Off., Anchorage, NPS
Photo No. 2



Dog Feed Cache and Sled Storage (No. 105),
north elevation, Mount McKinley National
Park Headquarters District

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 3

Denali National Park and Preserve, Alaska



Dog kennels south of Dog Feed Cache (No. 105),
Mount McKinley National Park Headquarters
District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 4



Main headquarters road (looking north) at inter-
section with loop residential road, Mount
McKinley National Park Headquarters District
Denali National Park and Preserve, Alaska
Photographer: Kathleen Lidfors
Date: 13 May 1985
Negative: Alaska Regional Off., Anchorage, NPS
Photo No. 5



Employee Residences (Nos. 13, left, and 12,
right) from small residential loop road,
Mount McKinley National Park Hdqtrs. District
Denali National Park and Preserve, Alaska
Photographer: Kathleen Lidfors
Date: 13 May 1985
Negative: Alaska Regional Off., Anchorage, NPS
Photo No. 6



Main road at headquarters, looking south, Mount
McKinley National Park Headquarters District
Denali National Park and Preserve, Alaska
Photographer: Gail Evans
Date: 21 July 1985
Negative: Alaska Regional Off., Anchorage, NPS
Photo No. 7



Office Building (No. 22) and residence buildings, looking south from park road, Mount McKinley National Park Headquarters District Denali National Park and Preserve, Alaska

Photographer unknown

Date: c. 1927

Negative at Denali National Park and Preserve

Photo No. 8



Power House (No. 110), left foreground, and
Warehouse (No. 101), center, looking south,
Mt. McKinley Nat. Pk. Headquarters District
Denali National Park and Preserve, Alaska

Photographer unknown

Date: c. 1932

Negative at Denali National Park and Preserve

Photo No. 9



Office Building (No. 22) in original location
facing park road, looking south, Mount
McKinley National Park Headquarters District
Denali National Park and Preserve, Alaska
Photographer unknown
Date: 1939
Negative at Denali National Park and Preserve
Photo No. /0

76



11

Main road into headquarters, looking south,
Mount McKinley National Park Headquarters
District

Denali National Park and Preserve, Alaska

Photographer unknown

Date: c. 1941

Negative at Denali National Park and Preserve

Photo No. //



Main headquarters road, looking north, Mount
McKinley National Park Headquarters District
Denali National Park and Preserve, Alaska
Photographer unknown
Date: 1942
Negative at Denali National Park and Preserve
Photo No. 12



Warehouse (No. 101), left, and Rangers' Dormitory (No. 21), looking north, Mount McKinley National Park Headquarters District
Denali National Park and Preserve, Alaska
Photographer unknown
Date: c. 1942
Negative at Denali National Park and Preserve
Photo No. 13



Garage and Repair Shop (No. 102), left, and
Warehouse (No. 101), center, looking north-
west, Mount McKinley Nat. Pk. Hqtrs. District
Denali National Park and Preserve, Alaska

Photographer unknown

Date: c. 1942

Negative at Denali National Park and Preserve

Photo No. *14*



Dog Feed Cache (No. 105), north and east elevations, Mount McKinley National Park Headquarters District

Denali National Park and Preserve, Alaska

Photographer unknown

Date: December 1939

Negative at Denali National Park and Preserve

Photo No. 15



Kennels at Dog Feed Cache (No. 105), corner
visible, Mount McKinley National Park
Headquarters District

Denali National Park and Preserve, Alaska

Photographer unknown

Date: 1940

Negative at Denali National Park and Preserve

Photo No. 16



Employee Residences (Nos. 12 & 13), looking
southwest, Mount McKinley National Park
Headquarters District
Denali National Park and Preserve, Alaska
Photographer unknown
Date: September 1938
Negative at Denali National Park and Preserve
Photo No. 17



Employee quarters, built mid-1930s, burned
1950, Mount McKinley National Park Headquar-
ters District

Denali National Park and Preserve, Alaska

Photographer unknown

Date: November 1940

Negative at Denali National Park and Preserve

Photo No. *18*



Employee Residence (No. 13), east and north
elevations, Mount McKinley National Park
Headquarters District

Denali National Park and Preserve, Alaska

Photographer: Gail Evans

Date: 21 July 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 12/13 -1



Employee Residence (No. 13), south elevation,
Mount McKinley National Park Headquarters
District

Denali National Park and Preserve, Alaska

Photographer: Gail Evans

Date: 21 July 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 12/13 - 2



Employee Residence (No. 13), portion of west
wall, Mount McKinley National Park Head-
quarters District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 12/13 - 3



Employee Residence (No. 12), enclosed porch
entry, Mount McKinley National Park Head-
quarters District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 1213 - 4



Rangers' Dormitory (No. 21), east and north
elevations, Mount McKinley National Park
Headquarters District

Denali National Park and Preserve, Alaska

Photographer: Gail Evans

Date: 21 July 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 21 - 1



Rangers' Dormitory (No. 21), battered log ends
and porch entry on east elevation, Mount
McKinley National Park Headquarters District
Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 21-2



Rangers' Dormitory (No. 21), west elevation with
porch modification, Mount McKinley National
Park Headquarters District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Negative: Alaska Regional Off., Anchorage, NPS

Date: 13 May 1985

Photo No. 21-3



Rangers' Dormitory (No. 21), north and west elevations, Mount McKinley National Park

Headquarters District


Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 21-4



Office Building (No. 22), south and east elevations,
Mount McKinley National Park Headquarters District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 22 - 1



Employee's Residence (No. 23), east elevation,
Mount McKinley National Park Headquarters
District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 23-1



Employee's Residence (No. 23), east and north
elevations, Mount McKinley National Park
Headquarters District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 23 - 2



Employee's Residence (No. 23), south porch,
Mount McKinley National Park Headquarters
District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 23 - 3



NO
PARKING
ANY
TIME
→

Superintendent's Garage (No. 50), noncontributing building, east and north elevations,
Mount McKinley National Park Headqtrs. Dist.

Denali National Park and Preserve, Alaska

Photographer: Gail Evans

Date: 22 July 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 50-1



Warehouse (No. 101), south and east elevations,
Mount McKinley National Park Headquarters
District

Denali National Park and Preserve, Alaska

Photographer: Gail Evans

Date: 21 July 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 101 - 1



Warehouse (No. 101), north and west elevations,
Mount McKinley National Park Headquarters
District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 101-3



Warehouse (No. 101), south and east elevations,
Mount McKinley National Park Headquarters
District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 101-2



Garage and Repair Shop (No. 102) with noncon-
tributing addition, north elevation, Mount
McKinley National Park Headquarters District
Denali National Park and Preserve, Alaska

Photographer: Gail Evans

Date: 22 July 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 102-1



Garage and Repair Shop (No. 102), east elevation,
Mount McKinley National Headquarters
District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 102-2



Garage and Repair Shop (No. 102), south and east
elevations, Mount McKinley National Park
Headquarters District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 102-3



THE CACHE

Garage (No. 103), south and east elevations,
Mount McKinley National Park Headquarters
District

Denali National Park and Preserve, Alaska

Photographer: Gail Evans

Date: 22 July 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 103-1



NO PARKING
FIRE LANE

NO PARKING
FIRE LANE

103

Garage (No. 103), south elevation, Mount McKin-
ley National Park Headquarters District
Denali National Park and Preserve, Alaska
Photographer: Kathleen Lidfors
Date: 13 May 1985
Negative: Alaska Regional Off., Anchorage, NPS
Photo No. 103-2



EMERGENCY VEHICLE
DO NOT BLOCK

Garage (No. 103), west elevation, Mount McKinley

National Park Headquarters District


Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 103-3



FISH CACHE

105

SLED ROOM

COOK HOUSE

Dog Feed Cache and Sled Storage (No. 105),
north elevation, Mount McKinley National
Park Headquarters District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 105-1



Dog Feed Cache and Sled Storage (No. 105),
second story of ^{South}~~north~~ elevation, Mount McKin-
ley National Park Headquarters District

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 105-2

Denali National Park and Preserve, Alaska



Barn (No. 106), west and south elevations, Mount
McKinley National Park Headquarters District
Denali National Park and Preserve, Alaska

Photographer: Gail Evans

Date: 22 July 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 106-1



Barn (No. 106), north and west elevations,
Mount McKinley National Park Headquarters
District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 106 - 2



Barn (No. 106), south elevation, Mount McKinley
National Park Headquarters District
Denali National Park and Preserve, Alaska
Photographer: Kathleen Lidfors
Date: 13 May 1985
Negative: Alaska Regional Off., Anchorage, NPS
Photo No. 106 - 3



Barn (No. 106), south and east elevations, Mount
McKinley National Park Headquarters District
Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 106-4



Barn (no. 106), south wall at joining of early
log addition and recent shed roof addition,
Mount McKinley National Pk, Hdqtrs. District
Denali National Park and Preserve, Alaska
Photographer: Kathleen Lidfors
Date: 13 May 1985
Negative: Alaska Regional Off., Anchorage, NPS
Photo No. 106-5



Boiler House (No. 107), south and east elevations, Mount McKinley National Park Headquarters District

Denali National Park and Preserve, Alaska

Photographer: Gail Evans

Date: 21 July 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 107-1



Boiler House (No. 107), south elevation, Mount
McKinley National Park Headquarters District
Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 107-2



THE UPPER POINT

110

Power House (No. 110), battered log ends at
northwest corner, Mount McKinley National
Park Headquarters District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 110-1



Power House (No. 110), south elevation, Mount
McKinley National Park Headquarters District
Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 110-2



Power House (No. 110), east elevation, Mount
McKinley National Park Headquarters District
Denali National Park and Preserve, Alaska
Photographer: Gail Evans
Date: 21 July 1985
Negative: Alaska Regional Off., Anchorage, NPS
Photo No. 110-3



Superintendent's Garage (No. 111), south elevation,
Mount McKinley National Park Headquarters District

Denali National Park and Preserve, Alaska

Photographer: Gail Evans

Date: 22 July 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 111 - 1



Superintendent's Garage (No. 111), stone work,
west and south walls, Mount McKinley National
Park Headquarters District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 111 - 2



Superintendent's Garage (No. 111), infill of
garage door opening on east elevation, Mount
McKinley National Park Headquarters District
Denali National Park and Preserve, Alaska

Photographer: Kathleen Lodfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 111-3



Comfort Station (No. 112), south and east elevations, Mount McKinley National Park Headquarters District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 112 - 1



Comfort Station (No. 112), south elevation,
Mount McKinley National Park Headquarters
District

Denali National Park and Preserve, Alaska

Photographer: Kathleen Lidfors

Date: 13 May 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 112-2



Comfort Station (No. 112), ^{late 1960s} addition on north
end of building ^(gone) Mount McKinley National Park
Headquarters District

Denali National Park and Preserve, Alaska

Photographer: Gail Evans

Date: 21 July 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 112-3



CCC Infirmary (No. 123), noncontributing building, west and south elevations, Mount McKinley National Park Headquarters District Denali National Park and Preserve, Alaska

Photographer: Gail Evans

Date: 21 July 1985

Negative: Alaska Regional Off., Anchorage, NPS

Photo No. 123 - 1