

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET

Section _____ Page _____

SUPPLEMENTARY LISTING RECORD

NRIS Reference Number: 07000714

Date Listed: 7/13/2007

Elkhorn Guard Station

Clallam

WA

Property Name

County

State

Olympic National Park MPS

Multiple Name

This property is listed in the National Register of Historic Places in accordance with the attached nomination documentation subject to the following exceptions, exclusions, or amendments, notwithstanding the National Park Service certification included in the nomination documentation.



Signature of the Keeper

7/13/2007

Date of Action

Amended Items in Nomination:

Function:

The historic and current functions should be amended to read: *Domestic: Camp (Guard Station); and Government: Government Office Building.* [This is consistent with previously documented Forest Service/National Park field station properties.]

Significance:

Criteria Consideration B should be checked.

[Criteria Consideration B (moved buildings) is usually not necessary for minor support buildings set within larger districts, but since the barn and shelter represent 2 of just 4 total buildings and the intact nature of the station is cited as a key element of the district's significance, it is appropriate to check and justify Criteria Consideration B for this property. The property meets the criteria consideration based on the architectural significance of the resources and the compatibility of the relocation with the historic setting and orientation of the resources.]

These clarifications were confirmed with the NPS FPO office.

DISTRIBUTION:

National Register property file

Nominating Authority (without nomination attachment)

United States Department of the Interior
National Park Service

714

National Register of Historic Places Registration Form

This form is for use in nominating or requesting determination for individual properties and districts. See instructions in *How to Complete the National Register of Historic Places Registration Form* (National Register Bulletin 16A). Complete each item by marking "x" in the appropriate box or by entering the information requested. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, architectural classification, materials, and area of significance, enter only categories and subcategories from the instructions. Place additional entries and narrative items on continuation sheets (NPS Form 10-900A). Use typewriter, word processor or computer to complete all items.

1. Name of Property

historic name Elkhorn Guard Station

other name/site number Elkhorn Ranger Station Historic District

2. Location

street & number Approximately 11.5 miles along Elwha River Trail from the Whiskey Bend Trailhead: Elwha Sub-district not for publication

city or town Olympic National Park Headquarters, Port Angeles vicinity

state Washington code WA county Clallam code 009 zip code 98362

3. State/Federal Agency Certification

As the designated authority under the National Historic Preservation Act, as amended, I hereby certify that this nomination request for determination of eligibility meets the documentation standards for registering properties in the National Register of Historic Places and meets the procedural and professional requirements set forth in 36 CFR Part 60. In my opinion, the property meets does not meet the National Register criteria. I recommend that this property be considered significant nationally statewide locally. (See continuation sheet for additional comments.)

4.25.07

Signature of certifying official>Title

Date

WASHINGTON STATE HISTORIC PRESERVATION OFFICE

State of Federal agency and bureau

In my opinion, the property meets does not meet the National Register criteria. (See continuation sheet for additional comments.)

6-8-07

Signature of certifying official>Title

Date

National Park Service

State of Federal agency and bureau

4. National Park Service Certification

I hereby certify that the property is:

- entered in the National Register.
 See continuation sheet.
- determined eligible for the National Register.
 See continuation Sheet.
- determined not eligible for the National Register.
- removed from the National Register.
- other, (explain: _____)

Signature of the Keeper

Date of Action

7/13/2007

5. Classification

Ownership of Property (Check as many boxes as apply)	Category of Property (Check only one box)	Number of Resources within Property (Do not include previously listed resources in the count.)	
<input type="checkbox"/> private	<input type="checkbox"/> building(s)	Contributing	Noncontributing
<input type="checkbox"/> public-local	<input checked="" type="checkbox"/> district	1	buildings
<input type="checkbox"/> public-State	<input type="checkbox"/> site		sites
<input checked="" type="checkbox"/> public-Federal	<input type="checkbox"/> structure	3	structures
	<input type="checkbox"/> object		objects
		4	Total

Name of related multiple property listing
(Enter N/A if property is not part of a multiple property listing.)

**Number of contributing resources previously listed
in the National Register**

Historic Resources of Olympic National Park

6. Function or Use

Historic Functions
(Enter categories from instructions)

Domestic: Camp (Guard Station)

Government: Fire Station

Current Functions
(Enter categories from instructions)

Domestic: Camp (Visitor Contact Station)

7. Description

Architectural Classification
(Enter categories from instructions)

OTHER: Rustic

Materials
(Enter categories from instructions)

foundation	<u>Wood and Stone</u>
walls	<u>Wood Log</u>
roof	<u>Wood Shake</u>
other	<u>Wood</u>

Narrative Description

(Describe the historic and current condition of the property on one or more continuation sheets.)

Summary: The Elkhorn Guard Station Historic District, also known as the Elkhorn Ranger Station, is comprised of four Rustic Style buildings sited in a small clearing within a dense forest, about 11.5 miles from the trailhead at Whiskey Bend, in the Elwha District of Olympic National Park. The buildings are rectangular or square, of log and shake construction, with shake-covered roofs. The buildings are in good condition and continue to function much as they did historically. All four buildings appear much the same as they did after their construction between 1930 and 1934 by the United States Forest Service. The complex is a fine example of two property types identified in the Multiple Property Documentation form for the Historic Resources of Olympic National Park: Government (Forest Service) and Architecture (Log, Pole, and Shake). The district has integrity of location, setting, design, materials, workmanship, feeling, and association, and meets the registration requirements set forth in the Multiple Property Documentation form.

8. Statement of Significance

Applicable National Register Criteria

(Mark "x" in one or more boxes for the criteria qualifying the property for National Register listing.)

- A** Property is associated with events that have made a significant contribution to the broad patterns of our history.
- B** Property is associated with the lives of persons significant in our past.
- C** Property embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic values, or represents a significant and distinguishable entity whose components lack individual distinction.
- D** Property has yielded, or is likely to yield, information important in prehistory or history.

Areas of Significance

(Enter categories from instructions)

Criterion A: Politics/Government

Criterion C: Architecture

Period of Significance

Criterion A: 1930 - 1934

Criterion C: 1930 - 1934

Criteria Considerations

(Mark "x" in all the boxes that apply.)

Property is:

- A** owned by a religious institution or used for religious purposes.
- B** removed from its original location.
- C** a birthplace or grave
- D** a cemetery.
- E** a reconstructed building, object, or structure.
- F** a commemorative property.
- G** less than 50 years of age or achieved significance within the past 50 years.

Significant Dates

Significant Person

(Complete if Criterion B is marked above.)

Cultural Affiliation

Architect/Builder

United States Forest Service
Civilian Conservation Corps

Narrative Statement of Significance

(Explain the significance of the property on one or more continuation sheets.)

9. Major Bibliographical References

Bibliography

(Cite the books, articles, and other sources used in preparing this form on one or more continuation sheets.)

Previous documentation on file (NPS):

- preliminary determination of individual listing (36 CFR 67)
- previously listed in the National Register
- previously determined eligible by the National Register
- designated a National Historic Landmark
- recorded by Historic American Buildings Survey
#
- recorded by Historic American Engineering Record
#

Primary location of additional data:

- State Historic Preservation Office
- Other State Agency
- Federal agency
- Local government
- University
- Other

Name of Repository:

10. Geographical Data

Acreage of Property: Approximately 4 acres

UTM References

(Place additional UTM references on a continuation sheet.)

1 10 zone	464950 easting	5302190 northing	3 10 zone	465080 easting	5302040 northing
2 10	465080	5302160	4 10	464850	5302000

— See continuation sheet

Verbal Boundary Description

The boundary is formed by an irregular polygon which encompasses the one building, three structures and the open meadow that reaches the river's edge and is visible from the residence.

Boundary Justification

The boundary includes the guard station residence, woodshed, shelter and barn, and the immediate surrounding clearing and forest backdrop to convey a sense of the historic setting.

11. Form Prepared By

name/title Gail E.H. Evans, Historian / Stephanie Toothman, Regional Historian(1986), Gretchen Luxenberg, Historian (1998), and Jacilee Wray, Anthropologist (2005).

organization National Park Service, Columbia Cascade Support Office date 1986/1998

street & number 909 1st Avenue telephone (206) 220-4138

city or town Seattle State Washington zip code 98104-1060

Additional Documentation

Submit the following items with the completed form:

Continuation Sheets

Maps

A 7.5 minute USGS map indicating the property's location.

A sketch map for historic districts and properties having large acreage or numerous resources.

Photographs

Representative black and white photographs of the property.

Additional Items

(Check with the SHPO or FPO for any additional items.)

Property Owner

(Complete this item at the request of SHPO or FPO.)

name	telephone
street & number	
city or town	state
	zip code

Paperwork Reduction Act Statement: This information is being collected for applications to the National Register of Historic Places to nominate properties for listing or determine eligibility for listing, to list properties, and to amend existing listings. Response to this request is required to obtain a benefit in accordance with the National Historic Preservation Act, as amended (16 U.S.C. 470 *et seq.*).

Estimated Burden Statement: Public reporting burden for this form is estimated to average 18.1 hours per response including time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding this burden estimate or any aspect of this form to the Chief, Administrative Services Division, National Park Service, P.O. Box 37127, Washington, DC 20013-7127; and the Office of Management and Budget, Paperwork Reductions Projects (1024-0018), Washington, DC 20503.

United States Department of the Interior
National Park Service

National Register of Historic Places
Continuation Sheet

Section number 7

Elkhorn Guard Station: Clallam County, WA

Page 1

Narrative Description: The Elkhorn Guard Station Historic District, also referred to as the Elkhorn Ranger Station, was constructed by the United States Forest Service (USFS) between 1930 and 1934 as part of that government agency's desire to have patrol stations in highly traveled areas of the national forest. It is located about 11.5 miles from the trailhead at Whiskey Bend, along the Elwha River in Olympic National Park. The complex is sited on a small, grassy knoll at the edge of an open meadow, against a backdrop of dense hemlock forest, about 100' from the Elwha River.

The style of architecture exhibited in this historic district indicates USFS construction methods and techniques. Beginning in 1905 the Forest Service gained jurisdiction of nearly 1.5 million acres of prime timber land on the peninsula through the establishment of the Olympic Forest Reserve. During the next thirty years, a network of administrative structures evolved facilitating the forest rangers and guards (seasonal assistance) patrol of this immense territory. Ranger stations were usually built at more accessible frontcountry sites, while guard stations were typically constructed at remote backcountry sites reached only by trail. As the ranks of forest personnel swelled and trails were built into the rugged interior of the forest, more stations were built. These complexes usually consisted of living/sleeping quarters, a fire cache, a tool/wood shed, a shelter, and sometimes a horse barn and corral.

This complex is one of the numerous administrative facilities constructed by the Forest Service on the Olympic Peninsula. The Elkhorn Guard Station complex was built mostly by labor provided by Depression-era work relief programs. The PWA and CCC assisted in the completion of these buildings. The major portion of the log residence was erected in the fall of 1933, just as the National Park Service was given jurisdiction of the Mount Olympus National Monument. PWA crews worked under the supervision of the Forest Service when the largest portion of construction took place. A new log structure replaced an older, smaller log cabin that served as the guard station. This older cabin was sited closer to where the present-day shelter now stands; it was subsequently burned at an unknown date. A barn with about 5 acres of open pasture and a shelter completed the guard station complex by late 1933. This complex was turned over to the National Park Service in 1938, when the NPS inherited all of the USFS designed and constructed buildings and structures after Olympic National Park was established in what was formerly Mount Olympus National Monument. The complex remains as one of only five Forest Service guard stations left within Olympic National Park, where there used to be dozens.

The guard station residence, built in 1933, is rectangular in shape, measuring approximately 12' x 16' (main body only) and set on a post and pier (rock) foundation. It is 1-story in height and 3 bays wide. The building is constructed of round, peeled logs with saddle-notched corners. The slightly overhanging gable roof has exposed log purlins and is sheathed in wood shingles. The gable roof extends about 4' beyond the structure on the rear elevation to create a porch supported by peeled log posts with exposed log purlins. A centered, shed-roofed overhang on the main facade creates a porch supported by peeled log posts set on wooden decking. The center front door is wood with a rustic, "Stick" style screen door. The windows are 6-over-6, and 3-over-3, double-hung sash with log surrounds. The only alterations appear to be the addition of a metal stovepipe.

United States Department of the Interior
National Park Service

National Register of Historic Places
Continuation Sheet

Section number 7

Elkhorn Guard Station: Clallam County, WA

Page 2

The guard station woodshed was constructed in 1934. It is a simple, 1-story, straightforward, functional building designed for a specific purpose. It is located 10' from the residence. It is rectangular in shape, measuring approximately 10' x 12' in size. Built of wood-frame wall construction and sheathed in wood shakes, it has a wood-shake gable roof that has extended eaves and exposed rafters. There are no windows. In 1997 extensive preservation maintenance was performed on the building. Preservation maintenance included extensive replacement in-kind of wood members due to powder post beetle damage. Concrete piers were added below the floor framing to lift the structure off the wet ground and the eaves were extended to minimize the splash from water runoff from the roof.

The Elkhorn Guard Station Barn was completed by CCC crews under the supervision of Forest Service personnel in the summer and fall of 1933. When completed, the barn housed four stalls, a manger, and a hay rack. Five acres of open pasture provided an area for pack animals to rest and graze. The three-sided barn is square, measuring 20' x 20', 1-story in height, and constructed of log pole wall construction with wood shake siding set on a wood sill foundation. The steeply pitched gable roof has wood shakes, and exposed rafters. There is plank flooring along the west wall and an earthen floor in the east portion of the interior. There are two wide, open bays on the east wall and no windows. There are two doors on the south wall sheathed in wooden shakes. The only alterations appear to be the removal of most of the east wall to create wider bays (possibly done in the 1970s) and the relocation of the south door (date unknown). This building, along with the shelter, was relocated from its original site as a preservation measure in 1996 because of the encroaching river course. They were relocated in an area deemed safe from the river course. The relationship between the structures was reestablished in the new location. The building relocation was accomplished following stipulations in a Memorandum of Agreement developed with the Washington SHPO. The relocation was considered the best method to preserve the structures threatened by the changing course of the river.

The Elkhorn Guard Station Shelter was built in the early 1930s as one of dozens of trail shelters erected by the Forest Service. It was one of six along the Elwha River and is the only remaining one dating from the 1930s that still stands today. The three-sided shelter is square, measuring 14' x 14', 1-story, and set on a stone foundation. It is of pole wall construction and sided in board and batten. The saltbox shaped roof is sheathed in cedar shake. It has exposed pole rafters, an interior wood floor, and bunk beds built into the sidewalls. The only alterations appear to be the replacement of the original wood shake siding with board and batten (possibly done in the 1950s), and the addition or replacement of the wood floor with an in-kind floor done in the 1950s. Although the original wood siding has been replaced with another type of wood siding, the building is compatible with the others in the complex and is a contributing element of the district because it adds to its cohesive appearance. The shelter was relocated in 1996 due to the changing course of the Elwha River. It was relocated away from the water but respected the spatial organization that existed historically within the complex. The building relocation was accomplished following stipulations in a Memorandum of Agreement developed with the Washington SHPO. The relocation was considered the best method to preserve the structure threatened by the changing course of the river.

The Elkhorn Guard Station Historic District continues to exhibit the qualities of its original design and method of construction as built by the Civilian Conservation Corps and the United States Forest Service, the latter, as part of the effort to establish a presence on the ground. The Forest Service built an extensive network of trails,

United States Department of the Interior
National Park Service

National Register of Historic Places

Continuation Sheet

Section number 7 and 8

Elkhorn Guard Station: Clallam County, WA

Page 3

shelters, and guard and ranger stations across national forest lands on the peninsula in order to protect valuable stands of timber. It is a representative example of the types of buildings and structures built in the backcountry by the USFS. Using local, natural materials in a straightforward, functional manner, the USFS designed and built dozens of these types of buildings over its tenure as land steward for the purpose of assisting forest rangers in their diverse range of duties. Although two of the buildings were moved, overall, this complex retains a high degree of integrity in its setting, design, materials, workmanship, feeling, and association, and exhibits the registration requirements identified in the Multiple Property Documentation form for the Historic Resources of Olympic National Park.

SEE ATTACHED INVENTORY CARDS PREPARED IN 1982 FOR PROPERTY.

Statement of Significance:

Summary: The Elkhorn Guard Station Historic District is significant for its association with politics and government (United States Forest Service) activities within what is today Olympic National Park (criterion A). The district also is an example of the distinctive type and method of construction, Log, Pole, and Shake construction, utilized by the United States Forest Service in its years of managing the national forest lands on the Olympic Peninsula prior to the establishment of the national park (criterion C). Built between 1930 and 1934, the four buildings comprising the historic district are representative of the types of buildings that the United States Forest Service constructed to accomplish one of its objectives on the Olympic Peninsula—protecting the valuable stands of timber the agency was charged with managing—by building an extensive network of ranger, guard and patrol cabins, shelters, and lookouts. The complex exhibits a high degree of craftsmanship and is indicative of two property types identified in the Multiple Property Documentation form for the Historic Resources of Olympic National Park: Government (Forest Service) and Architecture (Log, Pole, and Shake). The district has integrity of setting, design, workmanship, materials, feeling, and association, and meets the registration requirements set forth for these properties in the Multiple Property Documentation form.

Narrative: As road construction and recreational development invited a broader public to venture to the Olympic Peninsula, its earlier reputation as an untamed wilderness diminished. Accessibility provided by the loop highway encircling Mount Olympus National Monument was only one agent in the opening of the interior wilderness to recreational pursuits. Beginning in 1905 and continuing for 33 years, lands now included in the inland portion of the national park were under the administrative jurisdiction of the United States Forest Service. Although multiple resource management was, and is today, the underpinning of the USFS administrative policies, timber management received particular emphasis in the Olympics. Following the appointment of Rudo L. Fromme as Olympic Forest Supervisor in 1911, plans were initiated to develop a comprehensive trail system to facilitate management of timber and other resources, with the specific concern of forest fire prevention and suppression. This trail system would include shelters, houses, sheds, and phone lines to assist the forest rangers in their fire suppression work.

The Elkhorn Guard Station Historic District, with its residence, woodshed, barn, and shelter, was built between 1930 and 1934, and reflects the intense USFS development program. It is one of dozens of complexes that were built as part of this vast network of administrative facilities. This network of resources greatly assisted the forest

United States Department of the Interior
National Park Service

National Register of Historic Places
Continuation Sheet

Section number 8 and 9 Elkhorn Guard Station: Clallam County, WA Page 4


ranger in getting supplies into the backcountry and in conducting his work. By the 1930s, part of a ranger's job was to assist backcountry travelers, and these stations responded to the need of greeting and assisting hikers by serving as a contact station. To devise and construct this network of facilities was a tremendous effort in terms of human and fiscal resources.


Extensively used by Native Americans prior to the arrival of newcomers to the peninsula, the Elwha River is a natural hiking route into the interior of the Olympic Range. The Elwha River is widely known for its excellent trout fishing, and was singled out by the Forest Service as a prime target for recreational development. The Elkhorn Guard Station complex benefited from Depression-era CCC work crew who assisted in the completion of the buildings in this complex. The construction of this guard station represents an important period of growth and development of the Forest Service on the Olympic Peninsula in the 1930s. With the creation of Olympic National Park and the gradual introduction of air surveillance in fire management following World War II, construction of ranger and guard stations subsided. The NPS inherited a lot of Forest Service facilities in 1938, including the Elkhorn Guard Station complex. Many of the Forest Service facilities taken over by the NPS continue to be used as they were historically; many others were demolished over time by the NPS because of a different land management philosophy and administrative policies. This complex has remained intact, and continues to serve national park visitors today much as it did historically when the lands were managed by the Forest Service.

The historic district is a noteworthy example of Log, Pole, and Shake buildings popular during an era of unsurpassed recreational and administrative facility development by the Forest Service (criterion C), and is significant for its association with government activities and efforts to manage these federal lands for timber and recreationists (criterion A). The Elkhorn Guard Station Historic District exhibits a high degree of craftsmanship, and continues to reflect the values and philosophies of its builders in its architectural expressions and use. The need to relocate two of the buildings within the complex because of the threat from the encroaching river has not diminished their integrity. Great effort was made to reestablish the buildings in a manner that reflects their historic configuration, in the same setting, but a greater distance from the river to preserve them for the future.


The Elkhorn Guard Station Historic District is an example of two property types identified in the Multiple Property Documentation form for the Historic Resources of Olympic National Park: Government/Politics and Architecture. It is a cohesive ensemble that retains a high degree of integrity in its setting, design, materials, workmanship, feeling, and association, and meets the registration requirements set forth in the Multiple Property Documentation form.

Bibliography: Evans, Gail. Historic Resource Study. NPS. 1983; draft, national register nomination, 1986.





ELKHORN GUARD STATION HISTORIC DISTRICT



EKG

50 25 0 25 50 100 800



PNRO

INVENTORY

Westin Building, Room 1920

1. SITE I.D. NO.		2. NAME(S) OF STRUCTURE	185 ELKHORN GUARD STATION RESIDENCE (ELKHORN RANGER STATION RESIDENCE)	3. OWNER/ADMIN ADDRESS	Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362
4. SITE ADDRESS (STREET & NO.)	Elwha River Trail; approx. 11.5 miles from trailhead at Whiskey Bend	5. ORIGINAL USE	Seasonal Residence	6. PRESENT USE	Seasonal Residence
7. CLASSIFICATION		8. UTM ZONE	10	9. EASTING	4450505302075
10. DATE	1933-1934	11. NORTHING		12. REGION	PNR
13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXISTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.	<p>The Elkhorn Guard Station Residence was built by labor provided by Depression-era work relief programs--namely the CWA and the CCC. The major portion of this peeled log structure was erected in the fall of 1933, just as the National Park Service was given jurisdiction of the Mt. Olympus National Monument, in which the building stood. CWA work crews worked under the supervision of the Forest Service when the largest portion of construction took place. The new guard station residence replaced a smaller log cabin that served as a guard station, and that stood near the edge of the meadow close to the existing shelter. (This structure was subsequently burned.) A barn with approx. five acres of open pasture and a shelter, completed the guard station complex in late 1933. This structure is one of numerous administrative buildings constructed by the U.S. Forest Service on the Olympic Peninsula. Beginning in 1905 the Forest Service gained jurisdiction of nearly 1.5 million acres of prime timber land on the peninsula, then included in the Olympic Forest Reserve. During the next thirty three years, a network of administrative structures facilitating the forest rangers and guards (seasonal assistants) in patrolling this immense territory, evolved. Ranger stations, usually erected at more accessible front country sites, and guard stations, typically built at back country locations only reached by trail, played an important role in the Forest Service's efforts to pursue its multiple resource land use policy. Before 1911 only a few ranger and guard stations were built (including Storm King, Interrorem, and Louella). But as the ranks of forest personnel swelled, and trails were built into the rugged interior, more </p>				
14. CONDITION	<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> GOOD	<input type="checkbox"/> FAIR	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> RUINS
15. DANGER OF DEMOLITION? (SPECIFY THREAT)	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> UNKNOWN				

16. SIGNIFICANCE

stations were added. Often these ranger and guard stations consisted of living/sleeping quarters, a fire cache, a tool/wood shed, a shelter, and sometimes a horse barn and corral. With the arrival of the CCC on the peninsula in the 1930s, Forest Service administered lands witnessed a great boom in fire prevention and recreation development. The construction of Forest Service ranger and guard stations reached epoch proportions. By the end of the 1930s no fewer than twelve ranger stations and nearly thirty guard stations stood in existence on the Olympic Peninsula. Many of these 1930s Forest Service built administrative buildings embodied physical characteristics reflecting the Rustic Style, a style that advocated employing designs, materials, and sitings that were closely integrated with the surrounding landscape. The pine tree symbol, identified with both the Forest Service and the CCC, became widely used during the 1930s. With the creation of Olympic National Park in 1938 and the gradual introduction of air surveillance



Unsurveyed

19. LOCATED IN AN HISTORIC DISTRICT		<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> NAME _____
20. PUBLIC ACCESSIBILITY		<input type="checkbox"/> YES, LIMITED <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES, UNLIMITED <input type="checkbox"/> UNKNOWN	<input type="checkbox"/> EXISTING SURVEY <input type="checkbox"/> COUNTY <input checked="" type="checkbox"/> LOCAL <input type="checkbox"/> OTHER
21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS AND/OR OTHER		<input type="checkbox"/> NPS <input type="checkbox"/> NMNH <input type="checkbox"/> MASS <input type="checkbox"/> MATER-1 <input type="checkbox"/> MAER <input type="checkbox"/> NPS <input type="checkbox"/> STATE		

- Evans, Gail E. H. with T. Allan Comp. 1983. Historic Resource Study: Olympic National Park. Seattle: National Park Service, Pacific Northwest Region.

Righter, Elizabeth. 1978. Cultural Resource Overview of the Olympic National Forest, Washington, Vol. I and II. Washington, D.C.: Jack McCormick and Associates.

University of Washington, Seattle, Washington.

Letter from Preston P. Macy to O.A. Tomlinson. 1934 (20 August). Macy Papers (Box 1-1). Archives and Manuscripts Section.

Letter from Preston P. Macy to O.W. Carlson. 1936 (8 February). Macy Papers (Box 1-19). Archives and Manuscripts Section.

White, D. H. c. 1933. "Map of Olympic Peninsula, Washington." Tacoma, Washington: D. H. White. Photocopy. (Located in OLYM history files.)

PNR

INVENTORY

National Park Service
Pacific Northwest Region
Cultural Resources Division
Seattle, Washington 98121

1 SITE I.D. NO				2 NAME(S) OF STRUCTURE	185	3 CITY/VICINITY				4 OWNER/ADMIN ADDRESS			
ELKHORN GUARD STATION RESIDENCE (ELKHORN RANGER STATION RESIDENCE)			5 SITE ADDRESS (STREET & NO.)	6 ORIGINAL USE	7 CLASSIFICATION	8 UTM ZONE	9 EASTING	10 NORTHING	11 REGION	12 STATE	13 SCALE	14 OTHER	15 QUADRANGLE NAME
			8. PRESENT USE								1:24	1:25,000	
			9. OWNER/ADMIN ADDRESS	COUNTY	STATE								

3 DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXISTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.

In fire management following World War II, ranger and guard station construction subsided. More recently many existing structures have been demolished. In 1984 only four Forest Service ranger stations and eight guard stations are extant on the Olympic Peninsula. The Elkhorn Guard Station is one of five stations now standing in Olympic National Park.

16. SIGNIFICANCE

This building, as well as the barn, wood shed, and shelter, all standing at the Elkhorn Guard Station, are eligible for listing in the National Register of Historic Places as part of a total building ensemble. All four buildings were constructed between 1930 and 1934, at a time of exuberant construction and development of back country areas on the Olympic Peninsula by the U.S. Forest Service. Widely known since the 1890s, as a natural hiking route into the interior of the Olympic Range, and for its excellent trout fishing, the Elwha River was singled out by the Forest Service as a prime target for recreational development. In addition to the historical significance of this four structure building ensemble, the Elkhorn Guard Station Residence is an excellent example of Rustic Style architecture,

16 CONDITION	<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> GOOD	<input type="checkbox"/> FAIR	<input type="checkbox"/> POOR	17 DETERIORATION	<input type="checkbox"/> N/A	18 DANGER OF DEMOLITION?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> UNKNOWN
19 SIGNIFICANCE							19. DANGER OF DEMOLITION? (SPECIFY THREAT)			

which became a hallmark of 1930s Depression-era groups, such as the CWA and the CCC. Of the four buildings in this group, only the Elkhorn Shelter has undergone considerable loss of physical integrity through residing. As a total group, however, the Elkhorn building ensemble and its immediate surroundings have experienced minimal alteration since the 1930s. The Elkhorn Guard Station building group and surrounding grounds possess integrity of location, design, setting, materials, workmanship, feeling, and association. Only one other Forest Service back country guard station (North Fork Quinault Guard Station) on the Olympic Peninsula, dating from the 1930s, has retained its integrity as a building group.

16. LOCATED IN AN HISTORIC DISTRICT?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> NAME _____			
18. PUBLIC ACCESSIBILITY	<input checked="" type="checkbox"/> YES, LIMITED	<input type="checkbox"/> YES, UNLIMITED	<input type="checkbox"/> UNKNOWN			
20. EXISTING SURVEYS	<input checked="" type="checkbox"/> NR	<input type="checkbox"/> NHL	<input type="checkbox"/> HABS	<input type="checkbox"/> HAER	<input type="checkbox"/> NPS	<input type="checkbox"/> STATE
	<input type="checkbox"/> COUNTY	<input type="checkbox"/> LOCAL	<input type="checkbox"/> OTHER			

21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

22. INVENTORIED BY

AFFILIATION

DATE

PNIRO

INVENTORY

National Park Service
Pacific Northwest Region
Cultural Resources Division

1. SITE I.D. NO.					
2. NAME(S) OF STRUCTURE	187 ELKHORN GUARD STATION WOOD SHED (ELKHORN RANGER STATION WOOD SHED)				
3. SITE ADDRESS (STREET & NO.)	Elwha River Trail; approx. 11.5 miles from trailhead at Whiskey Bend				
4. CITY/VICINITY	Clallam, Washington				
5. ORIGINAL USE	Wood shed				
6. PRESENT USE	Wood shed/Storage				
7. CLASSIFICATION					
8. UTM ZONE	10	EASTING	465050	NORTHING	302075
9. RATING					
10. DATE	1934				
11. REGION	PNR				
12. OWNER/ADMIN ADDRESS	Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362				


13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXISTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.

The Elkhorn Guard Station Wood Shed was presumably built by the Depression-era, work relief Civilian Conservation Corps (CCC) when the new guard station residence was being completed. The construction of the Wood Shed in 1934 took place during a time when the administration of Mount Olympus National Monument, in which Elkhorn was included, was being transferred from the National Forest Service to the National Park Service. In addition to the Wood Shed, construction of the guard station residence and barn occurred in 1933-1934. This structure is one of numerous administrative buildings constructed by the U.S. Forest Service on the Olympic Peninsula. Beginning in 1905 the Forest Service gained jurisdiction of nearly 1.5 million acres of prime timber land on the peninsula, then included in the Olympic Forest Reserve. During the next thirty-three years, a network of administrative structures facilitating the forest ranger and guard (seasonal assistants) in patrolling this immense territory, evolved. Ranger stations, usually erected at more accessible front country sites, and guard stations, typically built at backcountry locations only reached by trail, played an important role in the Forest Service's efforts to pursue its multiple resource land use policy. Before 1911 only a few ranger and guard stations were built (including Storm King, Interorem, and Louella). But as the ranks of forest personnel swelled, and trails were built into the rugged interior, more stations were added. Often these ranger and guard stations consisted of living/sleeping quarters, a fire cache, a tool/wood shed, shelter, and sometimes a horse barn and corral. With the arrival of the CCC on the peninsula in the 1930s, Forest Service-administered lands witnessed a great boom in fire prevent:

14. CONDITION	<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> GOOD	<input type="checkbox"/> FAIR	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> RUINS
15. DANGER OF DEMOLITION? (SPECIFY THREAT)	<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> UNKNOWN				

16. SIGNIFICANCE This building, as well as the residence barn, and shelter, all standing at the Elkhorn Guard Station, are eligible for listing in the National Register of Historic Places as part of a total building ensemble. All four buildings were constructed between 1930 and 1934, at a time of exuberant construction and development of backcountry areas on the Olympic Peninsula by the U.S. Forest Service. Widely known since the 1890s, as a natural hiking route into the interior of the Olympic Range, and for its excellent trout fishing, the Elwha River was singled out by the Forest Service as a prime target for recreational development. In addition to the historical significance of this four-structure building ensemble, the Elkhorn Guard Station Residence is an excellent example of Rustic Style architecture, which became a hallmark of 1930s Depression-era groups such as the CWA and the CCC. Of the four buildings in this group, however, the Elkhorn building ensemble and its immediate surroundings have experienced minimal alteration since the 1930s. The Elkhorn Guard Station building group and surrounding grounds possess integrity of location, design, setting, materials,

17. PHOTOS AND SKETCH MAP OF LOCATION

NEG. 24:30
Unsurveyed

18. LOCATED IN AN HISTORIC DISTRICT?

 YES NO NAME

19. PUBLIC ACCESSIBILITY

 YES, LIMITED YES, UNLIMITED UNKNOWN20. EXISTING SURVEYS
 COUNTY LOCAL OTHER
NR NHL HABS HAER-1
HAER NPS STATE

21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

- Evans, Gail E. H. with T. Allan Comp. 1983. Historic Resource Study: Olympic National Park. Seattle: National Park Service, Pacific Northwest Region.
- Righter, Elizabeth. 1978. Cultural Resource Overview of the Olympic National Forest, Washington, Vol. I and II. Washington, D.C.: Jack McCormick and Associates.
- University of Washington, Seattle, Washington.
- Letter from Preston P. Macy to O. A. Tomlinson. 1934 (20 August). Macy Papers (Box 1-1). Archives and Manuscripts Section.
- Letter from Preston P. Macy to O. W. Carlson. 1936 (8 February). Macy Papers (Box 1-19). Archives and Manuscripts Section.
- White, D. H. c. 1933. "Map of Olympic of Olympic Peninsula, Washington." Tacoma, Washington: D. H. White. Photocopy. (Located in OLYM history files.)

22. INVENTORIED BY

Gail E. H. Evans

AFFILIATION

National Park Service

DATE

9/82, 1984

PNR INVENTORY

1. SITE I.D. NO					
2. NAME(S) OF STRUCTURE	187				
ELKHORN GUARD STATION WOOD SHED (ELKHORN RANGER STATION WOOD SHED)	5. ORIGINAL USE	Wood Shed	7. CLASSIFICATION		
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE	Wood Shed/ Storage	10. DATE		
Elwha River Trail; approx. 11.5 miles from trailhead at Whiskey Bend	8. UTM ZONE	EASTING	NORTHING	11. REGION	
CITY/VICINITY	STATE	SCALE	1:24	1:62.5	NAME
Elwha District, OLYM,	Washington	OTHER	QUAD		
4. COUNTY					
12. OWNER/ADMIN ADDRESS	Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362				

13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXISTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.
(continued from page one)
and recreation development. The construction of Forest Service ranger and guard stations reached epoch proportions. By the end of the 1930s no fewer than twelve ranger stations and nearly thirty guard stations stood in existence on the Olympic Peninsula. Many of these 1930s Forest Service-built administrative buildings embodied physical characteristics reflecting the Rustic Style, a style that advocated employing designs, materials, and sitings that were closely integrated with the surrounding landscape. The pine tree symbol, identified with both the Forest Service and the CCC, became widely used during the 1930s. With the creation of Olympic National Park in 1938 and the gradual introduction of air surveillance in fire management following World War II, ranger and guard station construction subsided. More recently many existing structures have been demolished. In 1984 only four Forest Service-ranger stations and eight guard stations are extant on the Olympic Peninsula. The Elkhorn Guard Station is one of five guard stations now standing in Olympic National Park.

Rectangular in shape; measures 10' x 12'; 1 story; wood-frame wall construction with shake siding; gable roof with shingles; no foundation; earth floor; no windows; one wood shake door. Alterations: portions of walls replaced with wood shingles. Siting: approx. 10' from rear of Elkhorn Patrol Station on grassy knoll at edge of open meadow.									
14. CONDITION	<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> GOOD	<input checked="" type="checkbox"/> FAIR	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> UNKNOWN
16. SIGNIFICANCE (continued from page one)	workmanship, feeling, and association. Only one other Forest Service back country guard station (North Fork Quinault Guard Station) on the Olympic Peninsula dating from the 1930s, has retained its integrity as a building group.								

17. PHOTOS AND SKETCH MAP OF LOCATION

16. LOCATED IN AN HISTORIC DISTRICT?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> NAME _____
18. PUBLIC ACCESSIBILITY	<input checked="" type="checkbox"/> YES, LIMITED NO	<input type="checkbox"/> YES, UNLIMITED <input type="checkbox"/> UNKNOWN	
19. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER			
20. EXISTING SURVEYS	<input type="checkbox"/> NR COUNTY	<input type="checkbox"/> NHL LOCAL	<input type="checkbox"/> MAABS <input type="checkbox"/> OTHER <input type="checkbox"/> HAER-I <input type="checkbox"/> HAER <input type="checkbox"/> NPS <input type="checkbox"/> STATE

22. INVENTORIED BY	AFFILIATION	DATE
--------------------	-------------	------

PNRO

INVENTORY

Westin Building, Room 1920

2001 Sixth Avenue

Seattle, Washington 98121

1. SITE I.D. NO.	188	2. NAME(S) OF STRUCTURE ELKHORN GUARD STATION BARN (ELKHORN RANGER STATION BARN)	5. ORIGINAL USE Barn	6. PRESENT USE Unoccupied	7. CLASSIFICATION	9. RATING
3. SITE ADDRESS (STREET & NO.) Elwha River Trail; approx. 11.5 miles from trailhead at Whiskey Bend	4. CITY/VICINITY Elwha District, Olympic National Park, Clallam, Washington	5. ORIGINAL USE Barn	6. PRESENT USE Unoccupied	7. CLASSIFICATION	9. RATING	
12 OWNER/ADMIN ADDRESS Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362		8. UTM ZONE 10	9. RATING NR	10. DATE 1933	11. REGION PNR	
		10. DATE 1933	11. REGION PNR			
		12. OWNER/ADMIN ADDRESS Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362	13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.	14. CONDITION <input checked="" type="checkbox"/> EXCELLENT	15. DANGER OF DEMOLITION (SPECIFY THREAT) <input type="checkbox"/> RUNS	
		13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.	14. CONDITION <input checked="" type="checkbox"/> EXCELLENT	15. DANGER OF DEMOLITION (SPECIFY THREAT) <input type="checkbox"/> RUNS	16. UNKNOWN	


The three-walled, shaked-sided Elkhorn Guard Station Barn was constructed during the summer and fall of 1933 by Civilian Conservation Corps (CCC) corpsmen under the supervision of the U.S. Forest Service. The new (presently existing) guard station residence was under construction at the same time. When completed, the barn housed four stalls, a manger, and a hay rack. The buildings at Elkhorn stood in five acres of open pasture, where pack animals were hitched and grazed. The construction of the barn in late 1933 took place during a time when administration of Mount Olympus National Monument, in which Elkhorn was included, was being transferred from the National Forest Service to the National Park Service. This structure is one of numerous administrative buildings constructed by the U.S. Forest Service on the Olympic Peninsula. Beginning in 1905 the Forest Service gained jurisdiction of nearly 1.5 million acres of prime timber land on the peninsula, then included in the Olympic Forest Reserve. During the next thirty-three years, a network of administrative structures facilitating the forest ranger and guard (seasonal assistants) in patrolling this immense territory, evolved. Ranger stations, usually erected at more accessible front country sites, and guard stations, typically built at back country locations only reached by trail, played an important role in the Forest Service's efforts to pursue its multiple resource land use policy. Before 1911 only a few ranger and guard stations were built (including Storm King, Interrorem, and Louella). But as the ranks of forest personnel swelled, and trails were built into the rugged interior, more stations were added. Often these ranger and guard stations consisted of living/

(Continued)

16. SIGNIFICANCE This building, as well as the residence, wood shed, and shelter, all standing at the Elkhorn Guard Station, are eligible for listing in the National Register of Historic Places as part of a total building ensemble. All four buildings were constructed between 1930 and 1934, at a time of exuberant construction and development of back country areas on the Olympic Peninsula by the U.S. Forest Service. Widely known since the 1890s, as a natural hiking route into the interior of the Olympic Range, and for its excellent trout fishing, the Elwha River was singled out by the Forest Service as a prime target for recreational development. In addition to the historical significance of this four-structure building ensemble, the Elkhorn Gurad Station Residence is an excellent example of Rustic Style architecture, which became a hallmark of 1930s Depression-era groups such as the CWA and the CCC. Of the four buildings in this group, only the Elkhorn Shelter has undergone considerable loss of physical integrity through residing. As a total group,

(continued)

17. PHOTOS AND SKETCH MAP OF LOCATION



NEG. 24:36A

18. LOCATED IN AN HISTORIC DISTRICT?

YES NO NAME

19. PUBLIC ACCESSIBILITY

YES, LIMITED YES, UNLIMITED UNKNOWN

20. EXISTING SURVEYS
 NA NHL MABS HAER-1 HAER NPS STATE
 COUNTY LOCAL OTHER

Unsurveyed



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

- Evans, Gail E. H. with T. Allan Comp. 1983. Historic Resource Study: Olympic National Park. Seattle: National Park Service, Pacific Northwest Region.
- Righter, Elizabeth. 1978. Cultural Resource Overview of the Olympic National Forest, Washington, Vol. I and II. Washington, D.C.: Jack McCormick and Associates.
- University of Washington, Seattle, Washington.
- Letter from Preston P. Macy to O.A. Tomlinson. 1934 (20 August). Macy Papers (Box 1-1). Archives and Manuscripts Section.
- Letter from Preston P. Macy to O.W. Carlson. 1936 (8 February). Macy Papers (Box 1-19). Archives and Manuscripts Section.
- White, D.H. ca. 1933. "Map of Olympic of Olympic Peninsula, Washington." Tacoma, Washington: D. H. White. Photocopy. (Located in OLYM history files.)

22. INVENTORIED BY

Gail E. H. Evans

AFFILIATION

NPS

DATE

9/82, 1984

PNRO

INVENTORY

1. SITE I.D. NO	188	2. NAME(S) OF STRUCTURE ELKHORN GUARD STATION BARN (ELKHORN RANGER STATION BARN)	3. SITE ADDRESS (STREET & NO) Elwha River Trail; approx. 11.5 miles from trailhead at Whiskey Bend	4. CITY/VICINITY	5. ORIGINAL USE Barn	6. PRESENT USE	7. CLASSIFICATION	8. UTM ZONE	EASTING	NORTHING	9. RATING
10. DATE		11. REGION									
12 OWNER/ADMIN ADDRESS											

13 DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXISTANT EQUIPMENT, AND
IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.

(continued from page one)

sleeping quarters, a fire cache, a tool/wood shed, shelter, and sometimes a horse barn and corral. With the arrival of the CCC on the peninsula in the 1930s, Forest Service-administered lands witnessed a great boom in fire prevention and recreation development. The construction of Forest Service ranger and guard stations reached epoch proportions. By the end of the 1930s no fewer than twelve ranger stations and nearly thirty guard stations stood in existence on the Olympic Peninsula. Many of these 1930s Forest Service-built administrative buildings embodied physical characteristics reflecting the Rustic Style, a style that advocated employing designs, materials, and settings that were closely integrated with the surrounding landscape. The pine tree symbol, identified with both the Forest Service and the CCC, became widely used during the 1930s. With the creation of Olympic National Park in 1938 and the gradual introduction of air surveillance in fire management following World War II, ranger and guard station construction subsided. More recently many existing structures have been demolished. In 1984 only four Forest Service ranger stations and eight guard stations are extant on the Olympic Peninsula. The Elkhorn Guard Station is one of five guard stations now standing in Olympic National Park.

Square in shape; measures 20' x 20'; 1-story; pole wall construction sided with wood shakes; steep pitched gable roof

14 CONDITION	<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> GOOD	<input type="checkbox"/> FAIR	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> RUINS	15 DANGER OF DEMOLITION? (SPECIFY THREAT)	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> UNKNOWN
--------------	------------------------------------	-------------------------------	-------------------------------	---------------------------------------	--------------------------------	--	------------------------------	-----------------------------	----------------------------------

EXPLANATION (Item No. 13 continued) with cedar shakes, exposed pole rafters; wood sill foundation; plank floor along west wall; earth floor in east portion of interior; two shake-sheathed doors on south wall; two wide, open bays on east wall; no windows. Alterations: removal of most of east wall to create wide bays, probably in early 1970s location of south door moved. Siting: near edge of open meadow approx. 100' east of Elwha River.

16. SIGNIFICANCE
however, the Elkhorn Guard Station building group and surrounding grounds possess integrity of location, design, setting, materials, workmanship, feeling, and association. Only one other Forest Service back country guard station (North Fork Quinault Guard Station) on the Olympic Peninsula dating from the 1930s, has retained its integrity as a building group.

17. PHOTOS AND SKETCH MAP OF LOCATION

18. LOCATED IN AN HISTORIC DISTRICT?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> NAME _____				
19. PUBLIC ACCESSIBILITY	<input checked="" type="checkbox"/> YES, LIMITED	<input type="checkbox"/> YES, UNLIMITED	<input type="checkbox"/> UNKNOWN				
20. EXISTING SURVEYS	<input type="checkbox"/> NR	<input type="checkbox"/> NHL	<input type="checkbox"/> HABS	<input type="checkbox"/> HAER-I	<input type="checkbox"/> HAER	<input type="checkbox"/> NPS	<input type="checkbox"/> STATE
	<input type="checkbox"/> COUNTY	<input type="checkbox"/> LOCAL	<input type="checkbox"/> OTHER				

21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

22. INVENTORIED BY	AFFILIATION	DATE
--------------------	-------------	------

PNPRO

INVENTORY

Westin Building, Room 1920

--	--	--	--	--	--	--	--

2001 Sixth Avenue
Seattle, Washington 98121

1. SITE I.D. NO. 300
 ELKHORN SHELTER

2 NAME(S) OF STRUCTURE ELKHORN SHELTER	5. ORIGINAL USE Shelter	7. CLASSIFICATION	9. RATING
3 SITE ADDRESS (STREET & NO.) Elwha River Trail; approx. 11.5 miles from trailhead at Whiskey Bend	6. PRESENT USE Shelter	8. UTM ZONE 10	10. DATE c. 1933
4 CITY/VICINITY Elwha District, OLYM,	STATE Washington	9. EASTING 4649505302100	11. REGION PNR
12 OWNER/ADMIN ADDRESS Clallam,	SCALE 1:24 (1:82,5)	10. OTHER QUAD Mt. Angeles	11. NAME

Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362

13 DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXISTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.

Built in the early 1930s, the Elkhorn Shelter was one of dozens of trail shelters erected by the U.S. Forest Service in the 1930s on the Olympic Peninsula. Known for its excellent trout fishing and popularity as a hiking route into the interior Olympic Mountains, the Elwha River was the site of six trail shelters, all constructed before 1941. (The others included, Lillian, Baltimore, Little Elkhorn, Hayes, and Chicago shelters.) The Elkhorn Shelter is the only shelter dating from the 1930s, that remains standing on the Elwha River. The U.S. Forest Service, which had jurisdiction over much of the area now included in Olympic National Park from 1905 to 1933, initiated shelter construction in the late 1920s and the 1930s. Shelter construction coincided with a period of active trail construction by the Forest Service. Shelters were at first intended for use by crews building and maintaining trails and laying telephone lines for fire protection purposes. As part of the Forest Service's multiple use management policy, trails and shelters served to encourage back country recreational use in the interior Olympics. In the 1930s, CCC corpsmen under the supervision of the Forest Service, accelerated shelter and trail construction activity. By the late 1930s nearly 90 shelters stood on the Olympic Peninsula. The greatest abundance of shelters built in the 1930s occurred on the north and east facing slopes of the Olympic Range. During this initial period of construction, shelters were built primarily in lowland valleys along major rivers and creeks, and sited at locations where the fishing and scenery was attractive. In some instances (particularly along the Bogachiel River), shelters replaced or augmented existing ranger or guard (continued)

14 CONDITION <input checked="" type="checkbox"/> EXCELLENT	15 DANGER OF DEMOLITION? <input type="checkbox"/> FAIR <input type="checkbox"/> DETERIORATED <input type="checkbox"/> RUINS	16 SIGNIFICANCE <input type="checkbox"/> (SPECIFY THREAT)	17 NO <input type="checkbox"/> YES	18 UNKNOWN <input type="checkbox"/>
---	--	--	---------------------------------------	--

This building, as well as the barn, wood shed, and residence, all standing at the Elkhorn Guard Station, are eligible for listing in the National Register of Historic Places as part of a total building ensemble. All four buildings were constructed between 1930 and 1934, at a time of exuberant construction and development of back country areas on the Olympic Peninsula by the U.S. Forest Service. Widely known since the 1890s as a hiking route into the interior of the Olympic Range, and for its excellent trout fishing, the Elwha River was singled out by the Forest Service as a prime target for recreational development. In addition to the historical significance of this four-structure building ensemble, the Elkhorn Guard Station Residence is an excellent example of Rustic Style architecture, which became a hallmark of 1930s Depression-era groups such as the CWA and the CCC. Of the four buildings in this group, only the Elkhorn Shelter has undergone considerable loss of physical integrity through residing. As a total group, however, the Elkhorn building ensemble and its immediate surroundings have experienced minimal alteration since the 1930s. The Elkhorn Guard Station



Unsurveyed

18. LOCATED IN AN HISTORIC DISTRICT N.E.C. 24:35

YES

19. PUBLIC ACCESSIBILITY

卷之三

21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTRACTS, AND/OR OTHER

Evans, Gail E.

Park Serv.

Kaune, Robert.

Nattinger, Jack

Olympic National

Shelter II

OLIMPIADES

U.S. Department

(Locally)

22. INVENTORIED BY

Gail E. H. Evans

APPENDIX

National Park Service

9/82, 1984

PNRO INVENTORY

1. SITE I.D. NO.				
2. NAME(S) OF STRUCTURE	300	5. ORIGINAL USE	7. CLASSIFICATION	
ELKHORN SHELTER		Shelter		
3. SITE ADDRESS (STREET & NO.)	Elwha River Trail; approx. 11.5 miles from trailhead at Whiskey Bend			
4. CITY/VICINITY	Elwha District, OLYM, Clallam, Washington			
5. OWNER/ADMIN ADDRESS				
13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXISTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.	<p><u>Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362.</u></p>			

(continued from page one)

stations, or were constructed at existing popular hunting or fishing "camps" (especially along the Elwha River). Typically, shelters stood from three to five miles apart on established trails. Architecturally, these Forest Service-built shelters dating from the 1930s were made from local materials obtained from the building site, were constructed of peeled-pole or split-cedar lumber sheathed with cedar shingles, and were capped with gable or shed, cedar-shake roofs. Shelters were three-sided, and roomy enough to provide several people protection from the inclement weather typical on the peninsula. Significant numbers of the late 1920s and 1930s Forest Service-type shelters were taken down in the mid 1970s, and in 1984 fewer than twenty remain standing.

Square in shape; measures 14' x 14'; 1 story; pole wall construction with board and batten siding; modified gable roof with cedar shingles; exposed pole rafters; stone foundation; open on one side; interior wood floor; bunk beds along sidewalls. Alterations: earlier shake walls replaced with board and batten siding possibly in the mid-1950s; wood floor also constructed in mid 1950s. Siting: near middle of an open meadow approx. 100' east of Elwha River.

14. CONDITION	<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> FAIR	<input type="checkbox"/> GOOD	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT?)	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> UNKNOWN
---------------	------------------------------------	-------------------------------	-------------------------------	---------------------------------------	--------------------------------	---	------------------------------	-----------------------------	----------------------------------

16. SIGNIFICANCE
(continued from page one)

building group and surrounding grounds possess integrity of location, design, setting, materials, workmanship, feeling, and association. Only one other Forest Service back country guard station (North Fork Quinault Guard Station) on the Olympic Peninsula dating from the 1930s, has retained its integrity as a building group.

17. PHOTOS AND SKETCH MAP OF LOCATION

18. LOCATED IN AN HISTORIC DISTRICT?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> NAME _____				
19. PUBLIC ACCESSIBILITY	<input checked="" type="checkbox"/> YES, LIMITED	<input type="checkbox"/> YES, UNLIMITED	<input type="checkbox"/> UNKNOWN				
20. EXISTING SURVEY	<input type="checkbox"/> NR	<input type="checkbox"/> NHL	<input type="checkbox"/> HABS	<input type="checkbox"/> HAER-1	<input type="checkbox"/> HAER	<input type="checkbox"/> NPS	<input type="checkbox"/> STATE
21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER							

22. INVENTORIED BY	AFFILIATION	DATE
--------------------	-------------	------