



Sierra Bonita Ranch-Founded 1872
(Bldgs face S) Garage/storage
area (L), ranch house (R), horse
stable (between).

3/18/75 A. Guhl

#1



Sierra Bonita Ranch

Horse stable (L), ranch house (R).

Bldgs face S.

3/18/75 A. Guhl

#2



Sierra Bonita Ranch

Present main entrance to ranch
house (faces S). See #7 for
comparison.

3/18/75 A. Guhl

#3



Sierra Bonita Ranch

Detail of ranch house to right
of south entrance.

3/18/75 A. Guhl

#4



Sierra Bonita Ranch

Enclosed courtyard (looking NE).

: 3/18/75 A. Guhl

#5



Sierra Bonita Ranch

Original "dinner" bell. Hangs
in W wall of court. This view
from outside court, looking E.

3/18/75 A. Guhl

#6



Sierra Bonita Ranch

E side of ranch house. Original
entrance is walled in and has 2
small windows (bathrooms inside).

3/18/75 A. Guhl

#7



Sierra Bonita Ranch

Bunkhouse, N of ranch house.

3/18/75 A. Guhl

#8



Sierra Bonita Ranch
Bunkhouse, N of ranch house.
(Faces W)

3/18/75 A. Guhl #9



Sierra Bonita Ranch
Bunkhouse, N of ranch house.
Closer view shows construction
and weatering.

3/18/75 A. Guhl

#10



Sierra Bonita Ranch

Old wagon behind bunkhouse.

Scene shows NE corner of bunk-
house.

3/18/75 A. Guhl

#11



Sierra Bonita Ranch

Horse stable (from SW). Presently
storage for grain and 2 old
horse-drawn carriages.

3/18/75 A. Guhl

#12



Sierra Bonita Ranch
Horse stable (from SW).

3/18/75 A. Guhl

#13



Sierra Bonita Ranch

Adobe corral walls. (Bldg is

NW corner of horse stable.....

see #12 & #13)

3/18/75 A. Guhl

#14




Sierra Bonita Ranch

Original bldg W of ranch house.

(View looking to ~~NW~~)

3/18/75 A. Guhl

#15



Sierra Bonita Ranch

West wall of #15 showing partial
deterioration.

3/18/75 A. Guhl

#16



Sierra Bonita Ranch

Old stable (N of ranch house, W
of bunkhouse). View looking N.

This side (the western) enters a
corral. See #18.

3/18/75 A. Guhl

#17



Sierra Bonita Ranch

Old stable (detail) showing broken
beam.

View from east entrance.

3/18/75 A. Guhl #18



Sierra Bonita Ranch
Scene in corral showing different
methods of "fencing."

3/18/75 A. Guhl

#19



Sierra Bonita Ranch

Corral scene showing adobe &
rock wall. All corrals were
originally enclosed by such
walls.

3/18/75 A. Guhl

#20



Sierra Bonita Ranch

Old wagon near corral N of
ranch house.

3/18/75 A. Guhl

#21