



Name: Agricultural Buildings and Complexes in Mill Creek
Hundred, 1800-1840, A. Armstrong Farm (N-10,909)

Location: Old Wilmington Road, Hockessin, Delaware 19707

Photographer: Valerie Cesna

Date: June 1986

Location of Negative: Bureau of Archaeology and Historic
Preservation, Dover, Delaware

Description: Dwelling, view from east

Photograph Number: 30



Name: Agricultural Buildings and Complexes in Mill Creek
Hundred, 1800-1840, A. Armstrong Farm (N-10,909)

Location: Old Wilmington Road, Hockessin, Delaware 19707

Photographer: Valerie Cesna

Date: June 1986

Location of Negative: Bureau of Archaeology and Historic
Preservation, Dover, Delaware

Description: Dwelling, view from south

Photograph Number: 31



Name: Agricultural Buildings and Complexes in Mill Creek
Hundred, 1800-1840, A. Armstrong Farm (N-10,909)

Location: Old Wilmington Road, Hockessin, Delaware 19707

Photographer: Valerie Cesna

Date: June 1986

Location of Negative: Bureau of Archaeology and Historic
Preservation, Dover, Delaware

Description: Barn, view from south

Photograph Number: 32