


MERIDIAN HILL PARK PHOTOGRAPHS  
Summer, 1993 (all photos by E. Carr)



TOP: View from southwest entrance (1)  
BOTTOM: Detail of lower terrace paving (2)

MERIDIAN HILL PARK PHOTOGRAPHS  
Summer, 1993 (all photos by E. Carr)



TOP: Cascade and great terrace wall (3)  
BOTTOM: Concrete and indirect lighting at stair landing (4)

MERIDIAN HILL PARK PHOTOGRAPHS  
Summer, 1993 (all photos by E. Carr)





TOP: Cascade from lower terrace reflecting pool (5)  
BOTTOM: Cascade from great (upper) terrace (6)

MERIDIAN HILL PARK PHOTOGRAPHS  
Summer, 1993 (all photos by E. Carr)



TOP: Stepped Ramp and Dante, view southeast (7)  
BOTTOM: Stairway and retaining wall, great terrace (8)

MERIDIAN HILL PARK PHOTOGRAPHS  
Summer, 1993 (all photos by E. Carr)



TOP: Pavement and baustrade, west of cascade, view west (9)  
BOTTOM: Baustrade (10)

MERIDIAN HILL PARK PHOTOGRAPHS  
Summer, 1993 (all photos by E. Carr)



TOP: View south on upper mall (11)  
BOTTOM: View east on great terrace (12)



Meridian Hill Park  
Washington, D.C.

Courtesy of HABS



MERIDIAN HILL PARK

4897 (1-3) 8/5/81 Bill Clark

*Meridian Hill Park Service*











