


CHARLES DOWNS, IL HOUSE WV See RT 1 MARLOWE VIC. BETERELEY COUNTY, W.V. By: PODNEY S. COLLINS 5/1990 FRONT (E.) ELEV. LOOKING W. PHOTO 1 OF9



CHARLES DOWNS, IF HOUSE WU SEC. RT. 1

MARLOW VIC. BERKELEY CO., W.VA.

PHOTO By FRANCES RUTH 4/1985

1. Charles Downs II House

- 2. Vicinity of Marlowe, WV.
- 3. Frances Ruth
- 4. April 1985
- 5. Courthouse, Martinsburg, WV.

6. Main entrance of panelled door set within panelled reveals with transom and sidelights; camera to southwest.

7. Photo #2

DOOR ENTRANCE DETAIL PHOTO 2 OF 9



CHARLES DOWNS, IF HOUSE WV SEC. RT. 1 MARLOWE VIC. BERKELEY CO., W.V. By: FRANCES RUTH 4/1985

1. Charles Downs II House

2. Vicinity of Marlowe, WV.

3. Frances Ruth

4. April 1985

5. Courthouse, Martinsburg, WV.


6. Second floor main hall, continuation of four-

flight, open-well stair; camera to northwest.

7. Photo #Han

PHOTO 30F9






- 1. Charles Downs II House
- 2. Vicinity of Marlowe, WV.
- 3. Frances Ruth
- 4. April 1985
- 5. Courthouse, Martinsburg, WV

6. Roundel and symmetrically molded trim, and panelled reveals, parlor to hall door detail; camera to north.

7. Photo #6"


PHOTO 4 OF9





- 1. Charles Downs II House
- 2. Vicinity of Marlowe, WV.
- 3. Frances Ruth
- 4. April 1985
- 5. Courthouse, Martinsburg, WV.
- 6. First flight in central hall of four-flight, open-well stair; camera to west.
- 7. Photo #3

STAIR DETAIL PHOTO 50F9



WV SEC. RT. 1, MARLOWE VIC., BERKELEY CO., W.V. Ry: FRANCES RUTH 4/1985

- 1. Charles Downs II House
- 2. Vicinity of Marlowe, WV.
- 3. Frances Ruth
- 4. April 1985
- 5. Courthouse, Martinsburg, WV.
- 6. Two-tiered, double panelled door cupboard,
- second floor of the ell; camera to west.

7. Photo # 7

CUPBOARD DETAIL


PHOTO GOF9



CHARLES DOWNS, IF HOUSE WV SEC. RT. I, MARLOWE VIC, BERKELEY CO., W.V.

- 1. Charles Downs II House
- 2. Vicinity of Marlowe, WV.
- 3. Frances Ruth
- 4. April 1985
- 5. Courthouse, Martinsburg, WV.
- 6. Kitchen fireplace and enclosed winderstair with cupboard in ell; camera to northwest.
- 7. Photo #8

By; FRANCES RUTH 4/1985 KITCHEN FIREPLACE PHOTO 9 DF9



CHARLES DOWNS, IL HOUSE W.V. SECONDARY RT. 1 MARLOWE VIC., W.V. By: FRANCES RUTH 4/1985

- 1. Charles Downs II House
- 2. Vicinity of Marlowe, WV.
- 3. Frances Ruth
- 4. April 1985
- 5. Courthouse, Martinsburg, WV.
- 6. Carpenters box lock on door from front section
- to dining room in ell; camera to west.
- 7. Photo #9

BOX LOCK DETAIL PHOTO 80F9



CHARLES DOWNS, IF HOUSE WV SEC. RT. 1, MARLOWE VIC. BERKELEY CO., W.V.

1. Charles Downs II House

2. Vicinity of Marlowe, WV.

3. Frances Ruth

4. April 1985

5. Courthouse, Martinsburg, WV.

6. One of four nearly identical mantels in the front section of the house. This one is in the south end parlor. Note too the panels under the windows; camera to southeast.

7. Photo #5

By: FRANCES RUTH MANTEL DETAIL PHOTO 90F9