Form KHC1985-2

Page 1 of 3 pages

KENTUCKY HISTORIC RESOURCES Individual Inventory Form

2931 NOV 1 5 1988

Resource # 155

Shelby County


. Name of Resource:	16. Date:
Harbison House	Original Building 1870's [6
2. Original Owner:	Addition 1950's ? [2
Samuel Harbison ?	17. Style:
. Other Names:	Victorian Vernacular [4V
None	i i
. Prehistoric Site x Building Object	18. Architect/Builder:
Historic Site Structure Other	Unknown
. Location: West side of Zaring Mill Road,	19. No. of Stories: 2 plus attic 2.0
	20. Original Floor Plan:
1/4 mile south of 1-64	T-plan with passage [TP
. Owner's Name:	21. Single Pile Double Pile X N.A.
Louis Payne	22. Roof Form & Material: ? Original x
Willard Igleheart [P]	Gable, standing seam meNadt Original
. Owner's Address:	23. Structural Material:
	Brick B 24. Exterior Material:
Rte. 5, Shelbyville, KY 40065	
Becomition: National Register [N]	Brick, running bond B
. Recognition & Date: Nat.Landmark Local Landmark	25. Foundation Material: Stone, cut [S
Nat.Register HABS/HAER	26. Major Alterations: None
Highway Marker KY Inventory <u>8-15-80</u>	
KY Landmark Certificate	x. Additions
0. N.R.Status & Date:	27. Special Features:
1. N.R.Group:	None
District Name: []	28. Outbuildings:
Mult.Resource Area: Shelby County []	Servants guarters (?) []
Thematic Name: []	29. Original Function:
2. Historical Theme:	Residential /Domestic, single dwell [014
Primary: Architecture [030]	30. Present Use:
Secondary: []	As above [014
Other: []	31. Condition:
3. Statement of Significance:	Excellent [E
This property is significant under criterion C	32. Endangered: Yes
as a well-preserved example of the late 19th	No <u>x</u>
century (1865-1900) 2-story, brick T-plan	33. Attach Photos:
with passage in Shelby County. It is one of	Roll: Photo Nos: No. of Slides:
8 such houses identified in the county. This	9 25A-29A 1
	9 25A-29A 1
is the only recorded instance of a [C]	
4. History:	
Droporty owned in 1000 hr Common Tombios	
Property owned in 1882 by Samuel Harbison.	1917 - · · · · · · · · · · · · · · · · · ·
Probably built in the 1870's judging from	$(\sigma_{1}, \sigma_{2}, \sigma_{2}, \sigma_{1}, \sigma_{2}, \sigma_{2},$
	tet (coltan))) or generation for the for- energy terms of the for-the for-the states of the states
Probably built in the 1870's judging from	international de la company de la company La company de la company de
Probably built in the 1870's judging from	
Probably built in the 1870's judging from plan and details.	
Probably built in the 1870's judging from plan and details.	
Probably built in the 1870's judging from plan and details.	
Probably built in the 1870's judging from plan and details.	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$
Probably built in the 1870's judging from plan and details.	$\begin{split} & = \left\{ \begin{array}{cccccccccccccccccccccccccccccccccccc$
Probably built in the 1870's judging from plan and details.	$ \left\{ \begin{array}{cccccccccccccccccccccccccccccccccccc$
Probably built in the 1870's judging from plan and details.	34. Prepared by: C'. Worsham
Probably built in the 1870's judging from plan and details.	34. Prepared by: C'. Worsham
Probably built in the 1870's judging from plan and details.	$ \frac{1}{2} \left\{ \begin{array}{cccccccccccccccccccccccccccccccccccc$

Form KHC1985-2 Page 2 of 3 pages

KENTUCKY HISTORIC RESOURCES

Individual Inventory Form

Resource # 155



Page 3 of 3 pages

Resource #155

(continued) 13. Statement of Significance:

double-pile T-plan in Shelby County. The servant's quarters demonstrate the continuity of servants housing and domestic-related layout of space from earlier times to the post-war period.

14. Description and House Plan: (continued)

onto side porch, brick veneer bathroom added in angle of ell on north side of house.

Interior:

Original woodwork consisting of earred door and window surrounds, panelled aprons beneath windows, high molded baseboards; secondary stair in southeast room of main portion of house.

Outbuildings:

2-room, frame, gabled servants quarters (?) to immediate west of house, now covered in tar paper, central stone chimney, coursed rubble foundation, four-panel doors, large stone chimney said to have been located on south gable end; modern frame, non-contributing shed in northwest corner of nominated acreage.

The nominated area includes two contributing buildings and one non-contributing building.