



82-A-5

The Lee Farm
Waterford, Caledonia County, Vt.
credit: Deborah Noble
date: January 1983
negative filed at Vt. Division for
Historic Preservation
description: farm complex with
Interstate 93; view looking
northwest
photograph #1



83-A-5

The Lee Farm
Waterford, Caledonia County, Vermont
credit: Deborah Noble
date: January 1983
negative filed at Vt. Division for
Historic Preservation
description: House main block and
wing (#1,1a); view looking
northwest
photograph #2



83-A-5

The Lee Farm
Waterford, Caledonia County, Vermont
credit: Deborah Noble
date: January 1983
negative filed at Vt. Division for
Historic Preservation
description: barn ell and wings of
main house (#1,1a,1b,1c); view
looking north
photograph #3



The Lee Farm
Waterford, Caledonia County, Vermont
credit: Deborah Noble
date: January 1983
negative filed at Vt. Division for
Historic Preservation
description: tenants' house (#4);
view looking southwest
photograph #7



The Lee Farm
Waterford, Caledonia County, Vermont
credit: Deborah Noble
date: January 1983
negative filed at Vt. Division for
Historic Preservation
description: harness shop/woodshed
(#3); view looking northeast
photograph #6

83-A-5



83-A-5

The Lee Farm
Waterford, Caledonia County, Vermont
credit: Deborah Noble
date: January 1983
negative filed at Vt. Division for
Historic Preservation
description: 1911 barn with entrance
ramp and milkroom (#2,2a,2b);
view looking north
photograph #4



The Lee Farm
Waterford, Caledonia County, Vermont
credit: Deborah Noble
date: January 1983
negative filed at Vt. Division for
Historic Preservation
description: 1911 barn and small
barn ell (#1c,2); view looking
southeast
photograph #5

83-A-5



The Lee Farm
Waterford, Caledonia County, Vermont
credit: Deborah Noble
date: January 1983
negative filed at Vt. Division for
Historic Preservation
description: equipment shed (#5);
view looking southwest
photograph #8