

Photo No. 3
By: George R. Adams, AASLH
Neg. at: HSS, HCRS
Date: February 1978

View: From northwest, showing from right to left, a portion of the Powerhouse, the Air Conditioning House, ruins of the Laboratory, and the Bathhouse.




Photo No. 1
By: George R. Adams, AASLH
Neg. at: HSS, HCRS
Date: February 1978

View: From southwest, showing furnace number two on left and furnace number one on right.




Photo No. 4
By: George R. Adams, AASLH
Neg. at: HSS, HCRS
Date: February 1978

View: From northwest, showing west end of Powerhouse and the Blowing-engine House.



Photo No. 2
By: George R. Adams, AASLH
Neg. at: HSS, HCRS

Date: February 1978

View: Detail of furnace Number one.




Photo No. 6
By: George R. Adams, AASLH
Neg. at: HSS, HCRS
Date: February 1978

View: From southeast, showing from right to left, the number one furnace base and the number two furnace.




Photo No. 5
By: George R. Adams, AASLH
Neg. at: HSS, HCRS
Date: February 1978

View: From southeast, showing number one furnace and portion of east Casting Shed.