



HIGH JENKS

1285

Central Falls Congregational Church

Central Falls, Rhode Island *Providence Co.*

Photographer: Richard Longstreth

Date: April, 1976

Negative: Rhode Island Historic Preservation Commission
150 Benefit Street, Providence, R.I.

Description: Northern and eastern facades, showing main
entrance to right under tower and northeastern
corner entrance porch.

Photograph #1 of 3



JUL 12 1976

PROPERTY OF THE NATIONAL REGISTER



Central Falls Congregational Church

Central Falls, Rhode Island

Providence Co.

Photographer: Richard Longstreth

Date: April, 1976

Negative: Rhode Island Historic Preservation Commission
150 Benefit Street, Providence, R.I.


Description: Southern facade, showing gable end of
north/south roof axis.

Photograph #2 -/ 2



JUL 12 1976

PROPERTY OF THE NATIONAL REGISTER



Central Falls Congregational Church

Central Falls, Rhode Island

Providence Co.

Photographer: Richard Longstreth

Date: April, 1976

Negative: Rhode Island Historic Preservation Commission
150 Benefit Street, Providence, R.I.

Description: Northwestern corner, facing Jenks Street.

Photograph #3 *a/2*



JUL 12 1976

PROPERTY OF THE NATIONAL REGISTER