



STATES BALLROOM

200

Photo #1 of 8

OCT 14 1981

States Ballroom (Bee Community Building)
(SW02-8)

Bee, Seward County, Nebraska

Photo by D. Murphy, Nebr. State Historical
Society, December, 1980 (NSHS 8012/3:28)

View looking north showing the main,
south facade.

MAR 24 1981

3

8012/3-28

Koysa



2

Photo #2 of 8 OCT 14 1981

States Ballroom (Bee Community Building)
(SW02-8)
Bee, Seward County, Nebraska

Photo by D. Murphy, Nebr. State Historical
Society, December, 1980 (NSHS 8012/3:35)

Overall view looking west showing east
front facade of ballroom with Elm Street
commercial area in background

MAR 24 1981

MAR 24 1981

3-2

8612/3-35

Kovner



Photo # 3 of 8

States Ballroom (Bee Community Building)
(SW02-8)

Bee, Seward County, Nebraska

Photo by D. Murphy, Nebr. State Historical
Society, December, 1980 (NSHS 8012/3:34)

View looking southwest showing north and
east facades.

MAR 24 1981
MAR 24 1981

8012/3-34
Koyser



Koyer

8012/3-31

3-20

31

Photo #4 of 8 OCT 14 1981

States Ballroom (Bee Community Building)
(SW02-8)

Bee, Seward County, Nebraska

Photo by D. Murphy, Nebr. States Historical
Society, December, 1980 (NSHS 8012/3:31)

Detail of south facade looking north
showing entrance and relief work.

MAR 24 1981



Photo #5 of 8

States Ballroom (Bee Community Building)
(SW02-8)

Bee, Seward County, Nebraska

Photo by D. Murphy, Nebr. States Historical
Society, December, 1980 (NSHS 8012/4:32)

Interior view looking northeast showing
dome and stage area.

OCT 14 1981

MAR 24 1981

Bee III

8012/4-32

5




Photo #6 of 8

States Ballroom (Bee Community Building)
(SW02-8)
Bee, Seward County, Nebraska

Photo by D. Murphy, Nebr. States Historical
Society, December, 1980, (NSHS 8012/4:34)

Interior view looking northwest showing
dome area and circumferential aisle.

OCT 14 1981

MAR 24 1981

Bee III

8012/4-34

51



51
28
Photo #7 of 8

States Ballroom (Bee Community Building)
(SW02-8)

Bee, Seward County, Nebraska

Photo by D. Murphy, Nebr. States Historical
Society, December, 1980 (NSHS 8012/4:28)

Interior view looking west showing
circumferential aisle and support columns

MAR 24 1981

OCT 14 1981



5
7
Photo #8 of 8

States Ballroom (Bee Community Building)
(SW02-8)
Bee, Seward County, Nebraska

Photo by D. Murphy, Nebr. State Historical
Society, December, 1980 (NSHS 8012/4:37)

Interior view looking west northwest
showing circumferential aisle and detail
work.

OCT 14 1981

MAR 24 1981