



- 1) J. C. Johnson House
- 2) Muncie, In.
- 3) Debra Beetem
- 4) October, 1999
- 5) 322 E. Washington
Muncie, In. (neg. location)
- 6) Southeast, Camera facing
northwest
- 7) #1



- 1) J. C. Johnson House
- 2) Muncie IN
- 3) Debra Beeter
- 4) October, 1979
- 5) 322 E. Washington
Muncie IN (neg. location)
- 6) northeast & north
- 7) #2 Camera facing southwest



- 1) J.C. Johnson House
- 2) Muncie IN
- 3) Debra Beetem
- 4) October, 1979
- 5) 322 E. Washington
Muncie IN (neg. location)
- 6) east facade, camera facing
southwest
- 7) #3



- 1) J. C. Johnson House
- 2) Muncie IN
- 3) Debra Beetem
- 4) October, 1979
- 5) 322 E. Washington
Muncie IN (neg. location)
- 6) west facade, camera facing
east
- 7) #4



- 1) J. C. Johnson House
- 2) Muncie IN
- 3) Debra Beeter
- 4) October, 1979
- 5) 322 E. Washington
Muncie IN (neg. location)
- 6) south facade, camera facing
north
- 7) # 5



- 1) J. C. Johnson House
- 2) Muncie IN
- 3) Debra Beeterm
- 4) October, 1979
- 5) 322 E. Washington
Muncie, IN (neg. location)
- 6) fireplace in entryway
on first floor
- 7) # 6



- 1) J. C. Johnson House
- 2) Muncie IN
- 3) Debra Beeterm
- 4) October, 1979

- 5) 322 E. Washington
Muncie IN (neg. location)
- 6) main entryway on
first floor & main
staircase

- 7) # 7



- 1) J. C. Johnson
- 2) Muncie IN
- 3) Debra Beeter
- 4) October, 1979
- 5) 332 E. Washington
Muncie, IN (neg. location)
- 6) fireplace in room
on first floor
- 7) #8



- 1) J.C. Johnson
- 2) Muncie IN
- 3) Debra Beeter
- 4) October, 1979
- 5) 322 E. Washington
Muncie IN (neg. location)
- 6) oriel window on second
floor on east facade
- 7) #9 camera facing west