



LEFT LANE
MUST
TURN LEFT

1813

Albuquerque High School, 110 Broadway NE
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978

JUL 10 1978

VIEW FROM S.E.

JUL 10 1978

Photograph by Donald Gunning, 7/77
Negative at Albuquerque Historic Landmarks Survey

Glass

PRODUCTS
INCORPORATED

Radio

SALES
DEPTS



STREET SCENE, CENTRAL AVE. 2
HUNING HIGHLANDS HISTORIC DISTRICT
ALBUQUERQUE, NEW MEXICO JUL 10 1978
VIEW FROM EAST, LOOKING SOUTH SIDE

PHOTOGRAPH BY CHRIS WILSON 3/78
NEGATIVE AT ALBUQUERQUE HISTORIC
LANDMARKS SURVEY

2

Central Ave
Looking SW

NOV 17 1978



STREET SCENE, CENTRAL AVE.

3

HUNING HIGHLANDS HISTORIC DISTRICT
ALBUQUERQUE, NEW MEXICO

VIEW FROM NORTH WEST JUL 10 1978

PHOTOGRAPH BY CHRIS WILSON 3/78
NEGATIVE AT ALBUQUERQUE HISTORIC LANDMARKS
SURVEY

central ave.

3

NOV 17 1978



PLAZA
ESCALANTE

PoCo LOCO
RECORDS
TAPES & THINGS

and CUT
JEWELRY

LOWEST
PRICES
IN THE
WORLD

PoCo
LOCO
HEAD
IMPORTS

GO BACK
20 PAGES

SPECIAL

\$15.00

WHITE
COATS

WHITE
COATS

\$15.00

RENT

Plaza Escalante, 412 Central S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978

VIEW FROM NORTH

JUL 10 1978

Photograph by Robert Willson, 8/76
Negative at Albuquerque Historic Landmarks Survey



Plaza Escalante, 412 Central S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978

VIEW FROM NORTH

Photograph by Robert Willson 8/76
Negative at Albuquerque Historic Landmarks Survey

JUL 10 1978



NOV 17 1978

Old Public Library, 423 Central N.E.
Huning Highlands Historic District
Albuquerque, New Mexico

6

JUL 10 1978

VIEW FROM SOUTH

Photograph by George Pearl 6/77
Negative at Albuquerque Historic Landmarks Survey



Old Public Library, 423 Central N.E.

7

Huning Highlands Historic District NOV 17 1978

Albuquerque, New Mexico

VIEW FROM SOUTHEAST

JUL 10 1978

Photograph by George Pearl 6/77

Negative at Albuquerque Historic Landmarks Survey



NOV 17 1978 8

Residence, 123 Edith N.E.
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

VIEW FROM NORTHEAST

Photograph by Christopher Wilson 8/77
Negative at Albuquerque Historic Landmarks Survey



Street scene: 200 block of Edith N.E.
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978 9

JUL 10 1978

VIEW FROM SOUTHWEST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey



OPERATION SER

Service
Employment
Redevelopment

CENTRO LEGAL 

CRIMINAL DEFENSE
PROJECT

handmade
job lot
wholesale

Street scene: 500 block of Central N.E.
Huning Highlands Historic District
Albuquerque, New Mexico

10

NOV 17 1978

VIEW FROM SOUTHWEST

JUL 10 1978

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey



Street scene: 100 block of Walter N.E. NOV 17 1978 11
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978
...

VIEW FROM SOUTHEAST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey



NOV 17 1978

McQuade House, 201 Walter NE
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

Photograph by Robert Wilson, 8/76
Negative at Albuquerque Historic Landmarks Survey

VIEW FROM S.E.



13

NOV. 17 1978

Residence, 201 High NE
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

Photograph by Robert Willson, 8/76
Negative at Albuquerque Historic Landmarks Survey

VIEW FROM S.E.



NOV 17 1978

14

Residence, 202 High SE
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

Photograph by Robert Willson, 8/76
Negative at Albuquerque Historic Landmarks Survey

VIEW FROM S.W.

ALHAMBRA
FURNISHED APARTMENTS
EFFICIENCY & 1-BEDROOM
NO VACANCY
FOR INFORMATION CALL 242-2888
J. ROTHMAN } . EVE. 255-4604



Alhambra Apartments, 210 High N.E.
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978 15

JUL 10 1978

VIEW FROM SOUTHWEST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey

713

ABOUT:

HAIR CUTS

CLASSIC Beauty 243 4986

Blue Jay

TURQUOISE - JEWELRY

BOB'S

FISH

CHIPS

PIZZA **BURGERS**

TRAVEL

VACATION

COOL

HEAT

R

PI

CLASSIC TRAVEL

OPEN

[Blacked out sign]



Street scene: 700 block of Central
Huning Highlands Historic District
Albuquerque, New Mexico

16

JUL 10 1978

VIEW FROM EAST

NOV 17 1978

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey



The Tropics

BAR & LOUNGE

30

Memorial Hospital, 800 Central S.E.

17

Huning Highlands Historic District

Albuquerque, New Mexico

JUL 10 1978

VIEW FROM NORTHWEST

NOV 17 1978

Photograph by Christopher Wilson 3/78

Negative at Albuquerque Historic Landmarks Survey



NOV 17 1978

18

Street scene and east district boundary
Huning Highlands Historic District
Albuquerque, New Mexico

VIEW FROM SOUTH

JUL 10 1978

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey



NOV 17 1978

19

Street scene: 800 block of Silver S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

VIEW FROM NORTHEAST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey

JUL 10 1978



NOV 17 1978

Residence, 212 High St. SE
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

Photograph by Robert Willson, 8/76
Negative at Albuquerque Historic Landmarks Survey

VIEW FROM N.W.

BUTTER KRUST
BAKERY
DISCOUNT
STORE
REDUCED PRICES BREAD-CAKE

BAKERY THRIFT STORE

• BREAD
• CAKES
• POTATO CHIPS

OPEN
MON. *thru* SAT.

THRIFT STORE

OPEN
MON. *thru* SAT.

CHIPS

milk
50¢



Butter Krust Bakery, 700 block of Coal S.E.
Huning Highlands Historic Distrist
Albuquerque, New Mexico

21

VIEW FROM SOUTHWEST

JUL 10 1978
NOV 17 1978

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey

Coal Ave



NOV 17 1978

22

Street scene: High Street S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

VIEW FROM SOUTHWEST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey

Plateau

HORN

Washburn Dairy
Ice Cream

HORN
OIL CO

35

WASHBURN
DAIRY

WASHBURN
DAIRY



Service station, 601 Coal S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

23

NOV 17 1978

JUL 10 1978

VIEW FROM SOUTHWEST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey



Residence, 415 Walter S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978₂₄

JUL 10 1978

VIEW FROM SOUTHEAST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey



ONE WAY

LEAD
WALKER

1741

NOV. 17 1978 25

Hill's Boarding House, 321 Walter S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

VIEW FROM S.E.

Photograph by Robert Willson, 8/76
Negative at Historic Landmarks Survey, Albuquerque



NOV 17 1978

26

Street scene: Walter Street S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

VIEW FROM SOUTHWEST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey




NOV 17 1978 27

Gable detail, residence, 317 Walter S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

VIEW FROM S.E.

JUL 10 1978

Photograph by Don Ivers, 3/71
Negative at Museum of Albuquerque



Residence, 306 Walter S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978

28

JUL 10 1978

VIEW FROM WEST

Photograph by Robert Willson, 8/76
Negative at Albuquerque Historic Landmarks Survey



302 Walter SE

Whitney House

Please return photo to:

HLS

U of Museum of Alb

PO Box 1293

Alb 87103

Whitney House, 302 Walter SE
Hunting Highlands Historic District
Albuquerque, New Mexico


NOV 17 1978

29

VIEW FROM S.W.

JUL 10 1978

Photograph by Robert Willson, 8/76
Negative at Albuquerque Historic Landmarks Survey



Street scene: Silver S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978

30

JUL 10 1978

VIEW FROM SOUTHWEST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey

30 Silver, SE
looking NE




Tuberculosis Cottages, 600 block of Silver S.E. 31
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978

VIEW FROM SOUTHWEST

JUL 10 1978

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey



NOV 17 1978

32

Gable detail, residence, 218 Walter S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

VIEW FROM WEST

Photograph by Don Ivers, 3/71
Negative at Museum of Albuquerque




NOV 17 1978
33

Residence, 209 Walter S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

VIEW FROM EAST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey



34
NOV 17 1978

Lernard House, 210 Walter SE
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

VIEW FROM N.W.

Photograph by Robert Willson, 8/76
Negative at Albuquerque Historic Landmarks Survey

34

LERNARD House



Cornish House, 123 Walter SE
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978

35

VIEW FROM S.E.

JUL 10 1978

Photograph by Robert Willson, 8/76
Negative at Albuquerque Historic Landmarks Survey



210-609

NOV 17 1978 36

McMillan House, 119 Walter SE
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

VIEW FROM N.E.

Photograph by Robert Willson, 8/76
Negative at Albuquerque Historic Landmarks Survey

36

McMillan Hse

119 Walter SE

76



Alley structures, between Edith and Walter S.E. 37
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

VIEW FROM NORTHWEST

NOV 17 1978

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey

37

17 200 blocks between Edith & Walter



220 Edith SE
Boatwright Home

Boatwright House, 220 Edith S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

VIEW FROM N.W.

Photograph by Robert Willson, 8/76
Negative at Albuquerque Historic Landmarks Survey

NOV 17 1978 38

JUL 10 1978



Street scene: Silver and Edith S.E. NOV 17 1978 39
Huning Highlands Historic District
Albuquerque, New Mexico

VIEW FROM NORTHEAST

JUL 1 1978

Photograph by *Opner* Wilson 3/78
New Mexico Albuquerque Historic Landmarks Survey

39

Silver, SE
looking SW



NOV 17 1978 40

Residences: 302 and 306 Edith S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

VIEW FROM SOUTHWEST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey



Residence, 324 Edith S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

41

VIEW FROM WEST

JUL 10 1978

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey



42

NOV 17 1978

Gable detail, residence, 410 Edith S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

VIEW FROM S.W.

Photograph by Don Ivers, 3/71
Negative at Museum of Albuquerque



NOV 17 1978

Residence, 419 Edith S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

VIEW FROM S.E.

Photograph by Robert Willson, 8/76
Negative at Albuquerque Historic Landmarks Survey

43

block
402 1/2 Edith SE - 419 Edith



NOV 17 1978

Residence, 637 Arno S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

44

JUL 10 1978

VIEW FROM SOUTHEAST

Photograph by Donald Gunning 2/78
Negative at Albuquerque Historic Landmarks Survey



Residence, 636 Arno S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978

JUL 10 1978

VIEW FROM WEST

Photograph by Donald Gunning 2/78
Negative at Albuquerque Historic Landmarks Survey



Residence, 628 Arno S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978

46

JUL 10 1978

VIEW FROM WEST

Photograph by Donald Gunning 2/78
Negative at Albuquerque Historic Landmarks Survey



Residence, 612 Arno S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

VIEW FROM WEST

Photograph by Donald Gunning 2/78
Negative at Albuquerque Historic Landmarks Survey

NOV 17 1978

47

JUL 10 1978

47



Residence, 608 Arno S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978

48

VIEW FROM WEST

JUL 10 1978

Photograph by Donald Gunning 2/78
Negative at Albuquerque Historic Landmarks Survey

48



KREPLIC CLUB
02404

NO PARKING

409

411

Residence, 409 Iron S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

VIEW FROM SOUTHWEST

Photograph by Donald Gunning 2/78
Negative at Albuquerque Historic Landmarks Survey

JUL 17 1978

JUL 10 1978

49



Residence, 506 Arno S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978

50

JUL 10 1978

VIEW FROM WEST

Photograph by Donald Gunning 2/78
Negative at Albuquerque Historic Landmarks Survey

50



NOV 17 1978

51

Residence, 502 Arno S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

VIEW FROM WEST

Photograph by Donald Gunning 2/78
Negative at Albuquerque Historic Landmarks Survey



52

NOV 17 1978

A. J. Richards House, 411 Arno S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

JUL 10 1978

VIEW FROM N.E.

Photograph by Robert Willson, 8/76
Negative at Albuquerque Historic Landmarks Survey

Harvey Towanhouse

29

411 Arno St



NOV 17 1978

Residence, 321 Arno S.E.

53

Huning Highlands Historic District

Albuquerque, New Mexico

JUL 10 1978

Photograph by Robert Willson 8/76

Negative at Albuquerque Historic Landmarks Survey



Street scene: South Broadway
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978 54

JUL 10 1978

VIEW FROM NORTHEAST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey

54

Broadway



Street scene: South Broadway
Huning Highlands Historic District
Albuquerque, New Mexico

55

JUL 10 1978

VIEW FROM SOUTHWEST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey

55
Broadway
looking NE

DETOUR

66



Residence, 222 Broadway S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 1 1978⁵⁶

JUL 10 1978

VIEW FROM SOUTHWEST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey

51

222 Broadway S.E.



Residence, 216 Broadway S.E.
Huning Highlands Historic District
Albuquerque, New Mexico

NOV 17 1978⁵⁷

JUL 10 1978

VIEW FROM SOUTHWEST

Photograph by Christopher Wilson 3/78
Negative at Albuquerque Historic Landmarks Survey

57

216 Broadway SE