



10 Pryor Street Building
Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources

Date: January, 1983

Description (1 of 12): Front and south sides;
photographer facing northeast.



10 Prvor Street Building
Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources

Date: January, 1983

Description (2 of 12): North side; photo-
grapher facing south.



10 Pryor Street Building
Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources

Date: January, 1983

Description (3 of 12): Rear view; photo-
grapher facing northwest.



10 Pryor Street Building
Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources

Date: January, 1983

Description (4 of 12): Main entrance;
photographer facing southeast.



10 Pryor Street Building
Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources

Date: January, 1983

Description (5 of 12): First floor, entrance
lobby; photographer facing northwest.



10 Pryor Street Building
Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources

Date: January, 1983

Description (6 of 12): First floor, elevator
door in lobby; photographer facing east.



10 Pryor Street Building
Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources

Date: January, 1983

Description (7 of 12): First floor, stairway
off lobby; photographer facing northwest.



10 Pryor Street Building
Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources

Date: January, 1983

Description (8 of 12): First floor, entrance
foyer ceiling; photographer facing west.



10 Pryor Street Building
Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources

Date: January, 1983

Description (9 of 12): Third floor, elevator
lobby; photographer facing southeast.



10 Pryor Street Building
Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources

Date: January, 1983

Description (10 of 12): Third floor,
elevator lobby; photographer facing west.



10 Pryor Street Building
Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources

Date: January, 1983

Description (11 of 12): Third floor, hall;
photographer facing south.



10 Pryor Street Building
Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources

Date: January, 1983

Description (12 of 12): Upper floor without
partitions; photographer facing southeast.