

Photo 1 0CT 2 1978 Blackman Building New Haven, CT D. Ransom Photo, 6/78 Negative: Connecticut Historical Commission View southwest



Photo 20CT 2 1978 Blackman Building New Haven, CT D. Ransom Photo, 6/78 Negative: Connecticut Historical Commission View southwest



Photo 3 OCT 2 1978 Blackman Building New Haven, CT D. Ransom Photo, 6/78 Negative: Connecticut Historical Commission Windows over doorway,

view west

COCKTA GOLD-LEAF :FLORIST: WEDDING

OCT 2 1978 Photo 4 Blackman Building New Haven, CT D. Ransom Photo, 6/78 Negative: Connecticut Historical Commission

Historical Commission Granite Pier, view northwest




Photo 5 Blackman Building New Haven, CT D. Ransom Photo, 6/78 Negative: Connecticut Historical Commission Doorway to uppper floors, view northwest



Photo 6 Blackman Building New Haven, CT D. Ransom Photo, 6/78 Negative: Connecticut Historical Commission Stair and balustrade, view southwest




Photo 7 Blackman Building New Haven, CT D. Ransom Photo, 6/78 Negative: Connecticut Historical Commission Interior brick bearing wall. view northwest



Photo 8
Blackman Building
New Haven, CT
Negative: New Haven
Colony Historical Soc.
Post card, view southwest
OCT 2 1978

DEC 2 C 12 15

NEG. NO: SUBJECT:

This photograph may not be reproduced without phonicsion of the New Haven Colony Historical Coclety.

Credit line should read: From the collection of the New Haven Colony Historical Society.



DEC 2 0 1978 Photo 9 Blackman Building New Haven, CT D. Ransom Photo, 6/78 Negative: Connecticut Historical Commission Northeast corner, view southeas Tr. 7 2 1978