



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

view of east facade

1 of 20




Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

view from southeast of main facades

2 of 20



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S

View of south facade

3 of 20



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

View of bank interior



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

View of interior; note tiled wall
and painted windows

A black and white photograph of a teller's booth. The booth has a highly decorative, ornate facade. At the top center is a decorative finial. Below it, a sign with the word "TELLER" in bold, white, sans-serif capital letters is set against a dark, arched background. The booth's sides are decorated with intricate, scrollwork-patterned metal grilles. The interior of the booth is visible through a large, arched opening, showing a desk with stacks of papers and a chair. In the foreground, a large, ribbed, bowl-shaped decorative element is attached to the front of the booth. The overall style is reminiscent of early 20th-century architecture.

TELLER

Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

detail of Teller Cage




BOOK-KEEPER

Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: KS.H.S.

detail of Bookkeeper cage



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

View of cage from back

8 of 20



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

Detail of cage

9 of 20



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

interior detail



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

view of window, note stenciling
below metal cornice



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

Bank safe



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

View of soffit beneath stair in
bank




Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

Cornice stencil detail in bank



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

detail of stenciled pressed
metal ceiling in bank



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

View of old Post Office space,
currently used as storage



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

South stair hall, note plaster
scored to look like stone.



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

View of second floor offices



Security State Bank, Eskridge, KS.

Photo credit: NP Small

Neg. on file: K.S.H.S.

View of Second floor Offices



Security State Bank, Eskridge, KS.

Photo credit: Unknown, 1920s

Neg. on file: K.S.H.S.

View from southeast