



Bagby Guard Station

(Vic) ESTACADA, Clackamas Co. Oregon

Melissa Darby, photographer

Aug. 1993

USDA Forest Service

595 Industrial Way

Estacada, Or. 97023

West Elevation, Cabin

photo 1 of 15



BAGBY Guard Station

vic. Estacada, Clackamas Co, Oregon

Melissa Darby photographer

Aug. 1993

USDA FOREST SERVICE

595 Industrial way

Estacada, Ore 97023

EAST Elevation Cabin

photo 2 of 15.



BAGBY gaard Station

vic. Estacada, Clackamas Co. Oregon

Melissa Darby photo

Aug. 1993

USDA Forest Service

595 Industrial way

Estacada Ore 97023

photos of 15



Bagby guard station

vic Estacoda, Clackamas Co., Oregon

Melissa Darby photographer

Aug 1993

USDA Forest Service

545 Industrial Way

Estacoda, OR 97023

South Elevation Cabin

photo 4 of 15



Bagby guard station
Vic Estacada Oregon, Clatsop Co.
Melissa Darby, photographer

Aug 1993

USDA Forest Service

595 Industrial Ave

Estacada, Ore. 97023

NORTH elevation

photo 5 of 15



WUNDA

Bagby Guard Station
vic. Estacada, Clatsamas Co. Oregon
melissa Darby, photographer
Aug 1993

USDA Forest Service
595 Industrial Way
Estacada OR 97023

Interior Cabin
photo 6 of 15



DONATE
HERE
REBUILD
BAG

JP

Bagby Sward Station

vic. Estacada, Ore., Clackamas County

Melissa Darby photographs

Aug 1993

USDA Forest Service

545 Industrial Way

Estacada, Oregon 97023

Interior Cabin

photo 7 of 15



Bagby guard station

vic. Estacada, Clackamas Co. Oregon

melissa Darby photographer

aug 1993

USPA Forest Service

595 Industrialway

Estacada Ore. 97023

West elevation shed

photos of 15



Bagby guard station

Vic. Estacada Clackamas Co. Oregon

Melissa Darby photographer

Aug 1993

USDA Forest Service

595 Industrial Way

Estacada, Or 97023

South elevation, shed

photo 9 of 15



Bagby guard station.

vic. Estacada. Clackamas Co, Oregon
melissa Darby photographer

Aug 1993

USDA Forest Service

595 Industrial Way

Estacada, Ore. 97023

EAST Elevation, shed

photo 10 of 15



Bagby guard station

vic. Estacada, Clackamas Co Oregon

Melissa Durby, photographer

Aug 1993

USDA Forest Service

595 Industrial way

Estacada Oregon 97023

north & east elevations, shed

photo 11 of 15



Bagby Guard Station
vic. Estacada, Clackamas Co. Oregon
Melissa Darby photographer
Aug 1993

USDA Forest Service

595 Industrial Way
Estacada Or 97023

Contextual photo
Both house

photo 12 of 15



Bagby Guard Station

vic. Estacada, Clackamas Co Oregon

photographer unknown

Historic View ca 1913

Oregon File

Estacada Ranger Dist.

595 Industrial Way

Estacada Oregon

97023

Facade, cabin & shed

west elevations

photo 13 of 5



Bagby guard station

vic. Estacada, Clackamas Co. Ore.
photographer unknown
Historic view CA. 1913

neg on file


Estacada, Oregon

595 Industrial Way

Estacada Oregon

97023

South elevation of cabinet
photo 14 of 13



Bagby guard station

vic. Estacada, Clackamas Co. Oregon
photographer unknown

Historic View 1966

Boyer (center) Carter (left) Phil Putz (right)

neg on file

Estacada, Oregon

595 Industrial way

Estacada, Ore 97023

Builder phil Putz overnight

photo 15 of 15